






report date: 2024-03-29

General information

Make	MERCEDES-BENZ
Model	SPRINTER 313 CDI
Colour	Blue
Year of manufacture	2010
Top speed	94 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	129 BHP
Max. torque	305 Nm at 1.200 rpm
Engine capacity	2.143 cc
Cylinders	4
Fuel type	Diesel
Consumption city	26.9 mpg
Consumption extra urban	38.7 mpg
Consumption combined	33.6 mpg



CarCheck.co.uk page 1/14



report date: 2024-03-29

Internet history

Entry 1

Date	2022-03-10
Pictures	1
Listing price	View report



source: cargurus.co.uk

CarCheck.co.uk page 2/14



report date: 2024-03-29

MOT history

MOT expiry date	2024-11-22
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	36
Total items failed	13


MOT #15		2023-11-23 15:45
MOT test	number	220404880271
Result		✓ Passed
Next expi	ry date	2024-11-22
Advice	Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))	
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Front Suspension arm ball joint has slight play both (5.3.4 (a) (i))	

MOT #14		2023-11-22 10:10
MOT test number		754123425939
Result		× Failed
Pass with rectification	Supplementary restraint system warning lamp indicate	s a fault (7.1.6 (a))
Pass with rectification	Engine MIL inoperative or indicates a malfunction (8.2.)	1.2 (h))
Advice Front Suspensio	n arm ball joint has slight play both (5.3.4 (a) (i))	
Fail Offside Rear Positio	n lamp not working (4.2.1 (a) (ii))	
Fail Offside Front Shock	absorbers likely to become detached (5.3.2 (a) (ii))	
Pass with rectification	Anti-lock braking system warning lamp indicates an AB	S fault (1.6 (b))
Advice Nearside Front 7	rack rod end ball joint has slight play (2.1.3 (b) (i))	
Advice Oil leak, but not	excessive (8.4.1 (a) (i))	

CarCheck.co.uk page 3/14



report date: 2024-03-29



MOT #12	2022-10-27 10:03
MOT test number	231956949019
Result	× Failed
Fail Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))	
Fail Exhaust diesel particulate filter shows evidence of tampering. (8.2.2.1 (c))	
Advice Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Play in steering rack inner joint(s)	
Advice Oil leak, but not excessive (8.4.1 (a) (i))	
Fail Parking brake efficiency below requirements (1.4.2 (a) (i))	
Advice Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Offside Front Shock absorbers has a reduced damping effect (5.3.2 (d))	

CarCheck.co.uk page 4/14



report date: 2024-03-29

MOT #11 2021-10-19 10:11 **MOT test number** 240847729203 Result ✓ Passed **Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **Advice** Rear Anti-roll bar linkage pin or bush worn but not resulting in excessive movement BOTH (5.3.4 (a) (i)) **Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) Advice Nearside Front Play in steering rack inner joint(s) Offside Front Service brake binding but not excessively (1.2.1 (f)) **Advice**

MOT #10		2020-10-21 08:56
MOT test	number	933299369816
Result		✓ Passed
Advice	Nearside Front Play in steering rack inner joint(s)	
Advice (a) (i))	Rear Anti-roll bar linkage pin or bush worn but not resulting in excessive mover	ment BOTH (5.3.4

MOT #9		2019-10-25 08:18
MOT test number		329218532399
Result		J Passed
Result		Viussed
Advice Tyre worn close to le	gal limit/worn on edge off side	rear tyre getting low (5.2.3 (e))
Advice Tyre worn close to le	gal limit/worn on edge both fro	ont tyres wearing outer tread (5.2.3 (e))

MOT #8	2018-10-06 13:23
MOT test number	584971330345
Result	✓ Passed
Advice Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i)) Advice Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	

CarCheck.co.uk page 5/14



report date: 2024-03-29

MOT #7

MOT test number

Result

Advice Wipers slightly deteriorated

Advice Parking brake lever has little reserve travel (3.1.6b)

MOT #6 2017-10-28 14:53 **MOT** test number 877930141055 Result **X** Failed Fail Nearside Front position lamp(s) not working (1.1.A.3b) Fail Parking brake: efficiency below requirements (3.7.B.7) Fail Parking brake lever has no reserve travel (3.1.6b) Fail Nearside Front Body has a projection caused by damage bumper (6.1.C.1) **Advice** Wipers slightly deteriorated

MOT #5

MOT test number

S17371397625

Result

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #4

MOT test number

Result

MOT #3

2015-09-07 20:54

173021259288

Passed

MOT #3

2014-09-01 11:04

MOT test number

906714044218

Result

✓ Passed

CarCheck.co.uk page 6/14



report date: 2024-03-29

MOT #2

MOT test number

Result

Advice

Nearside Front Macpherson strut has slight play in the sliding bush or gland (2.5.B.1b)

Advice

Nearside Front Tyre worn close to the legal limit (4.1.E.1)



CarCheck.co.uk page 7/14



report date: 2024-03-29

Tax & MOT check



Tax status Valid until 1 February

Days left 277

MOT expiry date 22 November 2024

Full MOT history See MOT history

CarCheck.co.uk page 8/14



report date: 2024-03-29

Damage history

Check the damage history for this MERCEDES-BENZ. See if, where and when this MERCEDES-BENZ had damage and the car repair costs. We also check if this MERCEDES-BENZ was scrapped. Download the premium report here for the results.

Damage 1

Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra MERCEDES-BENZ salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES-BENZ in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 10/14



report date: 2024-03-29

More info >

Owner history

*	
For how long did the current and previous owner(s) have this MERCEDES-BENZ? How may MERCEDES-BENZ have? Check it in the premium report and see all owner registrations. It report here .	

	More info >
Plate changes	
See in this check if this MERCEDES-BENZ had different number plates.	
Number of plates	,
Current registration	AIS UK
Plate since	
Current registration	UK UK
Plate since	

CarCheck.co.uk page 11/14



report date: 2024-03-29

Finance check

Check if this MERCEDES-BENZ is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES-BENZ has been settled.

If not, and you buy this MERCEDES-BENZ then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES-BENZ is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 12/14



report date: 2024-03-29

Mileage check

Registration #16

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-09-27
Last registration	2023-11-23
Complete history	See info



Registration #1	2010-09-27	22 mi
Registration #2	2013-09-26	41.941 mi
Registration #3	2014-09-01	60.013 mi
Registration #4	2015-09-07	75.912 mi
Registration #5	2016-09-27	88.945 mi
Registration #6	2017-10-28	104.933 mi
Registration #7	2017-10-30	104.982 mi
Registration #8	2018-10-06	119.095 mi
Registration #9		71,777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.177 es
Registration #14		11.777 es
Registration #15		11.777 es

7075.75.75

More info >

77. 777 mg

CarCheck.co.uk page 13/14



report date: 2024-03-29

Car features

Air conditioning	0225
	0295
	0482
	0501
	0566
	0567
	0569
	ow the complete MERCEDES REN7 factory list for this
ore inf	ew the complete MERCEDES-BENZ factory list for this hicle here.

Dimensions & weight

Width	2426 mm
Height	2435 mm
Length	5245 mm
Wheel base	3665 mm
Kerb weight	1985 kg
Max. allowed weight	3500 kg

Additional information

Fuel delivery	Direct Injection
Number of seats	3
Number of axles	2
Engine number	65195530306948

CarCheck.co.uk page 14/14