





report date: 2024-03-29

#### General information

Make	PEUGEOT
Model	5008 BLUEHDI S/S GT LINE PREMIUM
Colour	White
Year of manufacture	2018
Top speed	119 mph
0 - 60 mph	11.5 seconds
Gearbox	8 speed automatic

### Engine & fuel consumption

Power	129 BHP
Max. torque	300 Nm at 1.750 rpm
Engine capacity	1.500 cc
Cylinders	4
Fuel type	Diesel
Consumption city	64.2 mpg
Consumption extra urban	72.4 mpg
Consumption combined	68.9 mpg
CO2 emission	105 g/km
CO2 label	В



CarCheck.co.uk page 1/11



report date: 2024-03-29

### Internet history

#### Entry 1

Date 2021-06-05

Pictures 6

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



NV18ZYX report date: 2024-03-29

MOT history

MOT expiry date	2024-10-12
MOT pass rate	57 %
MOT passed	4
Failed MOT tests	3
Total advice items	6
Total items failed	5

MOT #7	2023-10-13 08:00
MOT test number	378757171648
Result	✓ Passed
Next expiry date	2024-10-12

MOT #6	2023-07-26 13:30
MOT test number	118233133214
Result	<b>✓</b> Passed
Advice All brake discs worn, but not excessively	

MOT #5	2023-06-20 14:39
MOT test number	860446587893
Result	🗙 Failed
Fail Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))	
Fail Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	
Advice Brake disc worn, pitted or scored, but not seriously weakened All (1.1.14 (a) (ii))	

MOT #4	2022-06-23 10:46
MOT test number	896931131469
Result	✓ Passed
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT #3 2022-06-18 10:26

**MOT test number** 529839117018

**Result** X Failed

Fail Front Brake pad(s) worn down to wear indicator (1.1.13 (a) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Fail** Offside Rear Rear fog lamp lens defective such that emitted light is adversely affected damaged and showing white light to rear (4.5.1 (b) (ii))

MOT #2 2021-06-22 15:53

**MOT test number** 740653750122

**Result** ✓ Passed

**MOT #1** 2021-06-22 09:28

**MOT test number** 954212539749

Result X Failed

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**Fail** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

CarCheck.co.uk page 4/11



NV18ZYX report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 October
Days left	155
MOT expiry date	12 October 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	49
Band	F
First licence fee (12 months)	£ 185,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 210,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



report date: 2024-03-29

#### Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

#### Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

Owner history	
For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report <a href="here">here</a> .	
***************************************	
***************************************	
***************************************	
***************************************	
***************************************	
Plate changes	More info >
See in this check if this PEUGEOT had different number plates.	
Number of plates	
Current registration	UK UK
Plate since	
Current registration	NK SIE
Plate since	
	More info >

CarCheck.co.uk page 8/11



report date: 2024-03-29

#### Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

**Contact info** 

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

## Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2018-07-31
Last registration	2023-10-13
Complete history	See info



Registration #1	2018-07-31	20 mi
Registration #2		11.777 es
Registration #3	2021-06-22	23.272 mi
Registration #4	2021-06-22	23.272 mi
Registration #5	2022-06-18	38.739 mi
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 esi

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-29

## Car features

S0225	Air conditioning
S0295	
50482	
S0501	
50566	
S0567	
50569	

## Safety ratings

NCAP rating	****
Adult	86%
Children	81%
Pedestrian	31%
Safety systems	97%
Overall rating	75%
Video	see crash video



## Dimensions & weight

Width	1841 mm
Height	1624 mm
Length	4447 mm
Wheel base	2675 mm
Kerb weight	1430 kg
Max. allowed weight	2000 kg

# Additional information

Fuel tank capacity	53 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11/1

Number of axles 2

Engine number Q3AR0025189