





## General information

Make	MINI
Model	COOPER D
Colour	Black
Year of manufacture	2010
Top speed	121 mph
0 - 60 mph	10.3 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	112 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	62.8 mpg
Consumption extra urban	76.4 mpg
Consumption combined	70.6 mpg
CO2 emission	105 g/km
CO2 label	В







### Internet history

Entry 2	
Date	2021-09-04
Pictures	30
Listing price	<u>View report</u>









source: cargurus.co.uk

Entry 1	
Date	

2021-09-03

View report

30

Pictures

Listing price

source: autotrader.co.uk









## MOT history

MOT expiry date	2024-11-21
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	12
Total items failed	5

MOT #16	2023-11-22 17:16
MOT test number	691139743977
Result	✓ Passed
Next expiry date	2024-11-21

MOT #15	2022-10-20 13:09
MOT test number	972413368975
Result	✓ Passed
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #14	2022-10-20 13:09
MOT test number	454422325685
Result	🗙 Failed
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
<b>Pass with rectification</b> Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))	

MOT #13	2021-11-04 17:28
MOT test number	210488862625
Result	✓ Passed





MOT #12	2021-06-02 15:	38
MOT test number	4919926589	84
Result	✓ Pass	ed
<b>Advice</b> Nearside Rear T inner edge (5.2.3 (e))	yre worn close to legal limit/worn on edge low tread and wearing out of shape	
MOT #11	2021-06-02 15:	38
MOT test number	6943652751	11
Result	× Faile	ed
Pass with rectification	Nearside Front Headlamp aim too high (4.1.2 (a))	
Advice Nearside Rear T inner edge (5.2.3 (e))	yre worn close to legal limit/worn on edge low tread and wearing out of shape	
Pass with rectification	Nearside Front Position lamp not working (4.2.1 (a) (ii))	

MOT #10	2020-06-09 13:44
MOT test number	624618747311
Result	✓ Passed
Advice Slight fuel leak from fuel filter area	
MOT #9	2019-04-24 12:36
MOT test number	113449988276
Result	✓ Passed
MOT #8	2018-04-19 14:00

MOT #8	2018-04-19 14:00
MOT test number	897972226938
Result	✓ Passed



<b>LB60KZR</b>
report date: 2024-03-29

MOT #7		2018-04-17 15:17
MOT test	number	657907151221
Result		🗙 Failed
Advice	Rear Direction indicator slightly discoloured both (1.4.A.2f)	
Advice	Nearside Front Direction indicator slightly discoloured (1.4.A.2f)	
<b>Fail</b> N	earside Front Shock absorber has a serious fluid leak (2.7.3)	

MOT #6	2017-04-27 10:25
MOT test number	210628152425
Result	✓ Passed

MOT #5	2016-04-22 13:45
MOT test number	435360025873
Result	✓ Passed
Advice Front tyres wearing on edges	
Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	

MOT #4		2015-04-29 10:33
MOT test	number	266479615145
Result		✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
Notice	Nearside front brake pad wear indicator insecure	
Advice	Inner Front Lower Suspension arm has slight play in a pin/bush (2.4.G.2)	

МОТ #3	2014-04-30 12:05
MOT test number	789520024142
Result	✓ Passed



<b>LB60KZR</b>
report date: 2024-03-29

MOT #2	2013-10-31 11:22
MOT test number	145174003368
Result	✓ Passed
MOT #1	2013-10-30 12:12
MOT test number	239873303394
Result	× Failed
<b>Fail</b> Centre Stop lamp not working (1.2.1b)	



Tax & MOT check

✓ Taxed Tax due: 1 November 2024	✓ MOT Expires: 21 November 2024
Tax status	Valid until 1 November
Days left	185
MOT expiry date	21 November 2024
Full MOT history	See MOT history
Tax calculation	

Vehicle class	49
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-





#### Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPL
Date	
Date	OLE
Category	E.S.
Туре	

#### Extra MINI salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >





#### Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4

More info  $\rightarrow$ 





## Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	
***********	
*******	
******	
***********	
********	
	More info >
Plate changes	
See in this check if this MINI had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	
	More info >





#### Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info  $\rightarrow$ 





# Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2010-12-30
Last registration	2023-11-22
Complete history	See info



Registration #1	2010-12-30	12 mi
Registration #2	2013-10-30	39.396 mi
Registration #3	2013-10-31	39.419 mi
Registration #4	2014-04-30	44.044 mi
Registration #5	2015-04-29	51.444 mi
Registration #6	2016-04-22	57.896 mi
Registration #7	2017-04-27	65.224 mi
Registration #8	2018-04-17	71.878 mi
Registration #9	2018-04-19	71.878 mi
Registration #10	2019-04-24	80.842 mi
Registration #10 Registration #11	2019-04-24	80.842 mi
-	2019-04-24	80.842 mi
Registration #11	2019-04-24	80.842 mi
Registration #11 Registration #12	2019-04-24	80.842 mi
Registration #11 Registration #12 Registration #13	2019-04-24	80.842 mi
Registration #11 Registration #12 Registration #13 Registration #14	2019-04-24	80.842 mi
Registration #11 Registration #12 Registration #13 Registration #14 Registration #15	2019-04-24	80.842 mi
Registration #11 Registration #12 Registration #13 Registration #14 Registration #15 Registration #16	2019-04-24	80.842 mi

More info  $\rightarrow$ 





### Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight	
Width	1683 mm
Height	1414 mm
Length	3723 mm
Wheel base	2467 mm
Kerb weight	1200 kg
Max. allowed weight	1630 kg
Additional information	
Fuel tank capacity	40
Fuel delivery	Direct Injection
Number of doors	2
Number of seats CarCheck.co.uk	4 page 13/13

Number of axles	2
Engine number	70077520