



PEUGEOT

E059ZXE

report date: 2024-03-28

General information

Make	PEUGEOT
Model	207 VERVE
Colour	Black
Year of manufacture	-
Top speed	104 mph
0 - 60 mph	15.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	72 BHP
Max. torque	118 Nm at 3.300 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	32.5 mpg
Consumption extra urban	56.5 mpg
Consumption combined	44.1 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-06-04
Pictures	2
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

<b>MOT #15</b>	2021-06-26 16:41
<b>MOT test number</b>	508026288704
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2022-06-25
<b>Advice</b>	Central Front Fluid leak, but not excessive coolant leaking from the front of the car (8.4.1 (a) (i))

<b>MOT #14</b>	2020-10-06 11:02
<b>MOT test number</b>	532304897348
<b>Result</b>	✓ Passed
<b>Advice</b>	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
<b>Advice</b>	Oil leak, but not excessive (8.4.1 (a) (i))
<b>Advice</b>	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
<b>Advice</b>	Central Front Exhaust mounting defective rear cat section bolt missing (6.1.2 (a))

**MOT #13**

2020-10-06 08:37

**MOT test number**

926478505912

**Result****✗ Failed**

- Advice** Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Exhaust hydrocarbon content after 2nd fast idle exceeds default limits (8.2.1.2 (b))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Exhaust carbon monoxide content at idle exceeds default limits (8.2.1.2 (b))
- Advice** Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))
- Advice** Central Front Exhaust mounting defective rear cat section bolt missing (6.1.2 (a))
- Advice** Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Fail** Exhaust carbon monoxide content after 2nd fast idle exceeds default limits (8.2.1.2 (b))



MOT #12

2019-10-02 08:56

MOT test number

762327037870

Result

✓ Passed

- Advice

Offside Front Tyre slightly damaged/cracking or perishing SLIGHTLY PERISHED (5.2.3 (d) (ii))
- Advice

Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))
- Advice

Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice

Front Engine mounting damaged but not to excess (6.1.8 (a) (i))
- Advice

Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))
- Advice

Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice

Oil leak, but not excessive (8.4.1 (a) (i))
- Advice

LONG TRAVEL ON PARK BRAKE LEVER (ADJ. REQ.)
- Advice

Rear Engine mounting damaged but not to excess (6.1.8 (a) (i))

**MOT #11** 2019-09-25 08:47**MOT test number** 182716262931**Result** ✗ Failed**Advice** Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Rear Engine mounting damaged but not to excess (6.1.8 (a) (i))**Fail** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))**Advice** LONG TRAVEL ON PARK BRAKE LEVER (ADJ. REQ.)**Advice** Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))**Advice** Offside Front Tyre slightly damaged/cracking or perishing SLIGHTLY PERISHED (5.2.3 (d) (ii))**Advice** Front Engine mounting damaged but not to excess (6.1.8 (a) (i))**Advice** Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #10** 2018-09-08 11:00**MOT test number** 142552058288**Result** ✓ Passed**MOT #9** 2017-09-21 14:30**MOT test number** 234311194745**Result** ✓ Passed**Advice** Rear exhaust bracket broken**Advice** Management light on dash

**MOT #8** 2017-09-14 14:40**MOT test number** 528904025315**Result** ✗ Failed**Fail** Nearside Front Sub-frame attachment bracket/mounting bolt missing bolt snapped (2.4.G.1)**Advice** Rear exhaust hanger broken**Advice** Engine management light on**Advice** Nearside Rear Tyre worn close to the legal limit 2mm (4.1.E.1)**Advice** Both rear tyres perished**MOT #7** 2016-09-23 12:29**MOT test number** 132316068053**Result** ✓ Passed**Advice** Rear exhaust hanger broken**Advice** Engine management light on**Advice** Nearside Rear Tyre worn close to the legal limit 2mm (4.1.E.1)**MOT #6** 2015-09-29 16:31**MOT test number** 831635057244**Result** ✓ Passed**MOT #5** 2015-09-29 10:34**MOT test number** 742197176992**Result** ✗ Failed**Fail** Exhaust emissions carbon monoxide content after 2nd fast idle excessive (7.3.D.3)**Fail** Exhaust emissions hydrocarbon content after 2nd fast idle excessive (7.3.D.3)**Fail** Exhaust emissions carbon monoxide content at idle excessive (7.3.D.4)**Fail** Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)

**MOT #4** 2015-09-22 12:44**MOT test number** 728744831561**Result** ✗ Failed

- Fail** Exhaust emissions carbon monoxide content at idle excessive (7.3.D.4)
- Fail** Exhaust emissions hydrocarbon content after 2nd fast idle excessive (7.3.D.3)
- Fail** Exhaust emissions carbon monoxide content after 2nd fast idle excessive (7.3.D.3)
- Fail** Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)

**MOT #3** 2014-09-25 08:40**MOT test number** 188818164209**Result** ✓ Passed**MOT #2** 2013-09-26 08:47**MOT test number** 398869863271**Result** ✓ Passed**MOT #1** 2012-09-05 09:54**MOT test number** 649229342243**Result** ✓ Passed

- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Front Brake pad(s) wearing thin (3.5.1g)



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	E059ZXE
Plate since	2019-03-28
Current registration	E059ZXE
Plate since	2019-03-28

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.


Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2009-09-28
Last registration	2021-06-26
Complete history	<a href="#">See info</a>



Registration #1	2009-09-28	29 mi
Registration #2	2012-09-05	45.894 mi
Registration #3	2013-09-26	48.620 mi
Registration #4	2014-09-25	52.048 mi
Registration #5	2015-09-22	55.621 mi
Registration #6	2015-09-29	55.977 mi
Registration #7	2015-09-29	55.977 mi
Registration #8	2016-09-23	56.629 mi
Registration #9	2017-09-14	57.000 mi
Registration #10	2018-09-28	58.377 mi
Registration #11	2019-09-28	59.754 mi
Registration #12	2020-09-28	61.131 mi
Registration #13	2021-06-26	62.508 mi
Registration #14	2022-03-28	63.885 mi
Registration #15	2023-03-28	65.262 mi
Registration #16	2024-03-28	66.639 mi
Registration #17	2025-03-28	68.016 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1920 mm
Height	1502 mm
Length	4030 mm
Wheel base	2540 mm
Kerb weight	1214 kg
Max. allowed weight	1617 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	FSW86163295