



PEUGEOT



report date: 2024-03-28

General information

Make	PEUGEOT
Model	107 VERVE
Colour	Black
Year of manufacture	2009
Top speed	98 mph
0 - 60 mph	14.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	67 BHP
Max. torque	93 Nm at 3.600 rpm
Engine capacity	998 cc
Cylinders	3
Fuel type	Petrol
Consumption city	51.4 mpg
Consumption extra urban	72.4 mpg
Consumption combined	62.8 mpg
CO2 emission	106 g/km
CO2 label	B









Internet history

Entry 1

Date	2021-06-15
Pictures	7
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-06-21
MOT pass rate	63 %
MOT passed	12
Failed MOT tests	7
Total advice items	51
Total items failed	6

MOT #19	2023-06-13 12:05
MOT test number	454391222251
Result	✓ Passed
Next expiry date	2024-06-21
Advice	Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
Advice	Rear Brake pipe slightly damaged (1.1.11 (c))
Advice	Nearside Rear Wheel bearing has slight play (5.1.3 (a) (i))

MOT #18	2023-06-13 12:05
MOT test number	292467001807
Result	✗ Failed
Advice	Nearside Rear Wheel bearing has slight play (5.1.3 (a) (i))
Advice	Rear Brake pipe slightly damaged (1.1.11 (c))
Pass with rectification	Nearside Rear Direction indicator incorrect colour (4.4.3 (a))
Advice	Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))



MOT #17

2022-06-22 15:57

MOT test number

399958403765

Result		✓ Passed
Advice	Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Rear Service brake binding but not excessively (1.2.1 (f))	
Advice	Offside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Rear Wheel bearing has slight play (5.1.3 (a) (i))	
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))	

**MOT #16**

2022-06-22 09:19

**MOT test number**

463965157626

**Result****✗ Failed**

- MAJOR** Exhaust has a major leak of exhaust gases (6.1.2 (a))
- Advice** Offside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Rear Wheel bearing has slight play (5.1.3 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- MAJOR** Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- MAJOR** Offside Rear Position lamp not working (4.2.1 (a) (ii))
- Advice** Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Advice** Nearside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- MAJOR** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

**MOT #15**

2021-06-01 08:36

**MOT test number**

928935706414

**Result****✓ Passed**

**MOT #14**

2021-01-04 16:01

**MOT test number**

857293368595

**Result**

✓ Passed

- Advice** Rear Tyre slightly damaged/cracking or perishing both rear (5.2.3 (d) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Rear exhaust back box bracket loose one side
- Advice** Front slight damage to front crash bar

**MOT #13**

2021-01-04 16:01

**MOT test number**

282359552917

**Result**

✗ Failed

- Advice** Rear Tyre slightly damaged/cracking or perishing both rear (5.2.3 (d) (ii))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Front slight damage to front crash bar
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Pass with rectification** Nearside Rear Position lamp not working (4.2.1 (a) (ii))
- Advice** Rear exhaust back box bracket loose one side

**MOT #12**

2019-10-08 16:26

**MOT test number**

293174376639

**Result**

✓ Passed

- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Central Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Rear Tyre slightly damaged/cracking or perishing Both sides outer edges (5.2.3 (d) (ii))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #11** 2019-10-08 11:46**MOT test number** 742871432321**Result** ✗ Failed

- Advice** Central Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Rear Tyre slightly damaged/cracking or perishing Both sides outer edges (5.2.3 (d) (ii))
- MAJOR** Nearside Rear Wheel bearing rough when rotated (5.1.3 (b) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #10** 2018-10-16 09:36**MOT test number** 541126308437**Result** ✓ Passed

- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened inner faces (1.1.14 (a) (ii))
- Advice** Central Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Rear Wheel bearing slightly noisy (5.1.3 (b) (i))

**MOT #9** 2017-05-04 09:28**MOT test number** 384486127315**Result** ✓ Passed**MOT #8** 2017-05-03 09:29**MOT test number** 355277365771**Result** ✗ Failed

- Fail** Offside Brake pipe excessively corroded front to rear (3.6.B.2c)

**MOT #7** 2016-04-29 12:42**MOT test number** 493079342913**Result** ✓ Passed

**MOT #6** 2016-04-29 12:42**MOT test number** 385654107504**Result** ✗ Failed**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)**Pass with rectification** Offside Headlamp aim too low (1.8)**MOT #5** 2015-05-02 10:05**MOT test number** 495052025121**Result** ✓ Passed**MOT #4** 2014-05-05 20:34**MOT test number** 718575824146**Result** ✓ Passed**MOT #3** 2014-05-03 13:14**MOT test number** 429773924148**Result** ✗ Failed**Fail** Nearside front brake binding (3.7.B.1)**MOT #2** 2013-05-04 10:02**MOT test number** 687144723169**Result** ✓ Passed**MOT #1** 2012-05-11 09:41**MOT test number** 838842432196**Result** ✓ Passed**Notice** Both front brake discs slightly worn





Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 November 2024

✓  
**MOT**  
**Expires:**  
21 June 2024

<b>Tax status</b>	Valid until 1 November
<b>Days left</b>	187
<b>MOT expiry date</b>	21 June 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	B
<b>Single payment (12 months)</b>	£ 20,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 21,00,-



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2009-07-22
Last registration	2023-06-13
Complete history	<a href="#">See info</a>



Registration #1	2009-07-22	16 mi
Registration #2	2012-05-11	22.897 mi
Registration #3	2013-05-04	32.396 mi
Registration #4	2014-05-03	44.458 mi
Registration #5	2014-05-05	44.585 mi
Registration #6	2015-05-02	59.913 mi
Registration #7	2016-04-29	79.968 mi
Registration #8	2016-04-29	79.968 mi
Registration #9	2017-05-03	100.217 mi
Registration #10	2017-05-04	100.217 mi
Registration #11	2018-10-16	103.659 mi
Registration #12	2019-05-02	103.659 mi
Registration #13	2019-05-02	103.659 mi
Registration #14	2019-05-02	103.659 mi
Registration #15	2019-05-02	103.659 mi
Registration #16	2019-05-02	103.659 mi
Registration #17	2019-05-02	103.659 mi
Registration #18	2019-05-02	103.659 mi
Registration #19	2019-05-02	103.659 mi
Registration #20	2019-05-02	103.659 mi
Registration #21	2019-05-02	103.659 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1630 mm
Height	1470 mm
Length	3430 mm
Wheel base	2340 mm
Kerb weight	875 kg
Max. allowed weight	1190 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4

Number of axles	2
Engine number	6218893