



report date: 2024-03-28

General information

Make	NISSAN
Model	NOTE VISIA
Colour	Silver
Year of manufacture	2010
Top speed	103 mph
0 - 60 mph	13.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	87 BHP
Max. torque	128 Nm at 3.200 rpm
Engine capacity	1.386 cc
Cylinders	4
Fuel type	Petrol
Consumption city	38.7 mpg
Consumption extra urban	55.7 mpg
Consumption combined	47.9 mpg
CO2 emission	139 g/km
CO2 label	E





## MOT history

MOT expiry date	2021-08-03
MOT pass rate	62 %
MOT passed	8
Failed MOT tests	5
Total advice items	34
Total items failed	8

## MOT #13 2020-07-21 10:16

MOT test number 660719248290

Result ✓ Passed

Next expiry date 2021-08-03

**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Wipers smearing

## MOT #12 2020-07-20 12:26

MOT test number 738566753996

Result ✗ Failed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Offside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))**Advice** Wipers smearing**Advice** Offside Rear Tyre worn close to legal limit/worn on edge 185/55/16 (5.2.3 (e))**Fail** Nearside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge worn on the outer edge (5.2.3 (e))

**MOT #11**

2019-07-18 16:15

**MOT test number**

588752295883

**Result**

✓ Passed

- Advice** Play in steering rack inner joint(s)
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #10**

2019-07-18 12:24

**MOT test number**

803129592892

**Result**

✗ Failed

- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Play in steering rack inner joint(s)
- Fail** Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #9**

2018-07-26 11:04

**MOT test number**

832388412272

**Result**

✓ Passed

- Advice** Track rod end ball joint has slight play both (2.1.3 (b) (i))

**MOT #8**

2017-07-17 13:07

**MOT test number**

301945938970

**Result**

✓ Passed

**Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**Advice** Nearside rear tyre deep cut in sidewall

**MOT #7**

2017-07-17 09:25

**MOT test number**

637736785680

**Result**

✗ Failed

**Fail** Front Windscreen wiper does not clear the windscreen effectively both (8.2.2)

**Advice** Nearside rear tyre deep cut in sidewall

**Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**Fail** Rear Registration plate lamp not working both (1.1.C.1d)

**Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**MOT #6**

2016-07-04 10:45

**MOT test number**

105425678831

**Result**

✓ Passed

**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**Advice** Nearside front tyre badly worn on the outer edge 185/55/16

**Advice** Offside front tyre slightly worn on the outer edge

**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**MOT #5** 2016-07-04 07:58**MOT test number** 838560422006**Result** ✗ Failed

- Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Nearside front tyre badly worn on the outer edge 185/55/16
- Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Fail** Offside front brake excessively fluctuating (3.7.B.3)
- Advice** Offside front tyre slightly worn on the outer edge

**MOT #4** 2015-07-20 17:09**MOT test number** 257241005260**Result** ✓ Passed**MOT #3** 2015-07-20 14:39**MOT test number** 928131605205**Result** ✗ Failed

- Fail** Offside Front Lower coil spring broken (2.4.C.1a)

**MOT #2** 2014-07-22 16:05**MOT test number** 948633204238**Result** ✓ Passed

- Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Notice** Cut in n/s/r tyre but not showing cords

**MOT #1** 2013-07-23 09:21**MOT test number** 278104103208**Result** ✓ Passed

- Notice** Small gouges to OSF tyre wall cords not exposed



Tax & MOT check

✕  
Untaxed

Tax expired:  
21 December 2020

✕  
MOT

Expired:  
3 August 2021

Tax status	Expired at 21 December 2020
Days left	1225 days too late
MOT expiry date	3 August 2021
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >





Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	
Plate since	2019-01-01
Current registration	
Plate since	2019-01-01

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2010-08-03
Last registration	2020-07-21
Complete history	<a href="#">See info</a>



Registration #1	2010-08-03	18 mi
Registration #2	2013-07-23	33.398 mi
Registration #3	2014-07-22	43.622 mi
Registration #4	2015-07-20	47.412 mi
Registration #5	2015-07-20	47.412 mi
Registration #6	2016-07-04	54.583 mi
Registration #7	2016-07-04	54.583 mi
Registration #8	2016-07-04	54.583 mi
Registration #9	2016-07-04	54.583 mi
Registration #10	2016-07-04	54.583 mi
Registration #11	2016-07-04	54.583 mi
Registration #12	2016-07-04	54.583 mi
Registration #13	2016-07-04	54.583 mi
Registration #14	2016-07-04	54.583 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1691 mm
Height	1550 mm
Length	4083 mm
Wheel base	2600 mm
Kerb weight	1092 kg
Max. allowed weight	1546 kg

Additional information

Fuel tank capacity	46 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Engine number	297604
---------------	--------