



report date: 2024-03-28

General information

Make	CITROEN
Model	XSARA HDI DESIRE PICASSO E4
Colour	Grey
Year of manufacture	-
Top speed	109 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	215 Nm at 1.750 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	43.5 mpg
Consumption extra urban	65.7 mpg
Consumption combined	55.4 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-08-25
Pictures	12
Listing price	View report



source: cargurus.co.uk

**MOT history**

MOT #20	2022-04-06 11:49
MOT test number	609660210688
Result	✓ Passed
Next expiry date	2023-04-05
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #19	2021-03-16 12:26
MOT test number	636980755531
Result	✓ Passed
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #18	2021-03-16 10:07
MOT test number	742003761244
Result	✗ Failed
Fail	Nearside Stop lamp(s) not working (4.3.1 (a) (ii))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #17	2020-03-07 11:35
MOT test number	150645629701
Result	✓ Passed
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #16** 2020-03-07 10:07**MOT test number** 298185713813**Result** ✗ Failed**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #15** 2019-03-16 09:49**MOT test number** 741317868960**Result** ✓ Passed**MOT #14** 2019-03-16 08:29**MOT test number** 195188614056**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #13** 2018-03-24 10:02**MOT test number** 975652828303**Result** ✓ Passed**MOT #12** 2018-03-24 08:26**MOT test number** 969398999038**Result** ✗ Failed**Fail** Nearside Front Anti-roll bar linkage ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)

**MOT #11** 2017-03-25 08:24**MOT test number** 992138501640**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #10** 2016-03-30 13:09**MOT test number** 374243240144**Result** ✓ Passed**Advice** Nearside front tyre wearing on outer edge**MOT #9** 2016-03-30 13:06**MOT test number** 905527118998**Result** ✗ Failed**Advice** Nearside front tyre wearing on outer edge**Fail** Exhaust emits an excessive level of metered smoke for a turbo charged engine (7.4.B.3b)**MOT #8** 2015-03-28 09:40**MOT test number** 967187885043**Result** ✓ Passed**MOT #7** 2014-03-22 10:57**MOT test number** 867441184094**Result** ✓ Passed**MOT #6** 2013-03-22 10:28**MOT test number** 879621083073**Result** ✓ Passed

**MOT #5** 2013-03-22 10:28**MOT test number** 676651683077**Result** ✗ Failed**Pass with rectification** Offside Stop lamp not working (1.2.1b)**MOT #4** 2012-03-28 13:08**MOT test number** 845178582042**Result** ✓ Passed**Notice** Front discs slightly worn**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #3** 2011-03-29 09:24**MOT test number** 326538081071**Result** ✓ Passed**MOT #2** 2010-03-25 09:25**MOT test number** 234434680020**Result** ✓ Passed**Notice** Both front tyres wearing on outer edges**Notice** Both rear tyres wearing on outer edges**MOT #1** 2009-03-04 15:51**MOT test number** 932483869060**Result** ✓ Passed



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	0
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2006-03-31
Last registration	2022-04-06
Complete history	See info



Registration #1	2006-03-31	14 mi
Registration #2	2009-03-04	26.866 mi
Registration #3	2010-03-25	39.051 mi
Registration #4	2011-03-29	50.800 mi
Registration #5	2012-03-28	63.445 mi
Registration #6	2013-03-22	70.743 mi
Registration #7	2014-03-22	75.245 mi
Registration #8	2015-03-28	79.745 mi
Registration #9	2016-03-30	85.867 mi
Registration #10	2016-03-30	85.867 mi
Registration #11	2017-03-25	92.338 mi
Registration #12	2018-03-25	92.338 mi
Registration #13	2019-03-25	92.338 mi
Registration #14	2020-03-25	92.338 mi
Registration #15	2021-03-25	92.338 mi
Registration #16	2022-03-25	92.338 mi
Registration #17	2023-03-25	92.338 mi
Registration #18	2024-03-25	92.338 mi
Registration #19	2025-03-25	92.338 mi
Registration #20	2026-03-25	92.338 mi
Registration #21	2027-03-25	92.338 mi

More info >



Safety ratings

NCAP rating

★ ★ ★ ★ ★

Video [see crash video](#)

Dimensions & weight

Width	1751 mm
Height	1637 mm
Length	4276 mm
Wheel base	2760 mm
Kerb weight	1300 kg
Max. allowed weight	1850 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	JB663026786