



report date: 2024-03-28

General information

| | |
|---------------------|------------------|
| Make | VOLKSWAGEN |
| Model | T-ROC R-LINE TDI |
| Colour | Red |
| Year of manufacture | 2019 |
| Top speed | 116 mph |
| 0 - 100 km/h | 10.9 seconds |
| 0 - 60 mph | 8.6 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|--------------------------|
| Power | 85 kW / 116 HP / 114 BHP |
| Max. torque | 250 Nm at 1.750 rpm |
| Engine capacity | 1.598 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 56.5 mpg |
| Consumption extra urban | 70.6 mpg |
| Consumption combined | 2.8 mpg |
| CO2 emission | 115 g/km |
| CO2 label | C |





Internet history

Entry 2

| | |
|---------------|-----------------------------|
| Date | 2021-09-28 |
| Pictures | 0 |
| Listing price | View report |

source: heycar.co.uk

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-09-02 |
| Pictures | 25 |
| Listing price | View report |



source: autotrader.co.uk



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2025-03-07 |
| MOT pass rate | 100 % |
| MOT passed | 4 |
| Failed MOT tests | 0 |
| Total advice items | 7 |
| Total items failed | 0 |

MOT #4 2024-03-08 16:15

MOT test number 592083520307

Result ✓ Passed

Next expiry date 2025-03-07

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear (5.3.4 (a) (i))

Minor Windscreen damaged but not adversely affecting driver's view in zone B not exceeding 5mm (3.2 (a) (i))

Advice Rear Tyre slightly damaged/cracking or perishing nearside and offside (5.2.3 (d) (ii))

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear (5.3.4 (a) (i))

Advice Front Tyre slightly damaged/cracking or perishing nearside and offside (5.2.3 (d) (ii))

MOT #3 2023-08-31 09:08

MOT test number 134737235502

Result ✓ Passed

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #2 2022-08-16 12:20

MOT test number 169977457481

Result ✓ Passed



| | |
|-----------------|------------------|
| MOT #1 | 2021-09-02 09:14 |
| MOT test number | 858423133724 |
| Result | ✓ Passed |



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
7 March 2025

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 March |
| Days left | 306 |
| MOT expiry date | 7 March 2025 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|---|------------|
| Vehicle class | 49 |
| Band | G |
| First licence fee (12 months) | £ 210,00,- |
| First licence fee diesel non RDE2 tested (12 months) | £ 255,00,- |
| Standard rate (12 months) | £ 180,00,- |
| Standard rate (6 months) | £ 99,00,- |
| Premium rate (12 months) | £ 570,00,- |
| Premium rate (6 months) | £ 313,50,- |



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

| | |
|----------------------|--|
| Number of plates | 1 |
| Current registration |  PK19HXR |
| Plate since | 2019-03-28 |
| Current registration |  PK19HXR |
| Plate since | 2019-03-28 |

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

| | | |
|-------------------|------------|------|
| Finance company | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type | XXXXXXXXXX | XXXX |
| Agreement term | XXXXXXXXXX | XXXX |
| Agreement number | XXXXXXXXXX | XXXX |
| Contact info | XXXXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 7 |
| First mileage registration | 2019-03-11 |
| Last registration | 2024-03-08 |
| Complete history | See info |



| | | |
|-----------------|------------|-----------|
| Registration #1 | 2019-03-11 | 12 mi |
| Registration #2 | 2021-09-02 | 19.866 mi |
| Registration #3 | 2023-03-20 | 25.277 mi |
| Registration #4 | 2023-03-20 | 25.277 mi |
| Registration #5 | 2023-03-20 | 25.277 mi |
| Registration #6 | 2023-03-20 | 25.277 mi |
| Registration #7 | 2023-03-20 | 25.277 mi |

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

| | |
|----------------|---------------------------------|
| NCAP rating | ★★★★★ |
| Adult | 96% |
| Children | 87% |
| Pedestrian | 79% |
| Safety systems | 71% |
| Overall rating | 86% |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1819 mm |
| Height | 1573 mm |
| Length | 4234 mm |
| Wheel base | 2603 mm |
| Kerb weight | 1320 kg |
| Max. allowed weight | 1890 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 50 l |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |

| | |
|-----------------|------------|
| Number of seats | 5 |
| Number of axles | 2 |
| Engine number | DGTE809662 |