



report date: 2024-03-29

General information

Make	LAND ROVER
Model	DEFENDER TD XS STATION WAGON
Colour	Grey
Year of manufacture	2011
Top speed	90 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	122 BHP
Max. torque	360 Nm at 2.000 rpm
Engine capacity	2.198 cc
Cylinders	4
Fuel type	Diesel
Consumption city	24.1 mpg
Consumption extra urban	30.1 mpg
Consumption combined	27.7 mpg





LABEL UNKNOWN



Internet history

Entry 1

Date	2022-01-12
Pictures	9
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-01-17
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	19
Total items failed	14

MOT #13	2024-01-18 16:36
MOT test number	385553922875
Result	✓ Passed
Next expiry date	2025-01-17
Minor	Nearside Drag link end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

MOT #12	2024-01-18 16:36
MOT test number	504558350230
Result	✗ Failed
Pass with rectification	Offside Headlamp aim too high (4.1.2 (a))
Pass with rectification	Nearside Headlamp aim too high (4.1.2 (a))
Minor	Nearside Drag link end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

MOT #11	2022-11-11 12:31
MOT test number	165185230919
Result	✓ Passed

**MOT #10**

2022-11-10 12:29

MOT test number

762646326721

Result

✗ Failed

- Fail** Horn not working (7.7 (a))
- Fail** Offside Rear Rear fog lamp does not emit a steady red light (4.5.4 (a))
- Fail** Nearside Front Track rod end ball joint dust cover insecure so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))
- Fail** Reversing lamp inoperative (4.6.1 (a))
- Fail** Front Windscreen washer jets misaligned and not providing sufficient fluid to the windscreen (3.5 (a))
- Fail** Offside Front Track rod end ball joint dust cover insecure so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))

MOT #9

2021-09-30 14:15

MOT test number

524460762949

Result

✓ Passed

MOT #8

2020-09-08 08:29

MOT test number

916176929574

Result

✓ Passed

- Advice** Vehicle structure is corroded but structural rigidity is not significantly reduced Nearside and offside front (6.1.1 (c) (i))
- Minor** Offside Front Steering linkage ball joint ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))
- Advice** Nearside Front Seat belt slightly damaged (7.1.2 (b) (i))
- Advice** Vehicle structure is corroded but structural rigidity is not significantly reduced Rear crossmember (6.1.1 (c) (i))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened Corrosion on inner faces (1.1.14 (a) (ii))
- Minor** Nearside Front Steering linkage ball joint ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

**MOT #7** 2019-09-19 09:34**MOT test number** 650780887056**Result** ✓ Passed**Advice** Nearside Front Seat belt slightly damaged (7.1.2 (b) (i))**Advice** Rear Vehicle structure is corroded but structural rigidity is not significantly reduced crossmember (6.1.1 (c) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Offside Front Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))**MOT #6** 2018-10-08 08:36**MOT test number** 356664513904**Result** ✓ Passed**MOT #5** 2017-11-13 17:07**MOT test number** 458688632714**Result** ✓ Passed**Advice** Nearside Rear wheel bearing has slight play (2.6.2)**Advice** Nearside Front Seat belt stitching slightly frayed (5.2.2b)

**MOT #4**

2017-11-10 11:04

MOT test number

949203926709

Result

✗ Failed

- Advice** Nearside Rear Lower Shock absorber has a slightly worn bush (2.7.4)
- Fail** Nearside Rear Brake lining(s) less than 1.5 mm thick (3.5.1g)
- Fail** Nearside Front Seat belt anchorage prescribed area is excessively corroded below passenger seat (5.2.6)
- Advice** Nearside Front Seat belt stitching slightly frayed (5.2.2b)
- Advice** Nearside Rear wheel bearing has slight play (2.6.2)
- Fail** Offside Rear Lower Shock absorber has an excessively worn bush (2.7.4)
- Advice** Rear brake disc worn, pitted or scored, but not seriously weakened offside and nearside (3.5.1i)
- Fail** Offside Rear Brake lining(s) insecure (3.5.1g)
- Advice** Brake pipe slightly corroded front to rear at rear flexi (3.6.B.2c)
- Fail** Offside Front Seat belt damaged sufficient to significantly weakened the webbing (5.2.2a)
- Fail** Brake performance not tested due to condition of rear brake pads (3.7.A.1)

MOT #3

2016-11-14 10:49

MOT test number

173073883934

Result

✓ Passed

MOT #2

2015-11-03 09:16

MOT test number

466915535417

Result

✓ Passed

MOT #1

2014-12-03 10:03

MOT test number

557747334339

Result

✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
17 January 2025

Tax status		Valid until 1 January
Days left		247
MOT expiry date		17 January 2025
Full MOT history		See MOT history



Damage history


Check the damage history for this LAND ROVER. See if, where and when this LAND ROVER had damage and the car repair costs. We also check if this LAND ROVER was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra LAND ROVER salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this LAND ROVER in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this LAND ROVER? How many owners did this LAND ROVER have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this LAND ROVER had different number plates.

Number of plates	1
Current registration	RE61YFM
Plate since	2024-03-29
Current registration	RE61YFM
Plate since	2024-03-29

More info >



Finance check

Check if this LAND ROVER is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LAND ROVER has been settled.

If not, and you buy this LAND ROVER then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this LAND ROVER is financed.


Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2011-12-16
Last registration	2024-01-18
Complete history	See info



Registration #1	2011-12-16	25 mi
Registration #2	2014-12-03	39.170 mi
Registration #3	2015-11-03	47.363 mi
Registration #4	2016-11-14	57.002 mi
Registration #5	2017-11-10	62.084 mi
Registration #6	2017-11-13	62.120 mi
Registration #7	2018-10-08	64.247 mi
Registration #8	2019-09-19	66.290 mi
Registration #9	2019-09-19	66.290 mi
Registration #10	2019-09-19	66.290 mi
Registration #11	2019-09-19	66.290 mi
Registration #12	2019-09-19	66.290 mi
Registration #13	2019-09-19	66.290 mi
Registration #14	2019-09-19	66.290 mi
Registration #15	2019-09-19	66.290 mi

More info >



Dimensions & weight

Width	1790 mm
Height	2128 mm
Length	3880 mm
Wheel base	2360 mm
Kerb weight	1875 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	111020125736DT224