





General information

Make	MAZDA
Model	2 SE
Colour	Blue
Year of manufacture	2014
Top speed	104 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	74 BHP	0 < 101 A
Max. torque	119 Nm at 3.500 rpm	101 - 120 B
Engine capacity	1.349 сс	121 - 140
Cylinders	4	141 - 165 F
uel type	Petrol	166 - 185
Consumption city	45.6 mpg	186 - 225
onsumption extra urban	65.7 mpg	225+
Consumption combined	56.5 mpg	
CO2 emission	115 g/km	
CO2 label	С	
CO2 label	С	





Internet history

Entry 2

Date Pictures 2021-02-06

22

Listing price

View report



source: yesauto.com

Entry 1

Date

Pictures

Listing price

2021-02-01 10

View report



source: autoonline.co.uk









MOT history

MOT expiry date	2025-02-08
MOT pass rate	89 %
MOT passed	8
Failed MOT tests	1
Total advice items	15
Total items failed	1

МОТ #9	2024-01-24 08:49
MOT test number	814232686774
Result	✓ Passed
Next expiry date	2025-02-08
Advice Front Brake disc worn, but not excessively (1.1.14 (a) (i))	
Minor Offside Front Windscreen wiper blade defective smearing the screen (3.4 (b) (i))	
Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt	

MOT #8		2023-02-08 15:31
MOT test	number	151472302548
Result		✓ Passed
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt	
Advice	Front Brake disc worn, but not excessively both sides have slight lip to edges	(1.1.14 (a) (i))



MOT #7	2023-02-01 14:22
MOT test number	569176589354
Result	🗙 Failed
Fail Offside Rear Tyre has a cut in excess of the requirements deep enough to (5.2.3 (d) (i))	o reach the ply or cords
Advice Front Brake disc worn, but not excessively both sides have slight lip to	o edges (1.1.14 (a) (i))
Advice Nearside Rear Child Seat fitted not allowing full inspection of adult bel	t
Advice Nearside Rear Tyre worn close to legal limit/worn on edge heavily weat cuts present (5.2.3 (e))	ring on edges and has small

МОТ #6	2022-02-01 08:46
MOT test number	349354107657
Result	✓ Passed
Advice Front Brake disc worn, but not excessively both	sides have slight lip to edges (1.1.14 (a) (i))
Advice Nearside Rear Child Seat fitted not allowing full i	inspection of adult belt
Advice Rear Tyre worn close to legal limit/worn on edge cracking and perishing (5.2.3 (e))	both rear tyres wearing on inner edges both also

MOT #5	2021-02-09 12:19
MOT test number	919843950943
Result	✓ Passed

MOT #4	2020-01-13 14:36
MOT test number	506452431927
Result	✓ Passed

MOT #3	2019-01-14 15:30
MOT test number	858904685946
Result	✓ Passed
Advice Both front tyres have worn smooth on inner edges	
Minor Nearside Windscreen wiper blade defective (3.4 (b) (i))	





MOT #2	2018-01-23 15:27
MOT test number	663146813075
Result	✓ Passed
Advice Nearside Front Tyre worn close to the legal limit 3mm and perished (4.1.E.1)	
MOT #1	2017-02-04 09:38
MOT test number	649828487828

Result

🗸 Passed



Tax & MOT check

✓ Taxed Tax due: 1 March 2025	✓ MOT Expires: 8 February 2025
Tax status	Valid until 1 March
Days left	305
MOT expiry date	8 February 2025
Full MOT history	See MOT history
Tax calculation	

Vehicle class	48
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-





Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FEIDO
Category	Lamp
Туре	
Damage 2	AMPLI
Date	1. the second se
Category	ante
Туре	

Extra MAZDA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 =





Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

NUMBER OF CONTRACTOR OF CONTRA	

	More info >
Plate changes	
See in this check if this MAZDA had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	
	More info >





Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MAZDA is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	



EN63OMT report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2014-02-06
Last registration	2024-01-24
Complete history	See info



Registration #1	2014-02-06	25 mi
Registration #2	2017-02-04	13.503 mi
Registration #3	2018-01-23	19.809 mi
Registration #4	2019-01-14	24.861 mi
Registration #5	2020-01-13	29.443 mi
Registration #6		11.777 esi
Registration #7		11.777 mi
Registration #8		11.777 mi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		11.117 esi



EN63OMT report date: 2024-03-29

Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight	
Width	1695 mm
Height	1475 mm
Length	3885 mm
Wheel base	2490 mm
Kerb weight	1030 kg
Max. allowed weight	1485 kg
Additional information	
Additional information Fuel tank capacity	42
	42 I Multi-Point Injection
Fuel tank capacity	
Fuel tank capacity Fuel delivery	Multi-Point Injection
Fuel tank capacity Fuel delivery Number of doors	Multi-Point Injection 5