



PEUGEOT



report date: 2024-03-28

General information

Make	PEUGEOT
Model	307 SPORT
Colour	Black
Year of manufacture	-
Top speed	118 mph
0 - 60 mph	10.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	107 BHP
Max. torque	147 Nm at 4.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	29.7 mpg
Consumption extra urban	48.7 mpg
Consumption combined	39.2 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-12-11
Pictures	50
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT #19	2021-12-10 11:26
MOT test number	133480414767
Result	✓ Passed
Next expiry date	2022-12-21
Advice	Rear Brake pad(s) wearing thin both sides (1.1.13 (a) (ii))

MOT #18	2021-12-08 17:03
MOT test number	314719159211
Result	✗ Failed
Advice	Rear Brake pad(s) wearing thin both sides (1.1.13 (a) (ii))
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #17	2020-12-22 14:04
MOT test number	683077806391
Result	✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #16	2020-12-22 11:16
MOT test number	158923247821
Result	✗ Failed
Fail	Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #15	2019-11-28 15:18
MOT test number	504032254955
Result	✓ Passed
Minor	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))

**MOT #14** 2019-11-28 15:12**MOT test number** 404950122876**Result** ✗ Failed**Fail** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))**MOT #13** 2018-11-09 11:39**MOT test number** 441074575412**Result** ✓ Passed**Advice** Nearside Front Outer Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #12** 2018-11-09 10:19**MOT test number** 109701580834**Result** ✗ Failed**Advice** Nearside Front Outer Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**MOT #11** 2017-11-07 17:44**MOT test number** 906937680820**Result** ✓ Passed**Advice** Nearside Front Play in steering rack inner joint(s)

**MOT #10** 2016-10-15 10:22**MOT test number** 780097826012**Result** ✓ Passed

- Advice** Front Exhaust has a minor leak of exhaust gases (7.1.2)
- Advice** Nearside Play in steering rack inner joint(s)
- Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)

MOT #9 2015-07-16 16:07**MOT test number** 236427195465**Result** ✓ Passed

- Advice** Inner Rear Brake pad(s) wearing thin (3.5.1g)

MOT #8 2015-07-14 17:07**MOT test number** 905115895179**Result** ✗ Failed

- Fail** Offside Rear fog lamp not working (1.3.2b)
- Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)
- Advice** Inner Rear Brake pad(s) wearing thin (3.5.1g)
- Fail** Offside Stop lamp not working (1.2.1b)
- Fail** Offside Rear Direction indicator not working (1.4.A.2c)
- Pass with rectification** Offside Headlamp not working on dipped beam (1.7.5a)
- Fail** Offside Rear position lamp(s) not working (1.1.A.3b)

**MOT #7** 2014-06-26 11:56**MOT test number** 179817674178**Result** ✓ Passed**Notice** O/S/F tyre wearing on edge**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Slight bind on rear brakes**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2013-07-01 14:29**MOT test number** 636622183137**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Notice** Slight brake bind on both rear wheels**MOT #5** 2012-06-14 09:27**MOT test number** 419986762109**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Damage down offside of vehicle**Advice** Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #4** 2011-02-12 09:22**MOT test number** 445433741094**Result** ✓ Passed



MOT #3	2010-01-23 12:41
MOT test number	620963220028
Result	✓ Passed

MOT #2	2010-01-23 08:31
MOT test number	524083620013
Result	✗ Failed
Fail	Rear Exhaust system not adequately supported (7.1.1)
Fail	Windscreen washer provides insufficient washer liquid (8.2.3)

MOT #1	2008-11-22 11:29
MOT test number	880297028332
Result	✓ Passed
Advice	Steering pivot point has slight play (2.2.B.1g)



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	KX55YAW
Plate since	2019-03-28
Current registration	KX55YAW
Plate since	2019-03-28

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2005-09-13
Last registration	2021-12-10
Complete history	See info



Registration #1	2005-09-13	21 mi
Registration #2	2008-11-22	21.796 mi
Registration #3	2010-01-23	24.866 mi
Registration #4	2010-01-23	24.866 mi
Registration #5	2011-02-12	27.452 mi
Registration #6	2012-06-14	29.652 mi
Registration #7	2013-07-01	31.403 mi
Registration #8	2014-06-26	33.025 mi
Registration #9	2015-07-14	34.772 mi
Registration #10	2015-07-16	34.779 mi
Registration #11	2016-10-15	36.532 mi
Registration #12	2016-10-15	36.532 mi
Registration #13	2016-10-15	36.532 mi
Registration #14	2016-10-15	36.532 mi
Registration #15	2016-10-15	36.532 mi
Registration #16	2016-10-15	36.532 mi
Registration #17	2016-10-15	36.532 mi
Registration #18	2016-10-15	36.532 mi
Registration #19	2016-10-15	36.532 mi
Registration #20	2016-10-15	36.532 mi
Registration #21	2016-10-15	36.532 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1746 mm
Height	1512 mm
Length	4202 mm
Wheel base	2608 mm
Kerb weight	1256 kg
Max. allowed weight	1660 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	FX7F2647868