



GP56LWX

report date: 2024-03-28

General information

Make	BMW
Model	X3 D M SPORT
Colour	Black
Year of manufacture	-
Top speed	137 mph
0 - 60 mph	7.7 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	215 BHP
Max. torque	500 Nm at 1.750 rpm
Cylinders	6
Fuel type	Diesel
Consumption city	25.2 mpg
Consumption extra urban	39.8 mpg
Consumption combined	32.8 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-06-16
Pictures	18
Listing price	View report



source: [autotrader.co.uk](#)

**MOT history**

MOT #21	2022-01-21 15:41
MOT test number	338333755033
Result	✓ Passed
Next expiry date	2023-02-15
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #20	2021-02-16 15:10
MOT test number	625914049914
Result	✓ Passed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

MOT #19	2020-01-31 18:21
MOT test number	633177792959
Result	✓ Passed
Advice	Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Offside Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #18	2020-01-31 13:06
MOT test number	985676000199
Result	✗ Failed
Advice	Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Fail	Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))
Fail	Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))
Advice	Offside Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #17**

2019-02-08 14:58

MOT test number

463838805696

Result

✓ Passed

Advice Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MOT #16**

2019-02-08 12:47

MOT test number

917003196123

Result

✗ Failed

Fail Electronic stability control warning lamp indicates a fault (7.12 (e))**Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))**Fail** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MOT #15**

2018-02-15 15:28

MOT test number

555830667548

Result

✓ Passed

MOT #14

2018-02-15 11:39

MOT test number

482200072018

Result

✗ Failed

Fail Offside Rear coil spring broken (2.4.C.1a)**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)



MOT #13	2017-01-04 11:45
MOT test number	863506462466
Result	✓ Passed
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #12	2017-01-03 12:03
MOT test number	800541626992
Result	✗ Failed
Fail	Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
Fail	Offside Suspension arm attachment bracket/mounting nut missing (2.4.G.1)

MOT #11	2015-12-12 14:24
MOT test number	347583650333
Result	✓ Passed

MOT #10	2014-12-29 10:26
MOT test number	565343364324
Result	✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
Notice	Engine covers fitted obscuring some components in the engine bay
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
Notice	Under-trays fitted obscuring some underside components
Notice	Front tyres splitting around full circumference of tread

**MOT #9**

2014-12-22 10:20

MOT test number

587806954372

Result**✗ Failed**

- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Notice** Engine covers fitted obscuring some components in the engine bay
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Fail** Rear parking brake recording little or no effort (3.7.B.6a)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Notice** Under-trays fitted obscuring some underside components
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Notice** Front tyres splitting around full circumference of tread
- Fail** Parking brake lever has no reserve travel (3.1.6b)
- Fail** Parking brake: efficiency below requirements (3.7.C.1b)

MOT #8

2013-12-31 10:30

MOT test number

697685263316

Result**✓ Passed**

- Notice** Under-trays fitted obscuring some underside components
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Notice** Engine covers fitted obscuring some components in the engine bay

**MOT #7**

2013-12-27 11:15

MOT test number

867111763374

Result**✗ Failed**

- Fail** Parking brake: efficiency below requirements (3.7.B.7)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Notice** Under-trays fitted obscuring some underside components
- Pass with rectification** Offside Front Headlamp insecure (1.7.3)
- Advice** Parking brake lever has little reserve travel (3.1.6b)
- Notice** Engine covers fitted obscuring some components in the engine bay
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Pass with rectification** Nearside Front Headlamp insecure (1.7.3)

MOT #6

2013-01-02 10:32

MOT test number

386242203080

Result**✓ Passed**

- Notice** Child seat fitted not allowing full inspection of adult belt
- Advice** Parking brake lever has little reserve travel (3.1.6b)
- Notice** Under-trays fitted obscuring some underside components

MOT #5

2012-12-28 11:00

MOT test number

638703262322

Result**✗ Failed**

- Notice** Child seat fitted not allowing full inspection of adult belt
- Advice** Parking brake lever has little reserve travel (3.1.6b)
- Fail** Parking brake: efficiency below requirements (3.7.C.1b)
- Notice** Under-trays fitted obscuring some underside components

**MOT #4** 2011-12-28 14:22**MOT test number** 197402061330**Result** ✓ Passed**Notice** Covers under car**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Notice** Brake pad warning light on**MOT #3** 2011-12-28 10:04**MOT test number** 465812361316**Result** ✗ Failed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Notice** Brake pad warning light on**Fail** Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Notice** Covers under car**MOT #2** 2010-12-30 10:59**MOT test number** 210024360378**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Nearside rear tyre worn close to 3mm in centre of tread**MOT #1** 2009-12-11 15:18**MOT test number** 203855649394**Result** ✓ Passed**Notice** No diesel emissions recorded -too clean to establish a minimum reading .



Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this BMW? How many owners did this BMW have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this BMW had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this BMW is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2006-12-22
Last registration	2022-01-21
Complete history	See info



Registration #1	2006-12-22	10 mi
Registration #2	2009-12-11	39.385 mi
Registration #3	2010-12-30	55.070 mi
Registration #4	2011-12-28	66.639 mi
Registration #5	2011-12-28	66.639 mi
Registration #6	2012-12-28	82.393 mi
Registration #7	2013-01-02	82.559 mi
Registration #8	2013-12-27	97.027 mi
Registration #9	2013-12-31	97.315 mi
Registration #10	2014-12-22	108.500 mi
Registration #11	2014-12-29	108.964 mi
Registration #12	2015-12-12	112.658 mi
Registration #13	2016-01-01	112.658 mi
Registration #14	2016-01-01	112.658 mi
Registration #15	2016-01-01	112.658 mi
Registration #16	2016-01-01	112.658 mi
Registration #17	2016-01-01	112.658 mi
Registration #18	2016-01-01	112.658 mi
Registration #19	2016-01-01	112.658 mi
Registration #20	2016-01-01	112.658 mi
Registration #21	2016-01-01	112.658 mi
Registration #22	2016-01-01	112.658 mi
Registration #23	2016-01-01	112.658 mi

More info >



Car features

The BMW factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete BMW factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1853 mm
Height	1674 mm
Length	4565 mm
Wheel base	2795 mm
Kerb weight	1810 kg
Max. allowed weight	2355 kg

Additional information

Fuel tank capacity	67 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	22856157