



General information

Make	VOLKSWAGEN
Model	EOS TSI
Colour	Black
Year of manufacture	2009
Top speed	135 mph
0 - 60 mph	8.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	160 BHP
Max. torque	240 Nm at 1.500 rpm
Engine capacity	1.390 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.5 mpg
Consumption extra urban	52.3 mpg
Consumption combined	42.8 mpg
CO2 emission	154 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-06-14
Pictures	5
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-03-15
MOT pass rate	71 %
MOT passed	12
Failed MOT tests	5
Total advice items	30
Total items failed	6

MOT #17 2023-03-06 12:23

MOT test number 573883600493

Result ✓ Passed

Next expiry date 2024-03-15

Minor Rear Position lamp with a multiple light source up to 1/2 not functioning Both sides (4.2.1 (a) (i))

Minor Rear Direction indicator with a multiple light source up to 1/2 not functioning Both sides (4.4.1 (a) (i))

MOT #16 2022-03-16 09:56

MOT test number 907803951468

Result ✓ Passed

MOT #15 2022-03-15 11:41

MOT test number 312344658662

Result ✗ Failed

Advice Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

Advice Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Fail Nearside Side repeater not working (4.4.1 (a) (ii))

**MOT #14** 2021-02-18 15:11**MOT test number** 594855323132**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge wearing inner edge (5.2.3 (e))**Advice** Undertrays fitted preventing a full inspection**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #13** 2020-02-06 16:05**MOT test number** 525004304957**Result** ✓ Passed**MOT #12** 2019-02-13 14:31**MOT test number** 168513327109**Result** ✓ Passed**MOT #11** 2019-02-13 11:53**MOT test number** 371547925830**Result** ✗ Failed**Fail** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))**MOT #10** 2018-03-06 17:05**MOT test number** 511544100506**Result** ✓ Passed**Advice** Rear Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement both (2.4.G.2)**Advice** Under tray fitted full length

**MOT #9** 2018-03-06 11:40**MOT test number** 128845132653**Result** ✗ Failed

Advice Rear Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement both (2.4.G.2)

Fail Nearside Front coil spring broken (2.4.C.1a)

Advice Under tray fitted full length

MOT #8 2017-02-16 08:31**MOT test number** 548672646800**Result** ✓ Passed

Advice Tyre worn close to the legal limit both front (4.1.E.1)

MOT #7 2017-02-15 12:35**MOT test number** 703583538518**Result** ✗ Failed

Fail Nearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)

Advice N/s/r brake grabbing slightly

Advice Tyre worn close to the legal limit both front (4.1.E.1)

Fail Windscreen wiper does not clear the windscreen effectively both (8.2.2)

MOT #6 2016-05-23 13:32**MOT test number** 833924515710**Result** ✓ Passed

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #5** 2015-04-28 17:28**MOT test number** 385498415122**Result** ✓ Passed**MOT #4** 2015-04-20 11:48**MOT test number** 656340615116**Result** ✗ Failed**Fail** Offside Front coil spring broken (2.4.C.1a)**MOT #3** 2014-05-21 09:29**MOT test number** 436281844185**Result** ✓ Passed**Notice** Oil leak**Notice** Both rear tyres cracked and perished**Notice** Nail in offside rear tyre**Notice** Under-trays fitted obscuring some underside components**MOT #2** 2013-05-13 15:41**MOT test number** 306043233118**Result** ✓ Passed**Notice** Nail in nearside front tyre**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Nearside front sill damaged**Notice** Under-trays fitted obscuring some underside components**Notice** Nearside and offside rear tyres cracked on outer sidewalls**Advice** Centre Exhaust has a minor leak of exhaust gases (7.1.2)



MOT #1	2012-05-10 12:19
MOT test number	737281732156
Result	✓ Passed
<div><div>Advice</div>Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)</div>	



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	7
Current registration	 *****
Plate since	2019-06-29
Current registration	 *****
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2009-04-23
Last registration	2023-03-06
Complete history	See info



Registration #1	2009-04-23	26 mi
Registration #2	2012-05-10	21.576 mi
Registration #3	2013-05-13	26.176 mi
Registration #4	2014-05-21	32.564 mi
Registration #5	2015-04-20	37.050 mi
Registration #6	2015-04-28	37.050 mi
Registration #7	2016-05-23	40.557 mi
Registration #8	2017-02-15	43.975 mi
Registration #9	2017-02-16	43.975 mi
Registration #10	2018-03-06	49.267 mi
Registration #11	2019-05-20	55.557 mi
Registration #12	2019-05-20	55.557 mi
Registration #13	2019-05-20	55.557 mi
Registration #14	2019-05-20	55.557 mi
Registration #15	2019-05-20	55.557 mi
Registration #16	2019-05-20	55.557 mi
Registration #17	2019-05-20	55.557 mi
Registration #18	2019-05-20	55.557 mi
Registration #19	2019-05-20	55.557 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	87%
Children	73%
Pedestrian	53%
Safety systems	71%
Overall rating	76%
Video	see crash video



Dimensions & weight

Width	1810 mm
Height	1404 mm
Length	4256 mm
Wheel base	2578 mm
Kerb weight	1318 kg
Max. allowed weight	1720 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	2

Number of seats	4
Number of axles	2
Engine number	CAV 101705