



report date: 2024-03-29

General information

Make	FIAT
Model	BRAVO DYNAMIC
Colour	Red
Year of manufacture	2009
Top speed	111 mph
0 - 60 mph	12.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	90 BHP
Max. torque	128 Nm at 4.500 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.5 mpg
Consumption extra urban	50.4 mpg
Consumption combined	42.2 mpg
CO2 emission	156 g/km
CO2 label	G



Internet history

Entry 1

Date	2022-06-17
Pictures	3
Listing price	View report



source: **cargurus.co.uk**



MOT history

MOT expiry date	2025-03-12
MOT pass rate	72 %
MOT passed	13
Failed MOT tests	5
Total advice items	33
Total items failed	12

MOT #18 2024-02-22 17:03

MOT test number 933358937976

Result ✓ Passed

Next expiry date 2025-03-12

Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Items removed from driver's view prior to test

MOT #17 2024-02-22 12:04

MOT test number 751011706684

Result ✗ Failed**Advice** Items removed from driver's view prior to test**Fail** Emissions unable to be completed (8.2.1.2 (d))**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**Fail** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Fail** Exhaust has a major leak of exhaust gases (6.1.2 (a))

MOT #16 2023-02-21 15:09

MOT test number 842883149115

Result ✓ Passed**Advice** Rear exhaust rusty

**MOT #15**

2023-02-20 13:39

MOT test number

569879540740

Result

✗ Failed

Fail Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))**Fail** Offside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Fail** Exhaust has a major leak of exhaust gases (6.1.2 (a))**Advice** Rear exhaust rusty**MOT #14**

2022-03-02 09:59

MOT test number

456941770724

Result

✓ Passed

MOT #13

2021-02-27 13:44

MOT test number

977672820895

Result

✓ Passed

MOT #12

2020-02-17 14:56

MOT test number

752311545722

Result

✓ Passed

Advice Offside Rear Inner Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Front Inner Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Front Inner Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #11**

2020-02-17 13:56

MOT test number

586942592699

Result

✗ Failed

Fail Nearside Front Inner Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Inner Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Rear Inner Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Offside Front Inner Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Inner Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #10**

2019-03-13 13:05

MOT test number

852335739287

Result

✓ Passed

MOT #9

2019-03-11 13:17

MOT test number

160698499961

Result

✗ Failed

Fail Offside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**MOT #8**

2018-02-13 08:56

MOT test number

977923013391

Result

✓ Passed

Advice Front registration plate delaminated but not likely to be misread (6.3.1d)**Advice** Front Oil leak Engine**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Rear registration plate delaminated but not likely to be misread (6.3.1d)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Front front brake fluctuating, but not excessively (3.7.B.3)

**MOT #7** 2017-02-08 08:24**MOT test number** 736798366117**Result** ✓ Passed

- Advice** Nearside Front Tyre slightly perished and cracked
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Rear registration plate delaminated but not likely to be misread (6.3.1d)
- Advice** Offside Front Tyre slightly perished and cracked
- Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)

MOT #6 2017-02-06 12:06**MOT test number** 638226226445**Result** ✗ Failed

- Advice** Nearside Front Tyre slightly perished and cracked
- Fail** Nearside Headlamp aim too high (1.8)
- Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Front Tyre slightly perished and cracked
- Fail** Offside Rear Passenger's seat cannot be secured in the upright position. (6.2.A.2)
- Advice** Rear registration plate delaminated but not likely to be misread (6.3.1d)

MOT #5 2016-01-25 09:22**MOT test number** 691853512464**Result** ✓ Passed

**MOT #4** 2015-02-09 12:59**MOT test number** 265830545017**Result** ✓ Passed

- Notice** Engine covers fitted obscuring some components in the engine bay
- Advice** Rear registration plate delaminated but not likely to be misread (6.3.1d)
- Notice** Under-trays fitted obscuring some underside components
- Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #3 2014-02-13 12:20**MOT test number** 936094944095**Result** ✓ Passed**MOT #2** 2013-02-11 14:38**MOT test number** 538902043099**Result** ✓ Passed**MOT #1** 2012-02-15 10:26**MOT test number** 429136042041**Result** ✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 June 2024

✓
MOT

Expires:
12 March 2025

Tax status	Valid until 1 June
Days left	33
MOT expiry date	12 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2009-03-27
Last registration	2024-02-22
Complete history	See info



Registration #1	2009-03-27	6 mi
Registration #2	2012-02-15	3.464 mi
Registration #3	2013-02-11	7.637 mi
Registration #4	2014-02-13	9.692 mi
Registration #5	2015-02-09	10.659 mi
Registration #6	2016-01-25	12.068 mi
Registration #7	2017-02-06	14.484 mi
Registration #8	2017-02-08	14.492 mi
Registration #9	2018-02-13	17.639 mi
Registration #10	2019-03-11	21.869 mi
Registration #11	2020-03-20	25.000 mi
Registration #12	2021-03-20	25.000 mi
Registration #13	2022-03-20	25.000 mi
Registration #14	2023-03-20	25.000 mi
Registration #15	2024-03-20	25.000 mi
Registration #16	2025-03-20	25.000 mi
Registration #17	2026-03-20	25.000 mi
Registration #18	2027-03-20	25.000 mi
Registration #19	2028-03-20	25.000 mi
Registration #20	2029-03-20	25.000 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1792 mm
Height	1498 mm
Length	4336 mm
Wheel base	2600 mm
Kerb weight	1205 kg
Max. allowed weight	1715 kg

Additional information

Fuel tank capacity	58 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	1307868