





report date: 2024-03-28

General information

Make	ТОУОТА
Model	VERSO VALVEMATIC T SPIRIT
Colour	Silver
Year of manufacture	2009
Top speed	115 mph
0 - 60 mph	10.4 seconds
Gearbox	7 speed Manual

Engine & fuel consumption

Power	145 BHP
Max. torque	180 Nm at 4.000 rpm
Engine capacity	1.798 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.5 mpg
Consumption extra urban	47.9 mpg
Consumption combined	40.4 mpg
CO2 emission	164 g/km
CO2 label	G



CarCheck.co.uk page 1/13



Internet history

C +	-
ENTIV	

LIICI Y I	
Date	2021-10-02
Pictures	0
Listing price	View report

source: autotrader.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2024-07-02
MOT pass rate	69 %
MOT passed	11
Failed MOT tests	5
Total advice items	25
Total items failed	10

MOT #16	2023-07-03 10:55
MOT test number	868695708515
Result	✓ Passed
Next expiry date	2024-07-02

MOT #15	2023-07-03 10:55
MOT test number	866298446481
Result	X Failed
Pass with rectification	Nearside Rear Position lamp not working (4.2.1 (a) (ii))
Pass with rectification Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2	
(c))	

MOT #14	2022-06-28 09:18
MOT test number	749237362393
Result	✓ Passed

MOT #13		2022-06-28 09:18
MOT test number		563421404557
Result		× Failed
Pass with rectification	Nearside Rear Position lamp not working (4.2.1 (a) (ii))	

CarCheck.co.uk page 3/13



MOT #12 2021-07-01 08:12

MOT test number 606027398357

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #11 2020-06-09 11:18

MOT test number 150471788434

Result ✓ Passed

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #10 2020-06-09 11:18

MOT test number 387223649222

Result × Failed

Pass with rectification Nearside Rear Position lamp not working (4.2.1 (a) (ii))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #9 2018-08-02 09:26

MOT test number 621304806877

Result Passed

Advice Offside Front All position lamps no lamps fitted at time of test (4.2.1 (a))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Nearside Front All position lamps no lamps fitted at time of test (4.2.1 (a))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear All position lamps no lamps fitted at time of test (4.2.1 (a))

CarCheck.co.uk page 4/13



LL09TZK

report date: 2024-03-28

MOT #8

MOT test number

819549103370

Result

Advice Offside Front tyre close to legal limit

Advice Nearside Front tyre close to legal limit

MOT test number 438051246159

Result ✓ Passed

Advice Front windscreen wiper blades smearing screen.

Advice Offside rear tyre cracked & perished up.

Advice Offside front mirror glass cracked up.

Advice Rear brake disc's started to corroded on edges.

MOT #6

MOT test number

686897595135

Result

Notice Front wipers smearing

2015-07-16 12:22 **MOT #5** 936387995157 **MOT** test number Result × Failed Fail Nearside Front Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a) Fail Offside Obligatory mirror seriously obscured affecting the rear view (8.1.2a) Notice Front wipers smearing Fail Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1) Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 5/13



Result

LL09TZK report date: 2024-03-28

2014-07-31 17:00 MOT #4

127872914203 **MOT** test number

Result ✓ Passed

Notice Offside front tyre on 2.mm tread depth.

MOT #3 2014-07-29 18:34

MOT test number 527270414299

X Failed

Notice Nearside front driveshaft boot small damage & leaking.

Fail Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)

Notice Front brake pad linning approx 95% worn low.

Notice Offside front tyre on 2.mm tread depth.

Fail Offside Rear Registration plate lamp not working (1.1.C.1d)

Notice Front brake disc's lipped & worn.

Fail Offside front brake application uneven (3.7.B.2)

MOT #2 2013-07-23 12:34

MOT test number 698624003219

Result ✓ Passed

MOT #1 2012-08-01 17:09

MOT test number 227324112233

Result ✓ Passed

CarCheck.co.uk page 6/13



Tax & MOT check



Tax status	Valid until 1 October
Days left	155
MOT expiry date	2 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 7/13



LL09TZK

report date: 2024-03-28

Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner	بمنحاء أحا
UWNER	nistary
OVVIICI	IIISCUIV

For how long did the current and previous owner(s) have this TOYOTA? How many owner have? Check it in the premium report and see all owner registrations. Download the full it		A

	More info >	
Plate changes		
See in this check if this TOYOTA had different number plates.		
Number of plates		
Current registration	UK C	
Plate since		
Current registration	UK C	
Plate since		
	More info >	

CarCheck.co.uk page 10/13



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info


More info >

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2009-07-29
Last registration	2023-07-03
Complete history	See info



Registration #1	2009-07-29	13 mi
Registration #2	2012-08-01	59.089 mi
Registration #3	2013-07-23	80.857 mi
Registration #4	2014-07-29	102.741 mi
Registration #5	2014-07-31	102.741 mi
Registration #6	2015-07-16	122.180 mi
Registration #7	2015-07-16	122.180 mi
Registration #8	2016-08-01	145.544 mi
Registration #9	2017-07-28	98.088 mi
Registration #10		71.777 es
Registration #11		11.777 es
Registration #12		71.777 es
Registration #13		11.777 es
Registration #14		71.777 es
Registration #15		11.777 es
Registration #16		71.777 es
Registration #17		11.777 es
Registration #18		11.777 es

More info >

CarCheck.co.uk page 12/13



Car features

S0225	Air conditioning
50295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1790 mm
Height	1630 mm
Length	4440 mm
Wheel base	2780 mm
Kerb weight	1525 kg
Max. allowed weight	2125 kg

Additional information

Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	7
Number of axles CarCheck.co.uk	2 page 13/13