




report date: 2024-03-29

General information

Make	VAUXHALL
Model	ANTARA EXCLUSIV CDTI S/S
Colour	White
Year of manufacture	2013
Top speed	117 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	161 BHP
Max. torque	350 Nm at 2.000 rpm
Engine capacity	2.231 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	54.3 mpg
Consumption combined	46.3 mpg
CO2 emission	160 g/km
CO2 label	G





Internet history

Entry 2

Date	2021-08-07
Pictures	23
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)

Entry 1

Date	2021-08-01
Pictures	15
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2025-03-01
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	21
Total items failed	5

MOT #12	2024-02-14 10:32
MOT test number	337838536282
Result	✓ Passed
Next expiry date	2025-03-01
Advice	Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush, both sides (5.3.4 (a) (i))
Advice	Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #11	2024-02-14 10:32
MOT test number	532635545176
Result	✗ Failed
Pass with rectification	Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))
Advice	Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush, both sides (5.3.4 (a) (i))
Advice	Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #10**

2023-03-01 14:22

**MOT test number**

874188254968

**Result**

✓ Passed

**Advice** Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush both sides, slight play (5.3.4 (a) (i))

**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #9**

2022-02-24 09:20

**MOT test number**

814507651036

**Result**

✓ Passed

**Advice** Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush, both sides (5.3.4 (a) (i))

**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**Advice** Front Tyre worn close to legal limit/worn on edge both tyres (5.2.3 (e))

**MOT #8**

2021-02-09 10:39

**MOT test number**

997354760503

**Result**

✓ Passed

**MOT #7**

2021-02-04 12:38

**MOT test number**

458905092659

**Result**

✗ Failed

**Fail** Offside Front Suspension arm pin or bush excessively worn rear bush split (5.3.4 (a) (i))

**Advice** Offside Front Tyre slightly damaged/cracking or perishing perished and split (5.2.3 (d) (ii))

**Fail** Nearside Front Suspension arm pin or bush excessively worn rear bush split (5.3.4 (a) (i))

**Advice** Nearside Front Tyre slightly damaged/cracking or perishing perished and split 235/65/17 (5.2.3 (d) (ii))

**MOT #6** 2020-02-26 10:53**MOT test number** 167652521599**Result** ✓ Passed**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Tyre worn close to legal limit/worn on edge x2 front tyres (5.2.3 (e))**MOT #5** 2019-02-27 12:14**MOT test number** 533631974331**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #4** 2018-02-08 11:09**MOT test number** 416043048873**Result** ✓ Passed**MOT #3** 2017-01-25 14:25**MOT test number** 754101899196**Result** ✓ Passed**MOT #2** 2017-01-25 11:36**MOT test number** 341137131752**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)



MOT #1	2016-03-02 12:23
MOT test number	353699637135
Result	✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 March 2025

✓  
**MOT**  
**Expires:**  
1 March 2025

<b>Tax status</b>	Valid until 1 March
<b>Days left</b>	306
<b>MOT expiry date</b>	1 March 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	G
<b>Single payment (12 months)</b>	£ 240,00,-
<b>Single six month payment</b>	£ 132,00,-
<b>Total payable by 12 monthly instalments</b>	£ 252,00,-




Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	BK13HVD
Plate since	2019-03-29
Current registration	BK13HVD
Plate since	2019-03-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.


Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2013-03-29
Last registration	2024-02-14
Complete history	<a href="#">See info</a>



Registration #1	2013-03-29	17 mi
Registration #2	2016-03-02	29.131 mi
Registration #3	2017-01-25	36.758 mi
Registration #4	2017-01-25	36.785 mi
Registration #5	2018-02-08	41.335 mi
Registration #6	2019-02-27	45.550 mi
Registration #7	2020-02-26	49.546 mi
Registration #8	2021-02-04	51.467 mi
Registration #9	2022-02-02	55.277 mi
Registration #10	2023-02-02	59.277 mi
Registration #11	2023-02-02	59.277 mi
Registration #12	2023-02-02	59.277 mi
Registration #13	2023-02-02	59.277 mi
Registration #14	2023-02-02	59.277 mi
Registration #15	2024-02-14	59.277 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	95%
Children	84%
Pedestrian	46%
Safety systems	71%
Overall rating	81%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2085 mm
Height	1761 mm
Length	4596 mm
Wheel base	2707 mm
Kerb weight	1836 kg
Max. allowed weight	2505 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	Z22D1 263998K LNQ