



report date: 2024-03-28

General information

Make	FIAT
Model	BRAVO ACTIVE TJET
Colour	Silver
Year of manufacture	2008
Top speed	132 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	150 BHP
Max. torque	206 Nm at 2.250 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.4 mpg
Consumption extra urban	48.7 mpg
Consumption combined	39.8 mpg
CO2 emission	167 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-08-15
Pictures	17
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-01-30
MOT pass rate	68 %
MOT passed	13
Failed MOT tests	6
Total advice items	30
Total items failed	15

MOT #19	2024-01-31 15:10
MOT test number	222962881330
Result	✓ Passed
Next expiry date	2025-01-30
Advice	Offside Rear Outer Child Seat fitted not allowing full inspection of adult belt

MOT #18	2024-01-18 16:11
MOT test number	933360377748
Result	✗ Failed
Fail	Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
Advice	Offside Rear Outer Child Seat fitted not allowing full inspection of adult belt
Fail	Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
Fail	Nearside Track rod end ball joint has excessive play (2.1.3 (b) (i))

MOT #17	2022-08-04 08:59
MOT test number	425316052055
Result	✓ Passed



MOT #16	2022-08-03 14:46
MOT test number	696755771643
Result	✗ Failed
Advice	Offside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))
Fail	Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

MOT #15	2021-08-02 13:09
MOT test number	851112892582
Result	✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Rear exhaust silencer deteriorated

MOT #14	2021-07-31 08:10
MOT test number	577668116027
Result	✗ Failed
Fail	Windscreen washer provides insufficient washer liquid (3.5 (a))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
Fail	Offside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
Fail	Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Fail	Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
Fail	Nearside Rear Valve stem seriously damaged (5.2.3 (j))
Advice	Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Rear exhaust silencer deteriorated
Fail	Nearside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

**MOT #13** 2019-07-05 10:46**MOT test number** 635930478575**Result** ✓ Passed**Advice** Rear Child Seat fitted not allowing full inspection of adult belt**MOT #12** 2019-07-04 09:24**MOT test number** 800961323332**Result** ✗ Failed**Fail** Rear Exhaust system insecure (6.1.2 (a))**Advice** Rear Child Seat fitted not allowing full inspection of adult belt**Fail** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**MOT #11** 2018-02-16 09:48**MOT test number** 300147750429**Result** ✓ Passed**Advice** Front Sub-frame corroded but not seriously weakened (2.4.G.1)**Advice** Parking brake lever has little reserve travel (3.1.6b)**Advice** Rear exhaust box outer skin corroded**Advice** Rear Sub-frame corroded but not seriously weakened (2.4.G.1)

**MOT #10**

2018-02-15 11:54

MOT test number

571595521330

Result**✗ Failed****Fail**

Nearside Front Lower Suspension arm ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)

Advice

Parking brake lever has little reserve travel (3.1.6b)

Advice

Rear exhaust box outer skin corroded

Advice

Front Sub-frame corroded but not seriously weakened (2.4.G.1)

Advice

Rear Sub-frame corroded but not seriously weakened (2.4.G.1)

MOT #9

2017-02-17 11:40

MOT test number

896461563543

Result**✓ Passed****Advice**

Rear exhaust box corroded

Advice

Nearside Outer Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)

MOT #8

2016-02-15 12:35

MOT test number

199554924101

Result**✓ Passed****MOT #7**

2016-02-15 12:35

MOT test number

691404307774

Result**✗ Failed****Pass with rectification**

Windscreen washer provides insufficient washer liquid (8.2.3)

**MOT #6** 2015-02-02 13:45**MOT test number** 777793635031**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #5** 2013-11-22 15:23**MOT test number** 319776223387**Result** ✓ Passed**MOT #4** 2012-12-21 10:42**MOT test number** 397396652312**Result** ✓ Passed**MOT #3** 2012-10-27 09:58**MOT test number** 437621402346**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Offside rear tyre cracking in tread**Notice** Vehicle fitted with engine cover**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Nearside rear tyre cracking in tread**Notice** Vehicle fitted with undertrays**Advice** Exhaust has a minor leak of exhaust gases (7.1.2)**MOT #2** 2011-11-05 09:19**MOT test number** 876839501320**Result** ✓ Passed



MOT #1	2010-11-29 15:16
MOT test number	103803530359
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 May 2025

✓
MOT
Expires:
30 January 2025

Tax status	Valid until 1 May
Days left	368
MOT expiry date	30 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	WV08VOY
Plate since	2019-03-28
Current registration	WV08VOY
Plate since	2019-03-28

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2008-03-31
Last registration	2024-01-31
Complete history	See info



Registration #1	2008-03-31	24 mi
Registration #2	2010-11-29	20.305 mi
Registration #3	2011-11-05	32.501 mi
Registration #4	2012-10-27	44.839 mi
Registration #5	2012-12-21	45.546 mi
Registration #6	2013-11-22	49.732 mi
Registration #7	2015-02-02	61.119 mi
Registration #8	2016-02-15	65.849 mi
Registration #9	2016-02-15	65.849 mi
Registration #10	2017-02-17	69.036 mi
Registration #11	2018-02-15	71.623 mi
Registration #12	2019-05-29	75.277 mi
Registration #13	2019-05-29	75.277 mi
Registration #14	2019-05-29	75.277 mi
Registration #15	2019-05-29	75.277 mi
Registration #16	2019-05-29	75.277 mi
Registration #17	2019-05-29	75.277 mi
Registration #18	2019-05-29	75.277 mi
Registration #19	2019-05-29	75.277 mi
Registration #20	2019-05-29	75.277 mi
Registration #21	2019-05-29	75.277 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1792 mm
Height	1498 mm
Length	4336 mm
Wheel base	2600 mm
Kerb weight	1275 kg
Max. allowed weight	1785 kg

Additional information

Fuel tank capacity	58 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	1194755