





report date: 2024-03-28

## General information

Make	HYUNDAI
Model	TUCSON GDI SE NAV
Colour	Grey
Year of manufacture	2019
Top speed	113 mph
Gearbox	6 speed Manual

# Engine & fuel consumption

Power	130 BHP
Max. torque	161 Nm at 4.850 rpm
Engine capacity	1.591 cc
Cylinders	4
Fuel type	Petrol
Consumption city	34.4 mpg
Consumption extra urban	44.1 mpg
Consumption combined	34.9 mpg
CO2 emission	162 g/km
CO2 label	G



CarCheck.co.uk page 1/11



EA19WZR report date: 2024-03-28

# Internet history

### Entry 1

Date 2022-05-06

Pictures 14

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-28

## MOT history

MOT expiry date	2025-03-08
MOT pass rate	60 %
MOT passed	3
Failed MOT tests	2
Total advice items	12
Total items failed	4

MOT #5	2024-03-01 14:10
MOT test number	575658256814
Result	<b>✓</b> Passed
Next expiry date	2025-03-08

MOT #4	2024-02-28 15:55
MOT test number	696975615891
Result	<b>X</b> Failed
Fail Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	

MOT #3	2023-03-03 15:38
MOT test number	469697924901
Result	✓ Passed
Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT #2 2022-03-09 17:14 **MOT test number** 332078900040 Result ✓ Passed **Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Advice Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt Minor Windscreen damaged but not adversely affecting driver's view Chipped (3.2 (a) (i)) **Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #1	2022-03-09 12:47
MOT test number	272434284758
Result	<b>×</b> Failed
Fail Nearside Headlamp aim too high (4.1.2 (a))	
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Minor Windscreen damaged but not adversely affecting driver's view Chipped (3.2 (a)	(i))
Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt	
Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Fail Offside Headlamp aim too high (4.1.2 (a))	
Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice Offside Rear Child Seat fitted not allowing full inspection of adult belt	

CarCheck.co.uk page 4/11



report date: 2024-03-28

## Tax & MOT check



Tax status	Valid until 1 May
Days left	366
MOT expiry date	8 March 2025
Full MOT history	See MOT history

### Tax calculation

Vehicle class	48
Band	I
First licence fee (12 months)	£ 645,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



report date: 2024-03-28

### Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

### Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

More info >

Owner history	
For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYU have? Check it in the premium report and see all owner registrations. Download the full report <a href="https://example.com/here">here</a> .	JNDAI
*******	
***************************************	
************	
HARMAN AND AND AND AND AND AND AND AND AND A	
**************************************	
Plate changes	>
See in this check if this HYUNDAI had different number plates.	
Number of plates	
SIP UK	
Plate since	
AND THE REPORT OF THE PROPERTY	
Plate since	

CarCheck.co.uk page 8/11



report date: 2024-03-28

### Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

**Contact info** 

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

# Mileage check

Odometer	In miles
Mileage registrations	7
First mileage registration	2019-03-08
Last registration	2024-03-01
Complete history	See info



Registration #1	2019-03-08	18 mi
Registration #2	2022-03-09	28.013 mi
Registration #3	2022-03-09	28.014 mi
Registration #4		11.777 es
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-28

## Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
50567	
50569	

# Safety ratings

NCAP rating	****
Adult	86%
Children	85%
Pedestrian	71%
Safety systems	71%
Overall rating	80%
Video	see crash video



# Dimensions & weight

Width	1850 mm
Height	1650 mm
Length	4475 mm
Wheel base	2670 mm
Kerb weight	1414 kg
Max. allowed weight	2030 kg

## Additional information

Fuel tank capacity	62 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11/1

Number of axles 2

Engine number G4FDKZ811474