





report date: 2024-03-28

General information

Make	FORD
Model	FIESTA STYLE PLUS TDCI
Colour	Blue
Year of manufacture	2010
Top speed	101 mph
0 - 60 mph	14.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	67 BHP
Max. torque	160 Nm at 1.750 rpm
Engine capacity	1.399 сс
Cylinders	4
Fuel type	Diesel
Consumption city	53.3 mpg
Consumption extra urban	80.7 mpg
Consumption combined	67.3 mpg
CO2 emission	110 g/km
CO2 label	В



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history

Entry 1

Date	2021-01-30	
Pictures	1	
Listing price	<u>View report</u>	



source: autoonline.co.uk

CarCheck.co.uk page 2/12



CP59WHL report date: 2024-03-28

MOT history

MOT expiry date	2024-05-25
MOT pass rate	91 %
MOT passed	10
Failed MOT tests	1
Total advice items	10
Total items failed	2

MOT #11	2019-09-02 09:40
MOT test number	551310962057
Result	✓ Passed
Next expiry date	2020-09-01
Advice Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn not exessive (5.1.2 (b) (i))	both axle bushes worn but

MOT #10		2018-10-11 08:59
MOT test	number	236987624025
Result		✓ Passed
Advice	Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))	
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))	
Advice	Offside Rear Direction indicator slightly discoloured (4.4.3 (a))	
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))	
Advice	Exhaust system in poor condition	

MOT #9	2017-10-13 09:05
MOT test number	381788494301
Result	✓ Passed
Advice Both front tyres wearing on edges	

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #8	2016-10-13 11:33
MOT test number	348524732097
Result	✓ Passed
Advice Rear silencer deteriorated.	

MOT #7	2015-10-15 14:42
MOT test number	884550586265
Result	✓ Passed
MOT #6	2015-10-14 11:54
MOT test number	879901856881
Result	× Failed
Fail Nearside Headlamp not working on dipped beam (1.7.5a)	
Fail Nearside Front Braking system leaking adjacent to pipe clip (3.6.A.1)	

MOT #5	2015-05-11 14:37
MOT test number	326581235111
Result	✓ Passed
Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	

MOT #4	2014-05-06 10:28
MOT test number	336116724124
Result	✓ Passed
Notice Child seat fitted not allowing full inspection of adult belt	

MOT #3	2013-04-11 12:57
MOT test number	615161403162
Result	✓ Passed

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #2	2013-01-08 15:15
MOT test number	128418203010
Result	✓ Passed
MOT #1	2012-08-18 08:26
MOT test number	616851532261
Result	✓ Passed

CarCheck.co.uk page 5/12



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 October
Days left	155
MOT expiry date	25 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

Owner history

For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report	
THE STATE OF THE S	

	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	
Current registration	NK NK
Plate since	
Current registration	NK NE
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >


CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2010-02-12
Last registration	2019-09-02
Complete history	See info



Registration #1	2010-02-12	29 mi
Registration #2	2012-08-18	30.888 mi
Registration #3	2013-01-08	31.037 mi
Registration #4	2013-04-11	34.379 mi
Registration #5	2014-05-06	47.774 mi
Registration #6	2015-05-11	56.601 mi
Registration #7	2015-10-14	59.655 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 mi
Registration #12		11.777 es
Registration #13		10.777 es

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1973 mm
Height	1481 mm
Length	3950 mm
Kerb weight	1141 kg
Max. allowed weight	1535 kg

Additional information

Fuel tank capacity	40 I
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	5
Number of axles CarCheck.co.uk	2 page 12/12

Engine number

9R21853