



HYUNDAI




report date: 2024-03-28

General information

Make	HYUNDAI
Model	IX35 CRDI SE
Colour	Black
Year of manufacture	2014
Top speed	108 mph
0 - 60 mph	12.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	114 BHP
Max. torque	260 Nm at 1.250 rpm
Engine capacity	1.685 cc
Cylinders	4
Fuel type	Diesel
Consumption city	47.1 mpg
Consumption extra urban	58.9 mpg
Consumption combined	54.3 mpg
CO2 emission	139 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-01-31
Pictures	1
Listing price	View report



source: autoonline.co.uk



MOT history

MOT expiry date	2024-07-30
MOT pass rate	64 %
MOT passed	7
Failed MOT tests	4
Total advice items	19
Total items failed	10

MOT #11	2023-07-31 09:16
MOT test number	442647337143
Result	✓ Passed
Next expiry date	2024-07-30
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt
Advice	Offside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #10	2022-07-27 16:33
MOT test number	747088511676
Result	✓ Passed

**MOT #9**

2022-07-26 10:29

MOT test number

696663730084

Result**✗ Failed****Fail**

Nearside Parking brake inoperative on one side (1.4.1 (a))

Advice

Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Offside Rear Nail in tyre

Fail

Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))

Fail

Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Fail

Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))

Advice

Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #8

2021-09-17 14:10

MOT test number

746224658220

Result**✓ Passed****Advice**

Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice

Items removed from driver's view prior to test

Advice

Nearside Front Tyre worn close to legal limit/worn on edge 1.8mm 225 60 17 (5.2.3 (e))

Advice

Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice

Child Seat fitted not allowing full inspection of adult belt

**MOT #7** 2021-09-14 09:46**MOT test number** 860513849792**Result** ✗ Failed**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Advice** Items removed from driver's view prior to test**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Offside Front Position lamp not working low beam (4.2.1 (a) (ii))**Advice** Child Seat fitted not allowing full inspection of adult belt**Advice** Nearside Front Tyre worn close to legal limit/worn on edge 1.8mm 225 60 17 (5.2.3 (e))**MOT #6** 2020-09-14 13:13**MOT test number** 919963471236**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge & cracking (5.2.3 (e))**Advice** Nearside Rear Nail in tyre**MOT #5** 2020-09-14 13:13**MOT test number** 445666784183**Result** ✗ Failed**Pass with rectification** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Nearside Rear Nail in tyre**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge & cracking (5.2.3 (e))**MOT #4** 2019-09-18 13:01**MOT test number** 811395891894**Result** ✓ Passed



MOT #3	2019-09-16 14:57
MOT test number	296108660682
Result	✗ Failed
Fail	Offside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
Fail	Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Fail	Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

MOT #2	2018-09-14 09:54
MOT test number	500846995286
Result	✓ Passed

MOT #1	2017-09-16 15:25
MOT test number	423127311080
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
30 July 2024

Tax status	Valid until 1 July
Days left	64
MOT expiry date	30 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2014-09-16
Last registration	2023-07-31
Complete history	See info



Registration #1	2014-09-16	12 mi
Registration #2	2017-09-16	42.117 mi
Registration #3	2018-09-14	49.952 mi
Registration #4	2019-09-16	58.906 mi
Registration #5	2019-09-18	58.105 mi
Registration #6	2020-09-14	67.550 mi
Registration #7	2020-09-14	67.550 mi
Registration #8	2020-09-14	67.550 mi
Registration #9	2020-09-14	67.550 mi
Registration #10	2020-09-14	67.550 mi
Registration #11	2020-09-14	67.550 mi
Registration #12	2020-09-14	67.550 mi
Registration #13	2020-09-14	67.550 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	88%
Pedestrian	54%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	1820 mm
Height	1665 mm
Length	4410 mm
Wheel base	2640 mm
Kerb weight	1537 kg
Max. allowed weight	1940 kg

Additional information

Fuel tank capacity	58 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	D4FDEZ258681