





### General information

AWD
tic

# Engine & fuel consumption

Power	202 BHP
Max. torque	420 Nm at 1.500 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Diesel
Consumption city	29.7 mpg
Consumption extra urban	48.7 mpg
Consumption combined	39.2 mpg
CO2 emission	189 g/km
CO2 label	J





Internet history	
Entry 1	
Date	2021-09-03
Pictures	1
Listing price	View report



source: autotrader.co.uk



## MOT history

MOT expiry date	2024-10-19
MOT pass rate	92 %
MOT passed	11
Failed MOT tests	1
Total advice items	11
Total items failed	1

MOT #12	2023-10-20 10:38
MOT test number	369675911557
Result	✓ Passed
Next expiry date	2024-10-19

MOT #11		2022-10-20 08:54
MOT test i	number	824274920590
Result		✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge Wearing on in	nner edge. (5.2.3 (e))

MOT #10	2021-09-03 12:47
MOT test number	447101438282
Result	✓ Passed

MOT #9		2020-08-25 11:33
MOT test	number	168156783629
Result		✓ Passed
Advice	Offside Rear Direction indicator slightly discoloured (4.4.3 (a))	
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))	
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	





MOT #8	2019-05-30 09:54
MOT test number	954294419234
Result	✓ Passed
MOT #7	2019-05-30 09:53
MOT test number	625543790579
Result	🗙 Failed

Pass with rectification Offside Front Outline marker lamp not working (4.2.1 (a))

MOT #6		2018-05-29 10:37
MOT test	number	288665535871
Result		✓ Passed
<b>Advice</b> (a) (i))	Nearside Rear Suspension arm pin or bush worn but not resulting in ex	xcessive movement (5.3.4
Advice (i))	Offside Rear Suspension arm pin or bush worn but not resulting in exc	essive movement (5.3.4 (a)

MOT #5	2017-06-05 11:16
MOT test number	725424489728
Result	✓ Passed
MOT #4	2016-06-06 09:25
MOT test number	692975040310
Result	Passed
MOT #3	2015-05-28 10:58
MOT test number	848328245141
Result	✓ Passed
Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)	





MOT #2	2014-06-03 13:44
MOT test number	929444954114
Result	✓ Passed
NoticeO/s/f tyre wearing on inner edgeNoticeFront number plate cracked	
MOT #1	2013-06-07 12:03

MOT test number	425588753126
Result	✓ Passed



Tax & MOT check

<b>Taxed</b> <b>Tax due:</b> 1 November 2024	<b>MOT</b> Expires: 19 October 2024
Tax status	Valid until 1 November
Days left	185
MOT expiry date	19 October 2024
Full MOT history	See MOT history

# Tax calculation

Vehicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-





### Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FER I
Category	 A PLANE
Туре	
Damage 2	AMPLE
Damage 2	E Stand
Date	*
Category	 ante.
Туре	

#### Extra VOLVO salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info  $\rightarrow$ 





### Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.00.000
Auction value	4 10.000
Average private trade value	4 10.200

More info  $\rightarrow$ 





# Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

and a second sec	
***********	
*******	
*******	
***********	
********	
	More info >
Plate changes	
See in this check if this VOLVO had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	
	More info >





#### Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info  $\rightarrow$ 





# Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2010-06-09
Last registration	2023-10-20
Complete history	See info



Registration #1	2010-06-09	27 mi
Registration #2	2013-06-07	26.142 mi
Registration #3	2014-06-03	32.500 mi
Registration #4	2015-05-28	37.080 mi
Registration #5	2016-06-06	44.469 mi
Registration #6	2017-06-05	49.154 mi
Registration #7	2018-05-29	53.993 mi
Registration #8		11.777 mil
Registration #8 Registration #9		11.777 es
-		01,000 est 01,000 est 01,000 est
Registration #9		01,000 est 01,000 est 01,000 est 01,000 est
Registration #9 Registration #10		01,000 est 01,000 est 01,000 est 01,000 est 01,000 est
Registration #9 Registration #10 Registration #11		01,000 est 01,000 est 01,000 est 01,000 est 01,000 est 01,000 est

More info >





### Car features

S0225	Air conditioning
S0295	
S0482	
\$0501	
S0566	
\$0567	
S0569	

# Dimensions & weight

Width	1861 mm
Height	1604 mm
Length	4838 mm
Wheel base	2815 mm
Kerb weight	1895 kg
Max. allowed weight	2400 kg

## Additional information

Fuel tank capacity	70 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	848865