




report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	CADDY C20 LIFE TDI
Colour	Purple
Year of manufacture	2016
Top speed	106 mph
0 - 60 mph	12.1 seconds
Gearbox	6 speed Semi Auto

Engine & fuel consumption

Power	101 BHP
Max. torque	250 Nm at 1.300 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	44.8 mpg
Consumption extra urban	62.8 mpg
Consumption combined	54.3 mpg
CO2 emission	135 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-11-19
Pictures	0
Listing price	View report

source: heycar.co.uk



MOT history

MOT expiry date	2024-11-05
MOT pass rate	71 %
MOT passed	5
Failed MOT tests	2
Total advice items	11
Total items failed	3

MOT #7	2023-11-06 09:48
MOT test number	828051039710
Result	✓ Passed
Next expiry date	2024-11-05
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #6	2022-10-21 10:23
MOT test number	755567119316
Result	✓ Passed

MOT #5	2021-10-13 14:28
MOT test number	511437034783
Result	✓ Passed
Advice	Offside Front Drivers seat play in mechanism.

MOT #4	2020-10-21 12:34
MOT test number	486179810668
Result	✓ Passed

**MOT #3** 2020-10-09 13:22**MOT test number** 784215357653**Result** ✗ Failed**Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))**Fail** Windscreen washer not working (3.5 (a))**MOT #2** 2019-10-24 12:58**MOT test number** 118709055136**Result** ✓ Passed**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Minor** Central Rear Stop lamp(s) with a multiple light source up to 1/2 not functioning (4.3.1 (a) (i))**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #1** 2019-10-24 11:00**MOT test number** 849840165656**Result** ✗ Failed**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Minor** Offside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))**Fail** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Minor** Central Rear Stop lamp(s) with a multiple light source up to 1/2 not functioning (4.3.1 (a) (i))



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
5 November 2024

Tax status	Valid until 1 June
Days left	32
MOT expiry date	5 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	RJ66HKH
Plate since	2019-03-29
Current registration	RJ66HKH
Plate since	2019-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2016-10-26
Last registration	2023-11-06
Complete history	See info



Registration #1	2016-10-26	26 mi
Registration #2	2019-10-24	36.239 mi
Registration #3	2019-10-24	36.239 mi
Registration #4	2020-10-09	44.891 mi
Registration #5	2020-10-21	44.894 mi
Registration #6	2023-11-06	55.277 mi
Registration #7	2023-11-06	55.277 mi
Registration #8	2023-11-06	55.277 mi
Registration #9	2023-11-06	55.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	84%
Children	78%
Pedestrian	58%
Safety systems	68%
Overall rating	74%
Video	see crash video



Dimensions & weight

Width	1793 mm
Height	1831 mm
Length	4878 mm
Kerb weight	577 kg
Max. allowed weight	2308 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles

2

Engine number

DFSB088166