



TOYOTA

HJ06YKL


report date: 2024-03-29

General information

Make	TOYOTA
Model	COROLLA VVTI T SPIRIT
Colour	Grey
Year of manufacture	2006
Gearbox	5 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	150 Nm at 3.800 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	31.4 mpg
Consumption extra urban	47.8 mpg
Consumption combined	47.8 mpg
CO2 emission	168 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-10-11
Pictures	0
Listing price	View report

source: cargurus.co.uk



MOT history

MOT expiry date	2023-03-22
MOT pass rate	88 %
MOT passed	14
Failed MOT tests	2
Total advice items	60
Total items failed	1

MOT #16	2022-03-12 18:43
---------	------------------

MOT test number	398043936249
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2023-03-22
------------------	------------

Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Exhaust has a minor leak of exhaust gases (6.1.2 (a))
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened Both sides (1.1.14 (a) (ii))
Advice	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
Advice	Front Suspension arm pin or bush worn but not resulting in excessive movement Both sides (5.3.4 (a) (i))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Rear Brake pad(s) wearing thin Both (1.1.13 (a) (ii))
Advice	Front Suspension arm pin or bush worn but not resulting in excessive movement Both sides (5.3.4 (a) (i))
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))
Minor	Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**MOT #15**

2021-03-04 15:04

MOT test number

769123314800

Result

✓ Passed

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement radial bush (5.3.4 (a) (i))

Advice Nearside Rear Brake hose slightly deteriorated perished and cracking slightly (1.1.12 (b) (ii))

Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement radial bush (5.3.4 (a) (i))

Advice Offside Rear Brake hose slightly deteriorated perished and cracking slightly (1.1.12 (b) (ii))

Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

MOT #14

2021-03-04 10:02

MOT test number

264942175026

Result

✗ Failed

Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))

MAJOR Offside Front Headlamp aim projected beam image is obviously incorrect product on lense (4.1.2 (c))

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement radial bush (5.3.4 (a) (i))

Advice Offside Rear Brake hose slightly deteriorated perished and cracking slightly (1.1.12 (b) (ii))

Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement radial bush (5.3.4 (a) (i))

Advice Nearside Rear Brake hose slightly deteriorated perished and cracking slightly (1.1.12 (b) (ii))

**MOT #13**

2020-03-10 13:20

MOT test number

262971907676

Result

✓ Passed

- Advice** Nearside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))
- Advice** Wipers starting to smear
- Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Offside Rear lamp unit cracked but operation unaffected
- Advice** Offside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))
- Advice** Offside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

MOT #12

2019-02-28 12:43

MOT test number

951773912295

Result

✓ Passed

- Advice** Offside Rear lamp unit cracked but operation unaffected
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Brake hose slightly deteriorated front and rear (all) (1.1.12 (b) (ii))
- Advice** Offside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #11**

2018-02-28 11:27

MOT test number

500295615652

Result

✓ Passed

- Advice** Nearside Front Brake hose slightly deteriorated (3.6.B.4d)
- Advice** Nearside Rear Brake hose slightly deteriorated (3.6.B.4d)
- Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)
- Advice** Offside Rear lamp unit cracked
- Advice** Offside Front Brake hose slightly deteriorated (3.6.B.4d)
- Advice** Offside Rear Brake hose slightly deteriorated (3.6.B.4d)
- Advice** Offside Headlamp has a product on the lens but not seriously reducing light output (1.7.5a)

MOT #10

2017-03-06 11:29

MOT test number

399298696209

Result

✓ Passed

- Advice** Offside Headlamp has a product on the lens but not seriously reducing light output (1.7.5a)
- Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)
- Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)

MOT #9

2016-03-23 16:10

MOT test number

382538526990

Result

✓ Passed

- Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)

MOT #8

2015-03-10 16:42

MOT test number

796419665052

Result

✓ Passed

**MOT #7** 2014-03-05 11:35**MOT test number** 125444964447**Result** ✓ Passed**Notice** N/s/f tyre side wall cut not to cords**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #6** 2013-03-05 17:02**MOT test number** 139824763027**Result** ✓ Passed**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2012-02-23 12:10**MOT test number** 995594252002**Result** ✓ Passed**MOT #4** 2011-03-11 10:15**MOT test number** 716190371050**Result** ✓ Passed**Notice** Deep cut in nsf tyre,not quite down to cords**MOT #3** 2011-03-11 10:15**MOT test number** 859730171036**Result** ✗ Failed**Pass with rectification** Nearside Rear Stop lamp not working (1.2.1b)**Notice** Deep cut in nsf tyre,not quite down to cords



MOT #2	2010-03-02 17:05
MOT test number	714421360013
Result	✓ Passed
Advice	Front Brake pad(s) wearing thin (3.5.1g)
Notice	Front wiper blades starting to smear
Notice	Offside rear tyre "stepping" on inner edge
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Notice	Nearside front tyre has deep cut through tread, no cords evident though

MOT #1	2009-03-18 14:19
MOT test number	750277279000
Result	✓ Passed
Notice	One washer jet on n/s jet inop



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2006-03-22
Last registration	2022-03-12
Complete history	See info



Registration #1	2006-03-22	21 mi
Registration #2	2009-03-18	31.716 mi
Registration #3	2010-03-02	39.722 mi
Registration #4	2011-03-11	47.199 mi
Registration #5	2012-02-23	54.541 mi
Registration #6	2013-03-05	62.197 mi
Registration #7	2014-03-05	67.998 mi
Registration #8	2015-03-10	73.784 mi
Registration #9	2016-03-23	75.042 mi
Registration #10	2016-03-23	75.042 mi
Registration #11	2016-03-23	75.042 mi
Registration #12	2016-03-23	75.042 mi
Registration #13	2016-03-23	75.042 mi
Registration #14	2016-03-23	75.042 mi
Registration #15	2016-03-23	75.042 mi
Registration #16	2016-03-23	75.042 mi
Registration #17	2016-03-23	75.042 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1710 mm
Height	1475 mm
Length	4180 mm
Wheel base	2600 mm
Kerb weight	1220 kg
Max. allowed weight	1655 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	3ZZU734849