





report date: 2024-03-28

General information

Make	JAGUAR
Model	XE PORTFOLIO
Colour	Black
Year of manufacture	2017
Top speed	140 mph
0 - 60 mph	7.4 seconds
Gearbox	8 speed automatic

Engine & fuel consumption

Power	177 BHP
Max. torque	430 Nm at 1.750 rpm
Engine capacity	1.999 сс
Cylinders	4
Fuel type	Diesel
Consumption city	55.4 mpg
Consumption extra urban	76.4 mpg
Consumption combined	67.3 mpg
CO2 emission	111 g/km
CO2 label	С



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history


Entry 1

Date 2021-01-31

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

MOT history

MOT expiry date	2024-10-31
MOT pass rate	83 %
MOT passed	5
Failed MOT tests	1
Total advice items	25
Total items failed	0

MOT #6	2023-11-0	1 16:37
MOT test	number 816492	677653
Result	✓	Passed
Next expi	iry date 202	4-10-31
Advice (d) (ii))	Offside Front Inner Tyre slightly damaged/cracking or perishing slight damage to sidewall (5	.2.3
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))	
Advice (d) (ii))		
Advice (d) (ii))	Offside Rear Outer Tyre slightly damaged/cracking or perishing slight damage to sidewall (5	.2.3
Advice	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))	

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #5 2023-04-13 12:26

MOT test number 958647672093

MOT test	930047072033
Result	✓ Passed
Advice	Offside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
Advice	Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
Advice	Offside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
Advice	Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

CarCheck.co.uk page 4/12



Result

MOT test number

OE67LUZ

report date: 2024-03-28

× Failed

185817422442

MOT #4 2023-04-12 08:40

MOT test number 816860359008

Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Offside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Nearside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MAJOR Brake pedal anti-slip provision missing (1.1.2 (c))

Advice Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Offside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

MOT #3 2022-04-14 11:01

Result \rightarrow Passed

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #2 2021-04-30 13:06

MOT test number 919632458016

Result
✓ Passed

MOT #1 2020-09-18 16:19

MOT test number 864118585541

Result ✓ Passed

CarCheck.co.uk page 5/12



OE67LUZ report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 January
Days left	248
MOT expiry date	31 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
First licence fee (12 months)	£ 210,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 255,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

More info >

Owner history	
For how long did the current and previous owner(s) have this JAGUAR? How many owners have? Check it in the premium report and see all owner registrations. Download the full r	
2000000	

	More info >
Plate changes	
See in this check if this JAGUAR had different number plates.	
Number of plates	
Current registration	OK SIE
Plate since	
Current registration	NK SIK
Minda sinca	

CarCheck.co.uk page 9/12



OE67LUZ report date: 2024-03-28

Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled.

If not, and you buy this JAGUAR then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this JAGUAR is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2017-12-07
Last registration	2023-11-01
Complete history	See info



Registration #1	2017-12-07	28 mi
Registration #2	2020-09-18	14.844 mi
Registration #3		11.777 es
Registration #4	2021-04-30	14.855 mi
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es

More info >

CarCheck.co.uk page 11/12



OE67LUZ report date: 2024-03-28

Safety ratings

NCAP rating	****
Adult	92%
Children	82%
Pedestrian	81%
Safety systems	82%
Overall rating	86%
Video	see crash video



Dimensions & weight

Width	2075 mm
Height	1416 mm
Length	4672 mm
Wheel base	2835 mm
Kerb weight	1565 kg
Max. allowed weight	2135 kg

Additional information

Fuel tank capacity	56 I
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	170210W0609204DTD

CarCheck.co.uk page 12/12