



HYUNDAI



report date: 2024-03-28

General information

Make	HYUNDAI
Model	SANTA FE CRDI PREMIUM
Colour	Blue
Year of manufacture	2010
Top speed	118 mph
0 - 60 mph	9.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	194 BHP
Max. torque	422 Nm at 1.900 rpm
Engine capacity	2.199 cc
Cylinders	4
Fuel type	Diesel
Consumption city	32.1 mpg
Consumption extra urban	50.4 mpg
Consumption combined	41.5 mpg
CO2 emission	176 g/km
CO2 label	I





MOT history

MOT expiry date	2022-01-10
MOT pass rate	73 %
MOT passed	8
Failed MOT tests	3
Total advice items	23
Total items failed	16

MOT #11	2021-01-05 14:06
MOT test number	503747337939
Result	✓ Passed
Next expiry date	2022-01-10
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #10**

2021-01-04 09:53

**MOT test number**

322525234695

**Result****✗ Failed**

- Fail** Nearside Front Suspension arm ball joint likely to become detached (5.3.4 (a) (ii))
- Fail** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))
- Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Fail** Headlamp aim too low (4.1.2 (a))
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Fail** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))
- Fail** Nearside Rear Service brake excessively binding (1.2.1 (f))
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm 235/60/18 (5.2.3 (e))
- Fail** Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

**MOT #9**

2020-01-06 17:22

**MOT test number**

451215277361

**Result****✓ Passed**

- Advice** Tyre slightly damaged/cracking or perishing both rear tyres heavily cracked and perished 235/60/18 (5.2.3 (d) (ii))
- Advice** Oil leak, but not excessive slight engine oil leak (8.4.1 (a) (i))
- Advice** Both rear coil springs have surface corrosion
- Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))

**MOT #8**

2020-01-06 10:49

**MOT test number**

294621433862

**Result****✗ Failed**

**Fail** Offside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

**Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))

**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))

**Advice** Anti freeze below minimum

**Fail** Parking brake lever has excessive movement indicating incorrect adjustment no reserve travel (1.1.6 (c))

**Pass with rectification** Offside Front Headlamp aim too high (4.1.2 (a))

**Fail** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

**Advice** Tyre slightly damaged/cracking or perishing both rear tyres heavily cracked and perished 235/60/18 (5.2.3 (d) (ii))

**Advice** Oil leak, but not excessive slight engine oil leak (8.4.1 (a) (i))

**Advice** Both rear coil springs have surface corrosion

**Pass with rectification** Nearside Front Headlamp aim too high (4.1.2 (a))

**MOT #7**

2019-01-07 16:23

**MOT test number**

551456792002

**Result****✓ Passed**

**Advice** Offside Front Outer cv boot damp with grease

**Advice** Both rear brake pipes have surface corrosion

**MOT #6** 2019-01-07 11:30**MOT test number** 120120877923**Result** ✗ Failed**Advice** Offside Front Outer cv boot damp with grease**Fail** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Offside Rear wheel has grinding noise from brakes when rotated**MOT #5** 2018-01-09 17:21**MOT test number** 391527711512**Result** ✓ Passed**Advice** Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**Advice** Offside Front Tyre worn close to the legal limit 3mm (4.1.E.1)**Advice** Offside Front Outer Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)**Advice** Nearside Front Tyre worn close to the legal limit 3mm (4.1.E.1)**MOT #4** 2017-01-06 13:57**MOT test number** 316645013355**Result** ✓ Passed**MOT #3** 2016-01-11 11:38**MOT test number** 664338829515**Result** ✓ Passed**MOT #2** 2014-12-05 14:34**MOT test number** 697729334389**Result** ✓ Passed**Advice** Parking brake lever has little reserve travel (3.1.6b)



MOT #1	2013-12-12 12:03
MOT test number	585036143344
Result	✓ Passed



Tax & MOT check

✕  
Untaxed

Tax expired:  
20 January 2021

✕  
MOT

Expired:  
10 January 2022

Tax status	Expired at 20 January 2021
Days left	1194 days too late
MOT expiry date	10 January 2022
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	49
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.


Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2010-12-13
Last registration	2021-01-05
Complete history	<a href="#">See info</a>



Registration #1	2010-12-13	25 mi
Registration #2	2013-12-12	99.572 mi
Registration #3	2014-12-05	129.874 mi
Registration #4	2016-01-11	152.476 mi
Registration #5	2017-01-06	165.279 mi
Registration #6	2018-01-09	174.516 mi
Registration #7	2019-01-09	183.753 mi
Registration #8	2020-01-09	193.000 mi
Registration #9	2021-01-05	202.247 mi
Registration #10	2022-01-05	211.494 mi
Registration #11	2023-01-05	220.741 mi
Registration #12	2024-01-05	229.988 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1890 mm
Height	1760 mm
Length	4660 mm
Wheel base	2700 mm
Kerb weight	1920 kg
Max. allowed weight	2570 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Engine number	D4HBAU323268
---------------	--------------