



report date: 2024-03-29

General information

Make	VAUXHALL
Model	VECTRA VXR
Colour	Blue
Year of manufacture	2009
Top speed	155 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	230 BHP
Max. torque	329 Nm at 1.800 rpm
Engine capacity	2.792 cc
Cylinders	6
Fuel type	Petrol
Consumption city	18.2 mpg
Consumption extra urban	38.2 mpg
Consumption combined	27.2 mpg
CO2 emission	250 g/km
CO2 label	L






Internet history

Entry 1

Date	2021-10-31
Pictures	10
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-10-31
MOT pass rate	81 %
MOT passed	13
Failed MOT tests	3
Total advice items	16
Total items failed	4

MOT #16	2023-10-07 07:46
MOT test number	870571324591
Result	✓ Passed
Next expiry date	2024-10-31
Advice	Offside Front Shock absorbers has light misting of oil (5.3.2 (b))
Advice	Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #15	2022-10-15 07:37
MOT test number	902323002043
Result	✓ Passed

MOT #14	2021-11-01 13:57
MOT test number	719522368380
Result	✓ Passed

MOT #13	2020-09-07 13:29
MOT test number	933680877863
Result	✓ Passed

**MOT #12** 2019-08-30 13:53**MOT test number** 246172092225**Result** ✓ Passed**Advice** Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))**Advice** Engine cover fitted obscuring components on the engine bay**Advice** Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))**MOT #11** 2019-08-23 14:41**MOT test number** 467528678447**Result** ✗ Failed**Fail** Offside Front Body component damaged and likely to cause injury door mirror casing (6.2.1 (a) (i))**Advice** Engine cover fitted obscuring components on the engine bay**Advice** Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))**Fail** Offside Front Obligatory mirror seriously damaged, affecting the rear view (3.3 (b) (ii))**Advice** Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))**MOT #10** 2018-09-06 13:47**MOT test number** 480487904086**Result** ✓ Passed**MOT #9** 2017-09-11 15:29**MOT test number** 788258997834**Result** ✓ Passed**MOT #8** 2017-09-11 15:29**MOT test number** 504142393678**Result** ✗ Failed**Pass with rectification** Registration plate lamp not working (1.1.C.1d)

**MOT #7** 2016-08-26 12:14**MOT test number** 754894764259**Result** ✓ Passed

- Advice** Slight wear power steering rack
- Advice** Offside Front coil spring corroded (2.4.C.1b)
- Advice** N/s/r tyre wearing inner edge
- Advice** Nearside Front Anti-roll bar linkage ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)
- Advice** O/s/f tyre has a screw in it

MOT #6 2015-07-15 10:24**MOT test number** 239276995147**Result** ✓ Passed**MOT #5** 2014-10-18 09:01**MOT test number** 478691794243**Result** ✓ Passed**MOT #4** 2013-10-28 16:39**MOT test number** 259361703356**Result** ✓ Passed**MOT #3** 2013-10-28 16:39**MOT test number** 899571703386**Result** ✗ Failed

- Pass with rectification** Registration plate lamp not working (1.1.C.1d)

MOT #2 2013-02-25 10:01**MOT test number** 147206953010**Result** ✓ Passed



MOT #1	2012-02-24 15:07
MOT test number	468455152048
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
31 October 2024

Tax status		Valid until 1 November
Days left		186
MOT expiry date		31 October 2024
Full MOT history		See MOT history

Tax calculation

Vehicle class	48
Band	L
Single payment (12 months)	£ 675,00,-
Single six month payment	£ 371,25,-
Total payable by 12 monthly instalments	£ 708,75,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 SG09MPV
Plate since	2019-09-29
Current registration	 SG09MPV
Plate since	2019-09-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2009-03-01
Last registration	2023-10-07
Complete history	See info



Registration #1	2009-03-01	17 mi
Registration #2	2012-02-24	21.058 mi
Registration #3	2013-02-25	32.128 mi
Registration #4	2013-10-28	38.565 mi
Registration #5	2014-10-18	54.298 mi
Registration #6	2015-07-15	64.683 mi
Registration #7	2016-08-26	82.898 mi
Registration #8	2017-09-11	96.135 mi
Registration #9	2017-09-11	96.135 mi
Registration #10	2019-05-29	95.377 mi
Registration #11	2019-05-29	95.377 mi
Registration #12	2019-05-29	95.377 mi
Registration #13	2019-05-29	95.377 mi
Registration #14	2019-05-29	95.377 mi
Registration #15	2019-05-29	95.377 mi
Registration #16	2019-05-29	95.377 mi
Registration #17	2019-05-29	95.377 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	2036 mm
Height	1460 mm
Length	4596 mm
Max. allowed weight	2055 kg

Additional information

Number of seats	5
Number of axles	2
Engine number	HN040300