



report date: 2024-03-29

General information

Make	MAZDA
Model	5 TS2
Colour	Blue
Year of manufacture	2007
Top speed	113 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	114 BHP
Max. torque	165 Nm at 4.000 rpm
Engine capacity	1.798 cc
Cylinders	4
Fuel type	Petrol
Consumption city	26.4 mpg
Consumption extra urban	44.8 mpg
Consumption combined	35.8 mpg
CO2 emission	190 g/km
CO2 label	J







Internet history

Entry 1

Date	2021-07-03
Pictures	22
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-07-06
MOT pass rate	74 %
MOT passed	14
Failed MOT tests	5
Total advice items	35
Total items failed	8

MOT #19	2023-07-07 10:30
MOT test number	919731541475
Result	✓ Passed
Next expiry date	2024-07-06
Minor	Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

MOT #18	2023-07-05 12:08
MOT test number	963152643740
Result	✗ Failed
Fail	Nearside Front Inner Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
Fail	Front Windscreen washer not working (3.5 (a))
Fail	Nearside Obligatory mirror seriously damaged, affecting the rear view (3.3 (b) (ii))
Fail	Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))
Minor	Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

**MOT #17** 2022-07-05 11:07**MOT test number** 912677118327**Result** ✓ Passed**Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #16** 2021-07-03 13:32**MOT test number** 317539232948**Result** ✓ Passed**MOT #15** 2020-07-06 15:10**MOT test number** 497510371175**Result** ✓ Passed**MOT #14** 2020-07-06 10:47**MOT test number** 408899570927**Result** ✗ Failed**Fail** Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Advice** Both front tyres are wearing unevenly on inner edges!**Advice** Engine has no oil in it! 1.5 litres added for testing purposes

**MOT #13**

2019-06-21 09:16

MOT test number

485269278694

Result

✓ Passed

- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #12

2018-06-15 16:42

MOT test number

189367069683

Result

✓ Passed

- Minor** Central Rear Stop lamp(s) with a multiple light source up to 1/2 not functioning (4.3.1 (a) (i))

MOT #11

2018-06-15 15:28

MOT test number

710967576297

Result

✗ Failed

- Fail** Central Rear Stop lamp(s) not working (4.3.1 (a) (ii))

MOT #10

2017-06-09 15:33

MOT test number

230757407087

Result

✓ Passed

- Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Central Rear stop lamp not working
- Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**MOT #9** 2017-06-09 11:11**MOT test number** 286571561944**Result** ✗ Failed

- Advice** Central Rear stop lamp not working
- Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm 2055516 (4.1.E.1)
- Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Offside Rear Tyre worn close to the legal limit badly cracked (4.1.E.1)

MOT #8 2016-06-13 16:58**MOT test number** 382473529663**Result** ✓ Passed

- Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Offside Front Tyre worn close to the legal limit 1.6mm (4.1.E.1)
- Advice** Offside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

MOT #7 2016-06-13 11:42**MOT test number** 613384419218**Result** ✗ Failed

Advice Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Advice Nearside Front Brake pad(s) wearing thin (3.5.1g)

Fail Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Advice Offside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Advice Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Advice Offside Front Tyre worn close to the legal limit 1.6mm (4.1.E.1)

**MOT #6** 2015-06-26 10:44**MOT test number** 246057375108**Result** ✓ Passed**Notice** Advise off side front wiper blade split**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #5** 2014-06-10 10:30**MOT test number** 256951564496**Result** ✓ Passed**MOT #4** 2013-06-25 10:16**MOT test number** 897956973108**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Under-trays fitted obscuring some underside components**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2012-06-20 10:49**MOT test number** 306262772113**Result** ✓ Passed**MOT #2** 2011-06-18 10:25**MOT test number** 516249061118**Result** ✓ Passed**MOT #1** 2010-06-30 14:00**MOT test number** 100431980167**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
6 July 2024

Tax status	Valid until 1 August
Days left	93
MOT expiry date	6 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2007-07-31
Last registration	2023-07-07
Complete history	See info



Registration #1	2007-07-31	25 mi
Registration #2	2010-06-30	11.691 mi
Registration #3	2011-06-18	16.052 mi
Registration #4	2012-06-20	19.193 mi
Registration #5	2013-06-25	24.352 mi
Registration #6	2014-06-10	30.324 mi
Registration #7	2015-06-26	38.237 mi
Registration #8	2016-06-13	44.844 mi
Registration #9	2016-06-13	44.844 mi
Registration #10	2017-06-09	53.180 mi
Registration #11	2017-06-09	53.181 mi
Registration #12	2018-06-09	61.517 mi
Registration #13	2018-06-09	61.517 mi
Registration #14	2018-06-09	61.517 mi
Registration #15	2018-06-09	61.517 mi
Registration #16	2018-06-09	61.517 mi
Registration #17	2018-06-09	61.517 mi
Registration #18	2018-06-09	61.517 mi
Registration #19	2018-06-09	61.517 mi
Registration #20	2018-06-09	61.517 mi
Registration #21	2018-06-09	61.517 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1755 mm
Height	1655 mm
Length	4505 mm
Wheel base	2750 mm
Kerb weight	1395 kg
Max. allowed weight	2090 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	7
Number of axles	2
Engine number	L8 20215250