






report date: 2024-03-29

General information

| Make | JAGUAR |
|---------------------|-------------------|
| Model | XJ D V6 LUXURY |
| Colour | Black |
| Year of manufacture | - |
| Top speed | 155 mph |
| 0 - 60 mph | 6.4 seconds |
| Gearbox | 6 speed automatic |

Engine & fuel consumption

| Power | 275 BHP |
|-------------------------|---------------------|
| Max. torque | 600 Nm at 2.000 rpm |
| Cylinders | 6 |
| Fuel type | Diesel |
| Consumption city | 29.4 mpg |
| Consumption extra urban | 50.4 mpg |
| Consumption combined | 40.4 mpg |



CarCheck.co.uk page 1/9



report date: 2024-03-29

223155906883

MOT history

MOT test number

| MOT #11 | 2020-09-15 15:20 |
|------------------|------------------|
| MOT test number | 380642229512 |
| Result | ✓ Passed |
| Next expiry date | 2021-09-14 |
| | |
| MOT #10 | 2019-08-09 09:13 |

| Result | ✓ Passed |
|-----------------|------------------|
| | |
| MOT #9 | 2018-08-02 16:04 |
| MOT test number | 829662519525 |
| Result | ✓ Passed |

| MOT #8 | 2018-08-02 16:04 | |
|-------------------------|--|--|
| MOT test number | 371076800495 | |
| Result | X Failed | |
| Pass with rectification | Nearside Registration plate lamp inoperative in the case of a single lamp or all | |
| lamps (4.7.1 (b) (ii)) | | |
| Pass with rectification | Offside Registration plate lamp inoperative in the case of a single lamp or all | |
| lamps (4.7.1 (b) (ii)) | | |

| MOT #7 | 2018-07-03 12:02 |
|--|------------------|
| MOT test number | 899185738121 |
| Result | × Failed |
| Fail Nearside Front Suspension component pin or bush excessively worn (5.3.4 (a) (i) Fail Offside Front Suspension component pin or bush excessively worn (5.3.4 (a) (i)) | |

| MOT #6 | 2017-06-12 09:03 |
|---|------------------|
| MOT test number | 751827021487 |
| Result | ✓ Passed |
| Advice Engine cover and under tray fitted | |

CarCheck.co.uk page 2/9



report date: 2024-03-29

| MOT #5 | 2016-06-13 15:57 |
|--|------------------|
| MOT test number | 537979550147 |
| Result | ✓ Passed |
| | |
| MOT #4 | 2015-06-05 14:42 |
| MOT test number | 207226555183 |
| Result | ✓ Passed |
| | |
| MOT #3 | 2014-05-09 14:54 |
| MOT test number | 159139024129 |
| Result | ✓ Passed |
| | |
| MOT #2 | 2013-08-22 17:05 |
| MOT test number | 398694333468 |
| Result | ✓ Passed |
| Advice Front registration plate deteriorated but not likely to be misread (6.3.1d) | |

| MOT # | 1 | 2013-08-20 13:12 |
|---|---|------------------|
| MOT te | st number | 356792733425 |
| Result | | 🗙 Failed |
| Fail | Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1) | |
| Fail | Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1) | |
| Fail Offside Front Tyre has ply or cords exposed (4.1.D.1b) | | |
| Advic | Front registration plate deteriorated but not likely to be misread (6.3.1d) | |
| Fail | Fail Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1) | |
| Fail | Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1) | |
| Fail | Nearside Front Tyre has ply or cords exposed (4.1.D.1b) | |

CarCheck.co.uk page 3/9



report date: 2024-03-29

Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|--|
| Date | |
| Category | |
| Туре | |
| Damage 2 | |
| Date | |
| Category | |
| Туре | |



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 4/9



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 5/9



report date: 2024-03-29

More info >

| Owner history | |
|---|-------------|
| For how long did the current and previous owner(s) have this JAGUAR? How many owner have? Check it in the premium report and see all owner registrations. Download the full | |
| ********* | |
| *************************************** | |
| ************ | |
| 2000000 | |
| *************************************** | |
| *************************************** | |
| | More info > |
| Plate changes | |
| See in this check if this JAGUAR had different number plates. | |
| Number of plates | |
| Current registration | UK UK |
| Plate since | |
| Current registration | NK SIE |
| Plate since | |

CarCheck.co.uk page 6/9



AGZ9142
report date: 2024-03-29

Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled.

If not, and you buy this JAGUAR then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this JAGUAR is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

Contact info

More info >

CarCheck.co.uk page 7/9



report date: 2024-03-29

Mileage check

| Odometer | In miles | |
|----------------------------|------------|--|
| Mileage registrations | 12 | |
| First mileage registration | 2010-09-23 | |
| Last registration | 2020-09-15 | |
| Complete history | See info | |



| Registration #1 | 2010-09-23 | 10 mi |
|------------------|------------|-----------|
| Registration #2 | 2013-08-20 | 43.396 mi |
| Registration #3 | 2013-08-22 | 43.396 mi |
| Registration #4 | 2014-05-09 | 49.720 mi |
| Registration #5 | 2015-06-05 | 61.170 mi |
| Registration #6 | 2016-06-13 | 73.883 mi |
| Registration #7 | | 11.777 es |
| Registration #8 | | 77,777 44 |
| Registration #9 | | 11.777 es |
| Registration #10 | | 11.777 es |
| Registration #11 | | 11.777 es |
| Registration #12 | | 11.777 mg |

More info >

CarCheck.co.uk page 8/9



report date: 2024-03-29

| | | | _ | | |
|------|------|-------|------------|----------------|------|
| - 11 | manc | Innc | . . | $M \cap M$ | aht |
| וט | mens | כווטו | CX. | $vv \subset v$ | ullu |
| | | | | | |

| Width | 2110 mm |
|---------------------|---------|
| Height | 1448 mm |
| Length | 5122 mm |
| Wheel base | 3157 mm |
| Kerb weight | 1796 kg |
| Max. allowed weight | 2365 kg |

Additional information

| Fuel tank capacity | 83 I |
|--------------------|------------------|
| Fuel delivery | Direct Injection |
| Number of doors | 4 |
| Number of seats | 5 |
| Number of axles | 2 |
| Engine number | 0502641306DT |

CarCheck.co.uk page 9/9