



HYUNDAI



report date: 2024-03-28

General information

| | |
|---------------------|-------------------|
| Make | HYUNDAI |
| Model | SANTA FE CRTD CDX |
| Colour | Grey |
| Year of manufacture | 2008 |
| Top speed | 111 mph |
| 0 - 60 mph | 12.9 seconds |
| Gearbox | 5 speed automatic |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 148 BHP |
| Max. torque | 335 Nm at 1.800 rpm |
| Engine capacity | 2.188 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 25.2 mpg |
| Consumption extra urban | 42.8 mpg |
| Consumption combined | 34.0 mpg |
| CO2 emission | 218 g/km |
| CO2 label | K |





Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-01-31 |
| Pictures | 10 |
| Listing price | View report |



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2022-06-28 |
| MOT pass rate | 80 % |
| MOT passed | 12 |
| Failed MOT tests | 3 |
| Total advice items | 16 |
| Total items failed | 8 |

| | |
|------------------|---|
| MOT #15 | 2021-06-29 17:54 |
| MOT test number | 801006504093 |
| Result | ✓ Passed |
| Next expiry date | 2022-06-28 |
| Advice | Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) |

| | |
|-----------------|--|
| MOT #14 | 2021-06-12 16:32 |
| MOT test number | 924037733907 |
| Result | ✗ Failed |
| Advice | Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) |
| Fail | Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c)) |
| Fail | Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b)) |

| | |
|-----------------|--|
| MOT #13 | 2020-11-13 14:29 |
| MOT test number | 215943113175 |
| Result | ✓ Passed |
| Minor | Nearside Front Steering linkage ball joint ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i)) |
| Advice | Oil leak, but not excessive (8.4.1 (a) (i)) |
| Minor | Offside Front Steering linkage ball joint ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i)) |

**MOT #12** 2020-06-27 11:46**MOT test number** 949394707174**Result** ✓ Passed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #11** 2019-04-17 10:41**MOT test number** 683933752211**Result** ✓ Passed**Advice** Nearside Power steering pipe/hose has slight seepage (2.1.5 (a))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #10** 2018-04-06 09:20**MOT test number** 902005451040**Result** ✓ Passed**MOT #9** 2018-04-06 09:20**MOT test number** 379932588624**Result** ✗ Failed**Pass with rectification** Offside Front position lamp(s) not working (1.1.A.3b)**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)**Pass with rectification** Nearside Rear Front position lamp(s) not working (1.1.A.3b)**Pass with rectification** Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #8** 2017-04-03 10:18**MOT test number** 983955143106**Result** ✓ Passed

**MOT #7** 2016-04-08 10:08**MOT test number** 875913361034**Result** ✓ Passed**MOT #6** 2015-04-27 17:00**MOT test number** 989767915195**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #5** 2014-04-29 15:35**MOT test number** 605729914124**Result** ✓ Passed**MOT #4** 2013-03-25 17:04**MOT test number** 795194583027**Result** ✓ Passed**Notice** Boot full, unable to check rear seat belts**Notice** Under-trays fitted obscuring some underside components**MOT #3** 2012-04-03 13:36**MOT test number** 136874992429**Result** ✓ Passed**MOT #2** 2012-04-03 13:36**MOT test number** 948584292096**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim too high (1.8)**Pass with rectification** Offside Headlamp aim too high (1.8)



MOT #12011-04-13 14:45

MOT test number666183301196

Result

✓ Passed

Advice

Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.C.1b)

Notice

Both front tyres wearing on edges

Advice

Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)



Tax & MOT check

✕
Untaxed

Tax expired:
10 October 2020

✕
MOT

Expired:
28 June 2022

| | |
|------------------|---------------------------------|
| Tax status | Expired at 10 October 2020 |
| Days left | 1296 days too late |
| MOT expiry date | 28 June 2022 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|---|------------|
| Vehicle class | 49 |
| Band | K |
| Single payment (12 months) | £ 395,00,- |
| Single six month payment | £ 217,25,- |
| Total payable by 12 monthly instalments | £ 414,75,- |



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

| | |
|----------------------|------------|
| Number of plates | 1 |
| Current registration | |
| Plate since | 2023-03-28 |
| Current registration | |
| Plate since | 2023-03-28 |

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

| | | |
|-------------------|----------|----------|
| Finance company | REDACTED | REDACTED |
| Date of agreement | REDACTED | REDACTED |
| Agreement type | REDACTED | REDACTED |
| Agreement term | REDACTED | REDACTED |
| Agreement number | REDACTED | REDACTED |
| Contact info | REDACTED | REDACTED |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 16 |
| First mileage registration | 2008-04-11 |
| Last registration | 2021-06-29 |
| Complete history | See info |



| | | |
|------------------|------------|------------|
| Registration #1 | 2008-04-11 | 28 mi |
| Registration #2 | 2011-04-13 | 32.958 mi |
| Registration #3 | 2012-04-03 | 41.171 mi |
| Registration #4 | 2013-03-25 | 47.091 mi |
| Registration #5 | 2014-04-29 | 57.851 mi |
| Registration #6 | 2015-04-27 | 65.691 mi |
| Registration #7 | 2016-04-08 | 71.178 mi |
| Registration #8 | 2017-04-03 | 79.540 mi |
| Registration #9 | 2018-04-03 | 88.000 mi |
| Registration #10 | 2019-04-03 | 96.500 mi |
| Registration #11 | 2020-04-03 | 105.000 mi |
| Registration #12 | 2021-04-03 | 113.500 mi |
| Registration #13 | 2022-04-03 | 122.000 mi |
| Registration #14 | 2023-04-03 | 130.500 mi |
| Registration #15 | 2024-04-03 | 139.000 mi |
| Registration #16 | 2025-04-03 | 147.500 mi |

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1890 mm |
| Height | 1725 mm |
| Length | 4650 mm |
| Wheel base | 2700 mm |
| Kerb weight | 1994 kg |
| Max. allowed weight | 2570 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 75 l |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 7 |

| | |
|---------------|-------------|
| Engine number | D4EB8575192 |
|---------------|-------------|