



HYUNDAI



report date: 2024-03-28

General information

| | |
|---------------------|-------------------|
| Make | HYUNDAI |
| Model | IX20 STYLE |
| Colour | White |
| Year of manufacture | 2011 |
| Top speed | 114 mph |
| 0 - 60 mph | 12.2 seconds |
| Gearbox | 4 speed automatic |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 123 BHP |
| Max. torque | 156 Nm at 4.200 rpm |
| Engine capacity | 1.591 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 34.0 mpg |
| Consumption extra urban | 51.4 mpg |
| Consumption combined | 43.5 mpg |
| CO2 emission | 154 g/km |
| CO2 label | G |



Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-06-29 |
| Pictures | 22 |
| Listing price | View report |



source: **autotrader.co.uk**



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-07-04 |
| MOT pass rate | 71 % |
| MOT passed | 10 |
| Failed MOT tests | 4 |
| Total advice items | 14 |
| Total items failed | 6 |

MOT #14 2023-07-04 16:27

MOT test number 276592685741

Result ✓ Passed

Next expiry date 2024-07-04

- Advice** Offside Front Tyre worn close to legal limit/worn on edge /age cracking (5.2.3 (e))
- Advice** Front Suspension arm pin or bush worn but not resulting in excessive movement both lower/inner (5.3.4 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))

MOT #13 2023-07-04 14:55

MOT test number 639094462919

Result ✗ Failed

- Advice** Front Suspension arm pin or bush worn but not resulting in excessive movement both lower/inner (5.3.4 (a) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge /age cracking (5.2.3 (e))
- Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Fail** Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #12**

2022-07-02 08:54

MOT test number

837497644695

Result

✓ Passed

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #11

2022-07-02 08:54

MOT test number

787191816622

Result

✗ Failed

Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Pass with rectification Front Windscreen washer provides insufficient washer liquid (3.5 (a))

MOT #10

2021-07-05 09:51

MOT test number

329533123304

Result

✓ Passed

MOT #9

2020-10-21 11:13

MOT test number

609355388041

Result

✓ Passed

MOT #8

2020-10-21 11:13

MOT test number

541792553825

Result

✗ Failed

Pass with rectification Nearside Headlamp aim too low (4.1.2 (a))



| | |
|---------------|------------------|
| MOT #7 | 2019-06-12 12:20 |
|---------------|------------------|

| | |
|------------------------|--------------|
| MOT test number | 668996045500 |
|------------------------|--------------|

| | |
|---------------|----------|
| Result | ✓ Passed |
|---------------|----------|

| | |
|---------------|------------------|
| MOT #6 | 2019-06-12 08:41 |
|---------------|------------------|

| | |
|------------------------|--------------|
| MOT test number | 872638126043 |
|------------------------|--------------|

| | |
|---------------|----------|
| Result | ✗ Failed |
|---------------|----------|

| | |
|-------------|---|
| Fail | Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) |
|-------------|---|

| | |
|-------------|--|
| Fail | Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b)) |
|-------------|--|

| | |
|---------------|------------------|
| MOT #5 | 2018-07-03 09:49 |
|---------------|------------------|

| | |
|------------------------|--------------|
| MOT test number | 987298691094 |
|------------------------|--------------|

| | |
|---------------|----------|
| Result | ✓ Passed |
|---------------|----------|

| | |
|---------------|------------------|
| MOT #4 | 2017-06-12 12:07 |
|---------------|------------------|

| | |
|------------------------|--------------|
| MOT test number | 474053220542 |
|------------------------|--------------|

| | |
|---------------|----------|
| Result | ✓ Passed |
|---------------|----------|

| | |
|---------------|------------------|
| MOT #3 | 2016-06-11 09:15 |
|---------------|------------------|

| | |
|------------------------|--------------|
| MOT test number | 910277080734 |
|------------------------|--------------|

| | |
|---------------|----------|
| Result | ✓ Passed |
|---------------|----------|

| | |
|---------------|------------------|
| MOT #2 | 2015-06-08 17:46 |
|---------------|------------------|

| | |
|------------------------|--------------|
| MOT test number | 647509555107 |
|------------------------|--------------|

| | |
|---------------|----------|
| Result | ✓ Passed |
|---------------|----------|

| | |
|---------------|------------------|
| MOT #1 | 2014-06-14 10:12 |
|---------------|------------------|

| | |
|------------------------|--------------|
| MOT test number | 446105964168 |
|------------------------|--------------|

| | |
|---------------|----------|
| Result | ✓ Passed |
|---------------|----------|



Tax & MOT check

✓
Taxed

Tax due:
1 July 2024

✓
MOT

Expires:
4 July 2024

| | |
|------------------|---------------------------------|
| Tax status | Valid until 1 July |
| Days left | 64 |
| MOT expiry date | 4 July 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|---|------------|
| Vehicle class | 48 |
| Band | G |
| Single payment (12 months) | £ 240,00,- |
| Single six month payment | £ 132,00,- |
| Total payable by 12 monthly instalments | £ 252,00,- |



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,299 |
| Auction value | £ 19,299 |
| Average private trade value | £ 19,299 |

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

| | |
|----------------------|------------|
| Number of plates | 1 |
| Current registration | EN11EUX |
| Plate since | 2024-03-28 |
| Current registration | EN11EUX |
| Plate since | 2024-03-28 |

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

| | | |
|-------------------|----------|------|
| Finance company | XXXXXXXX | XXXX |
| Date of agreement | XXXXXXXX | XXXX |
| Agreement type | XXXXXXXX | XXXX |
| Agreement term | XXXXXXXX | XXXX |
| Agreement number | XXXXXXXX | XXXX |
| Contact info | XXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 16 |
| First mileage registration | 2011-07-07 |
| Last registration | 2023-07-04 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2011-07-07 | 22 mi |
| Registration #2 | 2014-06-14 | 9.540 mi |
| Registration #3 | 2015-06-08 | 14.757 mi |
| Registration #4 | 2016-06-11 | 20.107 mi |
| Registration #5 | 2017-06-12 | 24.018 mi |
| Registration #6 | 2018-07-03 | 27.475 mi |
| Registration #7 | 2019-06-12 | 29.272 mi |
| Registration #8 | 2019-06-12 | 29.273 mi |
| Registration #9 | 2019-06-12 | 29.272 mi |
| Registration #10 | 2019-06-12 | 29.272 mi |
| Registration #11 | 2019-06-12 | 29.272 mi |
| Registration #12 | 2019-06-12 | 29.272 mi |
| Registration #13 | 2019-06-12 | 29.272 mi |
| Registration #14 | 2019-06-12 | 29.272 mi |
| Registration #15 | 2019-06-12 | 29.272 mi |
| Registration #16 | 2019-06-12 | 29.272 mi |

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

| | |
|----------------|---------------------------------|
| NCAP rating | ★★★★★ |
| Adult | 89% |
| Children | 85% |
| Pedestrian | 64% |
| Safety systems | 71% |
| Overall rating | 81% |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1765 mm |
| Height | 1600 mm |
| Length | 4100 mm |
| Wheel base | 2615 mm |
| Kerb weight | 1294 kg |
| Max. allowed weight | 1730 kg |

Additional information

| | |
|--------------------|-----------------------|
| Fuel tank capacity | 48 l |
| Fuel delivery | Multi-Point Injection |
| Number of doors | 5 |
| Number of seats | 5 |

| | |
|------------------------|--------------|
| Number of axles | 2 |
| Engine number | G4FCAZ212710 |