





report date: 2024-03-29

General information

| Make | AUDI |
|---------------------|-------------------|
| Model | A3 TFSI S LINE |
| Colour | Black |
| Year of manufacture | 2017 |
| Top speed | 136 mph |
| 0 - 100 km/h | 8.2 seconds |
| 0 - 60 mph | 8.2 seconds |
| Gearbox | 7 speed automatic |

Engine & fuel consumption

| Power | 110 kW / 150 HP / 148 BHP |
|-------------------------|---------------------------|
| Max. torque | 250 Nm at 1.500 rpm |
| Engine capacity | 1.498 сс |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 45.6 mpg |
| Consumption extra urban | 65.7 mpg |
| Consumption combined | 56.5 mpg |
| CO2 emission | 114 g/km |
| CO2 label | С |



CarCheck.co.uk page 1/11




Internet history

Entry 1

Date 2021-08-30

Pictures 32

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



| B 4 | \sim $-$ | | |
|-------|-------------|------|--------|
| 10.71 | $^{\prime}$ | hic | tory |
| 101 | C I | 1115 | I OI V |
| | • | | , |

| MOT expiry date | 2024-11-07 |
|--------------------|------------|
| MOT pass rate | 80 % |
| MOT passed | 4 |
| Failed MOT tests | 1 |
| Total advice items | 11 |
| Total items failed | 3 |

| MOT #5 | 2023-10-31 14:06 |
|------------------|------------------|
| MOT test number | 481945770049 |
| Result | ✓ Passed |
| Next expiry date | 2024-11-07 |

| MOT #4 | | 2022-11-08 14:28 |
|--|---|------------------|
| MOT test | number | 380010403236 |
| Result | | ✓ Passed |
| Advice | Nearside Front Outer Tyre slightly damaged (5.2.3 (d) (ii)) | |
| Advice | Undertrays fitted | |
| Advice | Offside Rear Shock absorbers has light misting of oil (5.3.2 (b)) | |
| Advice Nearside Rear Outer Tyre worn close to legal limit/worn on edge And side wall slightly damage has been run flat (5.2.3 (e)) | | |

CarCheck.co.uk page 3/11



MOT #3 2022-11-08 10:51

MOT test number 778594292001

Result X Failed

Fail Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))

Fail Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Advice Nearside Rear Outer Tyre worn close to legal limit/worn on edge And side wall slightly damage has been run flat (5.2.3 (e))

Advice Undertrays fitted

Advice Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))

Fail Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Advice Nearside Front Outer Tyre slightly damaged (5.2.3 (d) (ii))

MOT #2 2021-09-22 12:16

MOT test number 588091638626

Result \(\sqrt{Passed} \)

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #1 2020-09-08 12:36

MOT test number 277793049213

Result \(\sqrt{Passed} \)

Advice All tyres showing slight cracking/perishing

Minor Windscreen wiper blade defective (3.4 (b) (i))

CarCheck.co.uk page 4/11



Tax & MOT check



| Tax status | Valid until 1 July |
|------------------|--------------------|
| Days left | 63 |
| MOT expiry date | 7 November 2024 |
| Full MOT history | See MOT history |

Tax calculation


CarCheck.co.uk page 5/11



Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



| Owner | history |
|--------|---------|
| OWITEL | HISLULY |

| For how long did the current and previous owner(s) have this AUDI? How many owners did Check it in the premium report and see all owner registrations. Download the full report \(\frac{1}{2} \) | | ve? |
|---|-----------|-----|
| | | |
| *************************************** | | |
| | | |
| *************************************** | | |
| *************************************** | | |
| | | |
| *************************************** | | |
| | More info | |
| | More into | |
| Plate changes | | |
| See in this check if this AUDI had different number plates. | | |
| Number of plates | | , |
| Current registration | UK UK | |
| Plate since | | |
| Current registration | UK UK | |
| Plate since | | |
| | More info | > |

CarCheck.co.uk page 8/11



Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this AUDI is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Control info | |

Contact info


More info >

CarCheck.co.uk page 9/11



Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 7 |
| First mileage registration | 2017-09-29 |
| Last registration | 2023-10-31 |
| Complete history | See info |



| Registration #1 | 2017-09-29 | 16 mi |
|-----------------|------------|-----------|
| Registration #2 | 2020-09-08 | 16.562 mi |
| Registration #3 | | 11.177 es |
| Registration #4 | 2021-09-22 | 20.994 mi |
| Registration #5 | | 11.777 mi |
| Registration #6 | | 11.777 es |
| Registration #7 | | 11.777 es |

More info >

CarCheck.co.uk page 10/11



Car features

| S0225 | Air conditioning |
|-------|------------------|
| 50295 | |
| S0482 | |
| 50501 | |
| S0566 | |
| S0567 | |
| S0569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 95% |
| Children | 87% |
| Pedestrian | 74% |
| Safety systems | 86% |
| Overall rating | 88% |
| Video | see crash video |



Dimensions & weight

| Width | 1966 mm |
|-------------|---------|
| Height | 1426 mm |
| Length | 4313 mm |
| Wheel base | 2637 mm |
| Kerb weight | 1215 kg |

Additional information

| Fuel tank capacity | 50 I |
|---------------------------------|-----------------------|
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of axles | 2 |
| Engine number CarCheck.co.uk | DADA012121 page 11/11 |