





General information

Make	MERCEDES-BENZ
Model	CLK CLK350 SPORT
Colour	Silver
Year of manufacture	-
Top speed	155 mph
0 - 60 mph	6.7 seconds
Gearbox	7 speed automatic

Engine & fuel consumption

Power	268 BHP
Max. torque	350 Nm at 3.000 rpm
Cylinders	6
Fuel type	Petrol
Consumption city	19.3 mpg
Consumption extra urban	36.7 mpg
Consumption combined	27.7 mpg





Internet history

Entry 2

Date Pictures 2022-04-18

25

Listing price

-

View report



source: yesauto.com

Entry 1	
Date	2022-01-15
Pictures	26
Listing price	View report



source: autotrader.co.uk







MOT history

MOT #23	2023-07-12 12:54
MOT test number	854991734879
Result	✓ Passed
Next expiry date	2024-07-11

MOT #22		2023-07-10 08:04
MOT test	number	965019280547
Result		🗙 Failed
MAJOR	Offside Front Coil spring fractured or broken (5.3.1 (b) (i))	
Advice	Offside Front Shock absorbers has slight external damage to the casing (5.3.2 (b))	

MOT #21	2021-05-26 12:41
MOT test number	519931508382
Result	✓ Passed

MOT #20		2021-05-26 12:41
MOT test number		274560028712
Result		🗙 Failed
Pass with rectification	Offside Headlamp aim too low (4.1.2 (a))	
Pass with rectification	Nearside Headlamp aim too low (4.1.2 (a))	

MOT #19	2020-05-28 09:48
MOT test	number 872635968493
Result	✓ Passed
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Exhaust heat shield insecure at rear



CU06	LVS
report date:	2024-03-28

MOT #18		2020-05-27 08:44
MOT test	number	607087520885
Result		🗙 Failed
Advice	Nearside Rear Anti-roll bar ball joint has slight play (5.3.4 (a) (i))	
Advice	Exhaust heat shield insecure at rear	
MAJOR	Offside Front Headlamp levelling device inoperative sensor bracket broken (4	4.1.5 (a))
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1	.11 (c))

MOT #17	2019-05-17 13:57
MOT test number	465249329598
Result	✓ Passed
Advice Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	

MOT #16		2019-05-16 09:55
MOT test	number	702374760558
Result		🗙 Failed
MAJOR	Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))	
Advice	Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	

MOT #15		2018-05-30 14:23
MOT test	number	242852100167
Result		✓ Passed
Advice Nearside Rear Inner Brake pipe corroded, covered in grease or other material (1.1.11 (c))		
Advice	Advice Offside Rear Sub-frame pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))	
Advice	Nearside Rear Sub-frame pin or bush worn but not resulting in excessive	e movement (5.3.4 (a) (i))





MOT #14	2017-06-07 09:38	
MOT test number	423665821601	
Result	✓ Passed	
MOT #13	2017-06-06 13:48	
MOT test number	672660634952	
Result	🗙 Failed	
Fail Nearside Front Lower Suspension arm rubber bush deteriorated resulting in excessive movement front (2.4.G.2)		
Advice Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)		
Fail Offside Front Lower Suspension arm has excessive play in a ball joint rear (2.4.G.2)		
Fail Offside Front Lower Suspension arm rubber bush deteriorated resulting in excessive movement front (2.4.G.2)		
FailOffside Front front brake application uneven (3.7.B.2)		
Fail Nearside Front Lower Suspension arm has excessive play in a ball joint rea	ar (2.4.G.2)	
NOT #12		

MOT #12	2016-09-10 08:46
MOT test number	441397008477
Result	✓ Passed
Advice Offside Front Suspension arm ball joint dust cover damaged, but preventin camber (2.4.G.2)	ng the ingress of dirt
Advice Camber bushes starting to split	
Advice Offside Rear Nail in tyre	
Advice Nearside Front Suspension arm ball joint dust cover damaged, but preven camber (2.4.G.2)	ting the ingress of dirt



CU06	LVS
report date:	2024-03-28

MOT #11	2016-09-03 07:59	
MOT test number	862171668340	
Result	🗙 Failed	
Fail Offside Rear coil spring broken (2.4.C.1a)		
Advice Nearside Front Suspension arm ball joint dust cover damaged, but preventing the ingress of dirt camber (2.4.G.2)		
Advice Offside Front Suspension arm ball joint dust cover damaged, but preventing the ingress of dirt camber (2.4.G.2)		
Advice Offside Rear Nail in tyre		
Advice Camber bushes starting to split		

MOT #10		2015-08-31 07:55
MOT test	number	619256990618
Result		✓ Passed
Advice	Front tyres wearing on edges	
Advice	Rear Tyre worn close to the legal limit both (4.1.E.1)	

МОТ #9	2014-09-17 10:08
MOT test number	328520764421
Result	✓ Passed

MOT #8		2013-09-14 09:05
MOT test	number	338667953491
Result		✓ Passed
Advice	Front registration plate delaminated but not likely to be misread (6.3.1d)	
Notice	Nearside rear tyre cracked but not showing cord or ply	



CU06LVS report date: 2024-03-28

MOT #7		2013-09-06 15:10
MOT test	number	577579843290
Result		🗙 Failed
Advice	Front registration plate delaminated but not likely to be misread (6.3.1d)	
Notice	Nearside rear tyre cracked but not showing cord or ply	
Fail Offside Front Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)		
MOT #6		2012-09-17 12:53

MOT test number	328731362283
Result	✓ Passed

MOT #5	2011-09-29 13:24
MOT test number	389102871454
Result	✓ Passed

MOT #4	2011-07-27 08:22
MOT test number	179018701202
Result	🗙 Failed
Fail Nearside Rear Road wheel fractured (4.2.B.1a)	

МОТ #3	2010-07-30 12:49
MOT test number	760781910298
Result	✓ Passed

MOT #2	2010-07-30 10:30	
MOT test number 62150121		
Result	🗙 Failed	
Fail Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)		
Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)		





MOT #1	2009-10-15 15:45
MOT test number	134948689215
Result	✓ Passed





Damage history

Check the damage history for this MERCEDES-BENZ. See if, where and when this MERCEDES-BENZ had damage and the car repair costs. We also check if this MERCEDES-BENZ was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FERRE
Category	A PLANE
Туре	
Damage 2	AMPLE
	A A A A A A A A A A A A A A A A A A A
Date	1. E
Category	ant
Туре	

Extra MERCEDES-BENZ salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES-BENZ in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.00.000
Auction value	4 10.000
Average private trade value	4 10.200

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this MERCEDES-BENZ? How many owners did this MERCEDES-BENZ have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

NUMBER OF TAXABLE PARTY	

	More info >
Plate changes	
See in this check if this MERCEDES-BENZ had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Current registration Plate since	





Finance check

Check if this MERCEDES-BENZ is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES-BENZ has been settled.

If not, and you buy this MERCEDES-BENZ then you could lose the money and the car you paid for.

Download the premium report here and check if this MERCEDES-BENZ is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info \rightarrow



CU06LVS report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	26
First mileage registration	2006-03-22
Last registration	2023-07-12
Complete history	See info



Registration #1	2006-03-22	14 mi
Registration #2	2009-10-15	27.888 mi
Registration #3	2010-07-30	33.395 mi
Registration #4	2010-07-30	33.396 mi
Registration #5	2011-07-27	37.676 mi
Registration #6	2011-09-29	37.680 mi
Registration #7	2012-09-17	40.753 mi
Registration #8	2013-09-06	43.967 mi
Registration #9	2013-09-14	44.044 mi
Registration #10	2014-09-17	47.549 mi
Registration #11	2015-08-31	51.257 mi
Registration #12	2016-09-03	54.992 mi
Registration #13	2016-09-10	55.031 mi
Registration #14		11.777 est
Registration #15		11.707 est
Registration #16		11.777 est
Registration #17		11.707 est
Registration #18		11.777 est
Registration #19		11.777 est
Registration #20		11.777 est
Registration #21		11.777 esi
Registration #22		11.777 est
Registration #23		11.777 esi
Registration #24		11.777 est
Registration #25		11.777 mi
Registration #26		01.707 est
CarChaele ee ule		

CarCheck.co.uk

More info >



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Dimensions & weight

Width	1991 mm
Height	1415 mm
Length	4652 mm
Wheel base	2690 mm
Kerb weight	1735 kg
Max. allowed weight	2190 kg

Additional information

Fuel tank capacity	62
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4
Number of axles	2
Engine number	27296030352025