





report date: 2024-03-29

General information

Make	VOLVO
Model	XC60 D5 SE LUX NAV AWD
Colour	Grey
Year of manufacture	2016
Top speed	130 mph
0 - 60 mph	7.8 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	220 BHP
Max. torque	440 Nm at 3.000 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Diesel
Consumption city	42.2 mpg
Consumption extra urban	55.4 mpg
Consumption combined	49.6 mpg
CO2 emission	149 g/km
CO2 label	F



CarCheck.co.uk page 1/11



report date: 2024-03-29

Internet history

Entry 3

Date 2024-02-05

Pictures 1

Listing price <u>View report</u>

source: autoonline.co.uk

Entry 2

Date	2024-02-05
Pictures	0
Listing price	View report

source: carcraft.co.uk

Entry 1

Date 2021-06-04

Pictures 8

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-29

MOT history

MOT expiry date	2024-06-03
MOT pass rate	83 %
MOT passed	5
Failed MOT tests	1
Total advice items	12
Total items failed	1

MOT #6		2023-05-24 13:30
MOT test	number	166281895743
Result		✓ Passed
Next expi	ry date	2024-06-03
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #5	2023-05-23 11:00
MOT test number	554890513455
Result	★ Failed
Fail Nearside Front Coil spring fractured or broken (5.3.1 (b)	(i))
Advice Nearside Rear Tyre slightly damaged/cracking or per	rishing (5.2.3 (d) (ii))
Advice Offside Rear Tyre worn close to legal limit/worn on e	dge (5.2.3 (e))
Advice Offside Rear Tyre slightly damaged/cracking or peris	shing (5.2.3 (d) (ii))
Advice Nearside Rear Tyre worn close to legal limit/worn on	edge (5.2.3 (e))

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT #4		2022-05-24 07:41
MOT test	number	786479523199
Result		✓ Passed
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #3	2021-06-04 15:29
MOT test number	523915466331
Result	✓ Passed

MOT #2	2020-09-23 13:25
MOT test number	363214836040
Result	✓ Passed

MOT #1	2019-10-22 13:47
MOT test number	102678925435
Result	✓ Passed
Minor Nearside Rear Registration plate lamp inoperative in the case (4.7.1 (b) (i))	se of multiple lamps or light sources

CarCheck.co.uk page 4/11



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 March
Days left	306
MOT expiry date	3 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-

CarCheck.co.uk page 5/11



report date: 2024-03-29

Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

Owner history	

Owner history		
For how long did the current and previous owner(s) have this VOLVO? How many owners have? Check it in the premium report and see all owner registrations. Download the full is		

	More info >	
Plate changes		
See in this check if this VOLVO had different number plates.		
Number of plates		
Current registration	UK UK	
Plate since		
Current registration	UK NE	
Plate since		
	More info >	

page 8/11 CarCheck.co.uk



report date: 2024-03-29

Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2016-10-29
Last registration	2023-05-24
Complete history	See info



Registration #1	2016-10-29	9 mi
Registration #2	2019-10-22	30.449 mi
Registration #3	2020-09-23	38.723 mi
Registration #4	2021-06-04	40.316 mi
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		91.777 es
Registration #10		11.777 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	94%
Children	79%
Pedestrian	48%
Safety systems	86%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	2120 mm
Height	1713 mm
Length	4644 mm
Wheel base	2774 mm
Kerb weight	1865 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11/1