



TOYOTA



report date: 2024-03-29

General information

Make	TOYOTA
Model	COROLLA VERSO D-4D SR
Colour	Silver
Year of manufacture	2009
Top speed	122 mph
0 - 60 mph	9.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	134 BHP
Max. torque	310 Nm at 2.800 rpm
Engine capacity	2.231 cc
Cylinders	4
Fuel type	Diesel
Consumption city	35.3 mpg
Consumption extra urban	53.3 mpg
Consumption combined	44.8 mpg
CO2 emission	164 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-08-11
Pictures	1
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-02-21
MOT pass rate	81 %
MOT passed	13
Failed MOT tests	3
Total advice items	37
Total items failed	4

MOT #16	2024-02-21 13:41
MOT test number	174117748484
Result	✓ Passed
Next expiry date	2025-02-21

MOT #15	2023-01-30 12:40
MOT test number	120198427013
Result	✓ Passed

MOT #14	2022-02-09 16:32
MOT test number	232405328272
Result	✓ Passed

MOT #13	2022-02-09 11:24
MOT test number	666595413072
Result	✗ Failed

- MAJOR** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- DANGEROUS** Offside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- MAJOR** Brake pedal has insufficient reserve travel (1.1.2 (a))
- MAJOR** Offside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))
- MAJOR** Stop lamp(s) adversely affected by the operation of another lamp (4.3.3 (b))

**MOT #12**

2021-02-19 16:15

MOT test number

560629350806

Result

✓ Passed

Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #11**

2020-02-20 15:42

MOT test number

262173922521

Result

✓ Passed

Advice Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Brake hydraulic reservoir close to minimum mark (1.1.10 (d) (i))**Advice** Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #10**

2019-02-21 12:28

MOT test number

155298049603

Result

✓ Passed

Advice Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. n/s+o/s (1.2.1 (b) (i))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Minor** Nearside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Offside Front tyre worn inner outer edges**Minor** Offside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**MOT #9**

2019-02-21 12:28

MOT test number

364282697087

Result**✗ Failed****Minor** Nearside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. n/s+o/s (1.2.1 (b) (i))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Minor** Offside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Offside Front tyre worn inner outer edges**Pass with rectification** Offside Front Position lamp not working (4.2.1 (a))**MOT #8**

2018-02-22 16:12

MOT test number

306034699895

Result**✓ Passed****Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Rear Tyre cracked and perished**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**MOT #7**

2018-02-22 16:12

MOT test number

556255835729

Result**✗ Failed****Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Pass with rectification** Nearside Stop lamp not working (1.2.1b)**Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)**Advice** Nearside Rear Tyre cracked and perished**Advice** Rear Brake pad(s) wearing thin (3.5.1g)

**MOT #6** 2017-02-15 14:31**MOT test number** 469409184629**Result** ✓ Passed**MOT #5** 2016-02-17 11:54**MOT test number** 883282132746**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**MOT #4** 2015-02-18 10:15**MOT test number** 685109345076**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Advice** Parking brake lever has little reserve travel (3.1.6b)**Notice** Under-trays fitted obscuring some underside components**Notice** Play in steering rack inner joint(s)**MOT #3** 2014-02-21 10:34**MOT test number** 799252254041**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Notice** Under-trays fitted obscuring some underside components**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**MOT #2** 2013-02-18 18:30**MOT test number** 349579343074**Result** ✓ Passed



MOT #1	2012-01-16 15:47
MOT test number	859486112039
Result	✓ Passed
Advice	Offside Front Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
21 February 2025

Tax status	Valid until 1 February
Days left	278
MOT expiry date	21 February 2025
Full MOT history	See MOT history

Tax calculation


Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	XXXX XX
Plate since	2024-03-29
Current registration	XXXX XX
Plate since	2024-03-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2009-02-18
Last registration	2024-02-21
Complete history	See info



Registration #1	2009-02-18	21 mi
Registration #2	2012-01-16	32.083 mi
Registration #3	2013-02-18	42.922 mi
Registration #4	2014-02-21	61.499 mi
Registration #5	2015-02-18	79.119 mi
Registration #6	2016-02-17	93.800 mi
Registration #7	2017-02-15	108.064 mi
Registration #8	2018-02-22	122.396 mi
Registration #9	2018-02-22	122.396 mi
Registration #10	2019-02-20	136.728 mi
Registration #11	2020-02-18	151.060 mi
Registration #12	2021-02-16	165.392 mi
Registration #13	2022-02-14	179.724 mi
Registration #14	2023-02-12	194.056 mi
Registration #15	2024-02-10	208.388 mi
Registration #16	2025-02-08	222.720 mi
Registration #17	2026-02-06	237.052 mi
Registration #18	2027-02-04	251.384 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1620 mm
Length	4360 mm
Wheel base	2750 mm
Kerb weight	1495 kg
Max. allowed weight	2160 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	2AD5416863