



T767JKM

report date: 2024-03-29

General information

Make	JAGUAR
Model	XKR
Colour	Green
Year of manufacture	1999
Top speed	155 mph
0 - 60 mph	5.4 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	370 BHP
Max. torque	525 Nm at 3.600 rpm
Engine capacity	3.996 cc
Cylinders	8
Fuel type	Petrol
Consumption city	16.1 mpg
Consumption extra urban	28.8 mpg
Consumption combined	22.4 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-06-10
Pictures	32
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2024-07-30
MOT pass rate	74 %
MOT passed	14
Failed MOT tests	5
Total advice items	34
Total items failed	13

MOT #19	2023-07-31 15:34
MOT test number	586927790360
Result	✓ Passed
Next expiry date	2024-07-30
Advice	Central Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #18	2023-07-24 14:08
MOT test number	127204329736
Result	✗ Failed
Fail	Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))
Advice	Central Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Minor	Offside Rear Brake hose slightly chafed abs cable rubbing on pipe (1.1.12 (b) (i))
Fail	Nearside Front Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))

MOT #17	2022-06-13 09:34
MOT test number	244460979223
Result	✓ Passed
Advice	Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #16**

2022-06-01 09:36

**MOT test number**

112904816312

**Result**

✗ Failed

**Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**Fail** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))

**Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Fail** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))

**Fail** Nearside Front Upper Suspension arm pin or bush excessively worn front (5.3.4 (a) (i))

**MOT #15**

2021-06-14 14:46

**MOT test number**

620733134469

**Result**

✓ Passed

**Advice** Rear Slight play in suspension

**Advice** Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #14**

2019-10-07 10:01

**MOT test number**

469605009681

**Result**

✓ Passed

**Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Minor** Offside Headlamp lens slightly defective mounting broken (4.1.1 (b) (i))

**Advice** Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))

**Advice** Vehicle suspension light corrosion

**Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #13**

2019-07-24 09:52

**MOT test number**

913149075230

**Result**

✗ Failed

**Advice**

Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4

(a) (i))

**Advice**

Front Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Fail**

Brake pipe likely to become detached or damaged (1.1.11 (d) (ii))

**Minor**

Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Fail**

Offside Front Upper Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

**Advice**

Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a)

(i))

**Fail**

Offside Front Suspension component mounting prescribed area excessively corroded significantly reducing structural strength (5.3.6 (a) (i))

**Fail**

Offside Front Brake pipe excessively corroded (1.1.11 (c))

**MOT #12**

2018-06-22 10:51

**MOT test number**

776432729715

**Result**

✓ Passed

**Advice**

Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a)

(i))

**Advice**

Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4

(a) (i))

**Advice**

Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4

(a) (i))

**MOT #11**

2016-07-14 15:57

**MOT test number**

728036652810

**Result**

✓ Passed

**MOT #10**

2015-04-21 12:19

**MOT test number**

849671815160

**Result**

✓ Passed

**Notice**

N/s/r tyre worn on inner edges



**MOT #9** 2015-04-10 10:52**MOT test number** 425080205183**Result** ✗ Failed**Fail** Nearside front brake binding (3.7.B.1)**Notice** N/s/r tyre worn on inner edges**Fail** Offside Front Headlamp insecure (1.7.3)**Fail** Nearside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Notice** N/s/f wheel bearing not fully checked due to brake binding**MOT #8** 2013-08-08 15:32**MOT test number** 339980523440**Result** ✓ Passed**Notice** Nearside and offside rear tyres starting to split on side walls**Notice** Nearside front brake binding**Notice** Nearside front upper suspension bushes worn**MOT #7** 2012-05-22 11:16**MOT test number** 358913542183**Result** ✓ Passed**MOT #6** 2011-05-10 16:09**MOT test number** 958900731192**Result** ✓ Passed**MOT #5** 2010-05-04 15:25**MOT test number** 283724520108**Result** ✓ Passed

**MOT #4** 2010-04-14 10:04**MOT test number** 723974000116**Result** ✗ Failed**Fail** Offside Front Seat belt anchorage prescribed area is excessively corroded (5.2.6)**MOT #3** 2009-03-24 13:39**MOT test number** 414673089088**Result** ✓ Passed**MOT #2** 2008-04-03 15:15**MOT test number** 452044198029**Result** ✓ Passed**MOT #1** 2007-03-07 09:19**MOT test number** 701076567049**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** CORROSION AFFECTING VEHICLE STRUCTURE; REAR EXHAUST AND ALL BRAKE DISCS.**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)





Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 August 2024

✓  
**MOT**  
**Expires:**  
30 July 2024

<b>Tax status</b>	Valid until 1 August
-------------------	----------------------

<b>Days left</b>	94
------------------	----

<b>MOT expiry date</b>	30 July 2024
------------------------	--------------

<b>Full MOT history</b>	<a href="#">See MOT history</a>
-------------------------	---------------------------------



Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this JAGUAR had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29

More info >



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled.

If not, and you buy this JAGUAR then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this JAGUAR is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	1999-12-31
Last registration	2023-07-31
Complete history	<a href="#">See info</a>



Registration #1	1999-12-31	22 mi
Registration #2	2007-03-07	54.208 mi
Registration #3	2008-04-03	56.910 mi
Registration #4	2009-03-24	57.886 mi
Registration #5	2010-04-14	58.706 mi
Registration #6	2010-05-04	58.704 mi
Registration #7	2011-05-10	59.907 mi
Registration #8	2012-05-22	61.762 mi
Registration #9	2013-08-08	62.939 mi
Registration #10	2015-04-10	64.081 mi
Registration #11	2015-04-21	64.081 mi
Registration #12	2016-05-20	65.223 mi
Registration #13	2017-06-19	66.365 mi
Registration #14	2018-07-18	67.507 mi
Registration #15	2019-08-17	68.649 mi
Registration #16	2020-09-16	69.791 mi
Registration #17	2021-10-15	70.933 mi
Registration #18	2022-11-14	72.075 mi
Registration #19	2023-12-13	73.217 mi
Registration #20	2024-01-12	74.359 mi
Registration #21	2024-02-11	75.501 mi

More info >



Dimensions & weight

Width	2015 mm
Height	1306 mm
Length	4760 mm

Additional information

Fuel tank capacity	75 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of axles	2
Engine number	EC9902161552