



report date: 2024-03-29

General information

Make	CITROEN
Model	C5 HDI VTR PLUS GRAND PICASSO
Colour	Silver
Year of manufacture	2008
Top speed	112 mph
0 - 60 mph	12.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	110 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	38.7 mpg
Consumption extra urban	55.4 mpg
Consumption combined	47.9 mpg
CO2 emission	145 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-08-05
Pictures	21
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



## MOT history

MOT expiry date	2024-06-20
MOT pass rate	70 %
MOT passed	14
Failed MOT tests	6
Total advice items	13
Total items failed	15

MOT #20	2023-06-21 08:48
MOT test number	925876384990
Result	✓ Passed
Next expiry date	2024-06-20
Minor	Offside Front Lower Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #19	2023-06-14 11:30
MOT test number	531270726364
Result	✗ Failed
Fail	Nearside Front Position lamp not working (4.2.1 (a) (ii))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Offside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
Advice	Nearside Rear Nail in tyre
Fail	Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Fail	Nearside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
Fail	Parking brake efficiency below requirements (1.4.2 (a) (i))
Minor	Offside Front Lower Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**MOT #18** 2022-07-28 12:52**MOT test number** 915929047303**Result** ✓ Passed**MOT #17** 2021-09-09 13:17**MOT test number** 581395356711**Result** ✓ Passed**MOT #16** 2021-09-09 08:28**MOT test number** 499791700004**Result** ✗ Failed**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Fail** Nearside Front Brake lever has restricted free movement caliper (1.1.15 (e))**Fail** Nearside Front Parking brake inoperative on one side (1.4.1 (a))**Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Fail** Nearside Front Brake cable has restricted free movement (1.1.15 (e))**MOT #15** 2020-10-21 13:07**MOT test number** 255272588947**Result** ✓ Passed**MOT #14** 2020-10-19 15:00**MOT test number** 910380692297**Result** ✗ Failed**Fail** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))**MOT #13** 2019-10-18 08:22**MOT test number** 202618140769**Result** ✓ Passed

**MOT #12** 2019-10-18 08:22**MOT test number** 198190999892**Result** ✗ Failed**Pass with rectification** Offside Front Position lamp not working (4.2.1 (a) (ii))**MOT #11** 2018-10-18 11:10**MOT test number** 841661835855**Result** ✓ Passed**Advice** Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #10** 2017-10-30 12:23**MOT test number** 630111445302**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit on outer edge (4.1.E.1)**Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)**MOT #9** 2016-10-24 12:13**MOT test number** 383452821440**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #8** 2015-10-21 08:16**MOT test number** 162116551927**Result** ✓ Passed

**MOT #7** 2014-11-07 12:13**MOT test number** 369821914360**Result** ✓ Passed**MOT #6** 2014-11-04 09:54**MOT test number** 458468704435**Result** ✗ Failed**Fail** Nearside Front position lamp(s) not working (1.1.A.3b)**Fail** Front Fluid suspension has no suspension movement (2.4.D.5)**MOT #5** 2013-10-01 09:57**MOT test number** 337544073400**Result** ✓ Passed**MOT #4** 2012-10-30 11:16**MOT test number** 685894302344**Result** ✓ Passed**MOT #3** 2012-04-11 12:31**MOT test number** 395252202123**Result** ✓ Passed**Notice** Oil leak**MOT #2** 2012-04-11 12:31**MOT test number** 309462502199**Result** ✗ Failed**Pass with rectification** Offside Front Front position lamp(s) not working (1.1.A.3b)**Notice** Oil leak



MOT #1	2011-04-14 15:48
MOT test number	326654201164
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 January 2025

✓  
**MOT**  
**Expires:**  
20 June 2024

<b>Tax status</b>	Valid until 1 January
<b>Days left</b>	247
<b>MOT expiry date</b>	20 June 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	F
<b>Single payment (12 months)</b>	£ 200,00,-
<b>Single six month payment</b>	£ 110,00,-
<b>Total payable by 12 monthly instalments</b>	£ 210,00,-





Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	0
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.


Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2008-05-30
Last registration	2023-06-21
Complete history	<a href="#">See info</a>



Registration #1	2008-05-30	13 mi
Registration #2	2011-04-14	22.380 mi
Registration #3	2012-04-11	30.976 mi
Registration #4	2012-10-30	36.018 mi
Registration #5	2013-10-01	42.164 mi
Registration #6	2014-11-04	48.602 mi
Registration #7	2014-11-07	48.607 mi
Registration #8	2015-10-21	55.065 mi
Registration #9	2016-10-24	60.350 mi
Registration #10	2017-10-30	65.742 mi
Registration #11	2018-10-18	71.700 mi
Registration #12	2019-05-29	75.557 mi
Registration #13	2019-05-29	75.557 mi
Registration #14	2019-05-29	75.557 mi
Registration #15	2019-05-29	75.557 mi
Registration #16	2019-05-29	75.557 mi
Registration #17	2019-05-29	75.557 mi
Registration #18	2019-05-29	75.557 mi
Registration #19	2019-05-29	75.557 mi
Registration #20	2019-05-29	75.557 mi
Registration #21	2019-05-29	75.557 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1829 mm
Height	1700 mm
Length	4585 mm
Wheel base	2728 mm
Kerb weight	1530 kg
Max. allowed weight	2250 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Number of axles	2
Engine number	JBCV0002257