



PEUGEOT



WF59JMX


report date: 2024-03-28

General information

Make	PEUGEOT
Model	EXPERT TEPEE LEISURE L1 HDI 120 9STR
Colour	Blue
Year of manufacture	2009
Top speed	99 mph
0 - 60 mph	13.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	120 BHP
Max. torque	300 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	32.1 mpg
Consumption extra urban	43.5 mpg
Consumption combined	38.7 mpg
CO2 emission	198 g/km
CO2 label	J





Internet history

Entry 2

Date	2022-01-12
Pictures	46
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2022-01-10
Pictures	0
Listing price	View report

source: autotrader.co.uk



MOT history

MOT expiry date	2024-12-03
MOT pass rate	52 %
MOT passed	12
Failed MOT tests	11
Total advice items	30
Total items failed	39

MOT #23	2023-12-04 16:19
MOT test number	343268900647
Result	✓ Passed
Next expiry date	2024-12-03
Advice	Visible smoke on FAS test

MOT #22	2023-11-25 08:55
MOT test number	482013285117
Result	✗ Failed
Fail	Offside Front Direction indicator incorrect colour (4.4.3 (a))
Fail	Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
Fail	Offside Front Position lamp not working (4.2.1 (a) (ii))
Fail	Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
Fail	Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))
Advice	Visible smoke on FAS test
Fail	Nearside Front Position lamp not working (4.2.1 (a) (ii))

**MOT #21**

2023-01-24 11:06

MOT test number

160531956037

Result

✓ Passed

Advice Engine oil leak**Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**MOT #20**

2023-01-14 12:36

MOT test number

450859041233

Result

✗ Failed

Fail Offside Front Headlamp aim too low (4.1.2 (a))**Fail** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Fail** Emissions not tested (8.2.2.2 (e))**Fail** Windscreen damaged and affecting the driver's view of the road crack from off side going in to zone A in the view of road (3.2 (a) (ii))**Advice** Engine oil leak**Fail** Nearside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Fail** Nearside Rear Service brake lagging in operation (1.2.1 (d))**Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Fail** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))**MOT #19**

2022-01-13 09:19

MOT test number

423475761061

Result

✓ Passed

**MOT #18**

2022-01-12 17:04

MOT test number

109169280840

Result**✗ Failed**

Fail Nearside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Fail Nearside Front Inner Brake disc significantly and obviously worn (1.1.14 (a) (i))

Fail Offside Front Inner Brake disc significantly and obviously worn (1.1.14 (a) (i))

MOT #17

2021-04-15 12:28

MOT test number

720718938892

Result**✓ Passed**

Advice Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Advice Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #16

2021-04-09 08:33

MOT test number

775089289708

Result**✗ Failed**

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Advice Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Fail Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Fail Offside Stop lamp(s) not working (4.3.1 (a) (ii))

Fail Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Advice Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail Brakes imbalanced across an axle by more than 50% (1.2.1 (b) (ii))

**MOT #15** 2020-03-31 10:07**MOT test number** 648114200457**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Oil leak, but not excessive engine (8.4.1 (a) (i))**MOT #14** 2020-03-31 10:07**MOT test number** 519275750885**Result** ✗ Failed**Advice** Oil leak, but not excessive engine (8.4.1 (a) (i))**Pass with rectification** Offside Headlamp aim too high (4.1.2 (a))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Pass with rectification** Nearside Headlamp aim too low (4.1.2 (a))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #13** 2019-03-25 15:01**MOT test number** 299662618481**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #12**

2019-03-25 08:45

MOT test number

564349708563

Result**✗ Failed**

Fail Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Fail Offside Stop lamp(s) not working (4.3.1 (a) (ii))

Fail Rear Exhaust system insecure (6.1.2 (a))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #11

2018-04-16 16:37

MOT test number

566793798682

Result**✓ Passed****MOT #10**

2018-01-16 09:51

MOT test number

899958087320

Result**✓ Passed****MOT #9**

2018-01-09 09:38

MOT test number

491735854189

Result**✗ Failed**

Fail Offside Front Inner Anti-roll bar rubber bush deteriorated resulting in excessive movement (2.4.G.2)

Fail Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

Fail Offside Front position lamp(s) not working (1.1.A.3b)

Fail Power steering fluid level below minimum (2.3.1)

Fail Rear Exhaust system not adequately supported (7.1.1)

Fail Nearside Rear Direction indicator incorrect colour (1.4.A.2f)

**MOT #8** 2016-12-09 10:31**MOT test number** 649183310319**Result** ✓ Passed**MOT #7** 2016-12-09 10:31**MOT test number** 443876643528**Result** ✗ Failed

Pass with rectification Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

MOT #6 2015-09-26 11:57**MOT test number** 871690399299**Result** ✓ Passed**MOT #5** 2015-09-26 09:39**MOT test number** 674290160081**Result** ✗ Failed

Fail Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Fail Offside Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

MOT #4 2014-09-16 11:52**MOT test number** 357309154407**Result** ✓ Passed

Notice Under-trays fitted obscuring some underside components

Notice Child seat fitted not allowing full inspection of adult belt

**MOT #3** 2014-09-16 11:52**MOT test number** 339389554230**Result** ✗ Failed**Notice** Under-trays fitted obscuring some underside components**Pass with rectification** Nearside Headlamp aim too high (1.8)**Notice** Child seat fitted not allowing full inspection of adult belt**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #2** 2012-11-14 11:49**MOT test number** 987859812364**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #1** 2012-11-14 11:49**MOT test number** 247939212359**Result** ✗ Failed**Pass with rectification** Offside Windscreen washer provides insufficient washer liquid (8.2.3)**Pass with rectification** Nearside Windscreen washer provides insufficient washer liquid (8.2.3)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Child seat fitted not allowing full inspection of adult belt



Tax & MOT check

X

Untaxed

Tax expired:
22 March 2024

✓

MOT

Expires:
3 December 2024

Tax status	Expired at 22 March 2024
Days left	38 days too late
MOT expiry date	3 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	WF59JMX
Plate since	2019-03-28
Current registration	WF59JMX
Plate since	2019-03-28

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2009-09-23
Last registration	2023-12-04
Complete history	See info



Registration #1	2009-09-23	10 mi
Registration #2	2012-11-14	23.884 mi
Registration #3	2014-09-16	34.024 mi
Registration #4	2015-09-26	44.330 mi
Registration #5	2015-09-26	44.330 mi
Registration #6	2016-12-09	62.881 mi
Registration #7	2016-12-09	62.881 mi
Registration #8	2018-01-09	72.651 mi
Registration #9	2018-01-16	76.257 mi
Registration #10	2018-04-16	76.628 mi
Registration #11	2019-03-25	84.859 mi
Registration #12	2019-03-25	84.859 mi
Registration #13	2019-03-25	84.859 mi
Registration #14	2019-03-25	84.859 mi
Registration #15	2019-03-25	84.859 mi
Registration #16	2019-03-25	84.859 mi
Registration #17	2019-03-25	84.859 mi
Registration #18	2019-03-25	84.859 mi
Registration #19	2019-03-25	84.859 mi
Registration #20	2019-03-25	84.859 mi
Registration #21	2019-03-25	84.859 mi
Registration #22	2019-03-25	84.859 mi
Registration #23	2019-03-25	84.859 mi
Registration #24	2019-03-25	84.859 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1986 mm
Height	1980 mm
Length	5135 mm
Wheel base	3000 mm
Kerb weight	1821 kg
Max. allowed weight	2759 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	9
Number of axles	2
Engine number	DYWD4031054