



report date: 2024-03-28

General information

Make	CITROEN
Model	DISPATCH 1000 L1H1 SWB P/V HDI 90
Colour	White
Year of manufacture	2010
Gearbox	5 speed Manual

Engine & fuel consumption

Power	90 BHP
Max. torque	180 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-12-21
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-02-02
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	27
Total items failed	9

MOT #14	2023-02-03 14:40
MOT test number	999309311215
Result	✓ Passed
Next expiry date	2024-02-02
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Minor	Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

MOT #13	2022-01-10 15:12
MOT test number	742687051310
Result	✓ Passed
Advice	Nearside Front Anti-roll bar pin or bush worn but not resulting in excessive movement 'D' bush (5.3.4 (a) (i))
Minor	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

MOT #12	2021-02-19 11:57
MOT test number	167825539970
Result	✓ Passed

**MOT #11**

2020-03-17 09:42

MOT test number

359744451532

Result

✓ Passed

Advice

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Minor

Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice

Coolant low

Advice

Coolant leak

Advice

Offside rear light lense cover damaged

Minor

Nearside Rear Rear reflector defective or damaged by up to 50% of the reflecting surface (4.8.1 (a) (i))

Advice

Offside lower door mirror damaged

MOT #10

2019-03-15 16:20

MOT test number

672493085239

Result

✓ Passed

Advice

Service brake has a long travel

Advice

Coolant low

Advice

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Front brake pads appear low

**MOT #9** 2019-03-15 09:35**MOT test number** 112361223724**Result** ✗ Failed**Advice** Front brake pads appear low**Fail** Nearside Rear Service brake lagging in operation (1.2.1 (d))**Advice** Service brake has a long travel**Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))**Advice** Coolant low**Fail** Rear Brakes imbalanced across an axle (1.2.1 (b) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #8** 2018-02-27 08:29**MOT test number** 933404219272**Result** ✓ Passed**MOT #7** 2017-03-17 17:34**MOT test number** 593020155206**Result** ✓ Passed**MOT #6** 2017-03-17 15:08**MOT test number** 210754624292**Result** ✗ Failed**Fail** Registration plate lamp not working (1.1.C.1d)**Fail** Rear brake application uneven (3.7.B.2)**Fail** Brake pedal spongy (3.3.B.1b)

**MOT #5** 2016-03-11 15:01**MOT test number** 991776861925**Result** ✓ Passed**MOT #4** 2016-03-11 15:01**MOT test number** 798627181021**Result** ✗ Failed

- Pass with rectification** Offside Front position lamp(s) not working (1.1.A.3b)
- Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Pass with rectification** Nearside Front position lamp(s) not working (1.1.A.3b)
- Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)

MOT #3 2015-03-12 13:42**MOT test number** 609331375070**Result** ✓ Passed

- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #2 2014-03-14 16:44**MOT test number** 985453374017**Result** ✓ Passed

- Notice** Front pads getting low
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #1 2013-03-20 14:25**MOT test number** 308789573084**Result** ✓ Passed

- Notice** Slightly long pedal travel, recommend brake check.



Tax & MOT check

✕
Untaxed

Tax expired:
1 February 2024

✕
MOT

Expired:
2 February 2024

Tax status	Expired at 1 February 2024
Days left	89 days too late
MOT expiry date	2 February 2024
Full MOT history	See MOT history



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-03-15
Last registration	2023-02-03
Complete history	See info



Registration #1	2010-03-15	27 mi
Registration #2	2013-03-20	27.411 mi
Registration #3	2014-03-14	37.479 mi
Registration #4	2015-03-12	46.953 mi
Registration #5	2016-03-11	54.688 mi
Registration #6	2016-03-11	54.688 mi
Registration #7	2017-03-17	63.661 mi
Registration #8	2017-03-17	63.662 mi
Registration #9	2019-03-20	75.377 mi
Registration #10	2019-03-20	75.377 mi
Registration #11	2019-03-20	75.377 mi
Registration #12	2019-03-20	75.377 mi
Registration #13	2019-03-20	75.377 mi
Registration #14	2019-03-20	75.377 mi
Registration #15	2019-03-20	75.377 mi
Registration #16	2023-02-03	75.377 mi

More info >



Dimensions & weight

Width	2194 mm
Length	4805 mm

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	3
Engine number	JBBY0029866