





report date: 2024-03-28

General information

Make	PEUGEOT
Model	107 ACCESS
Colour	Silver
Year of manufacture	2012
Top speed	99 mph
0 - 60 mph	14.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	68 BHP
Max. torque	93 Nm at 3.600 rpm
Engine capacity	998 сс
Cylinders	3
Fuel type	Petrol
Consumption city	55.4 mpg
Consumption extra urban	74.3 mpg
Consumption combined	65.7 mpg
CO2 emission	99 g/km
CO2 label	A



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history


Entry 1

Date 2021-05-25

Pictures 13

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

Μ	OT	hist	ory

MOT expiry date	2024-08-08
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	15
Total items failed	5

MOT #12		2023-08-09 10:09
MOT test	number	125757686704
Result		✓ Passed
Next expi	ry date	2024-08-08
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #11	2022-06-22 12:32
MOT test number	287555356828
Result	✓ Passed
MOT #10	2022-05-17 07:26
MOT test number	596080137342
Result	X Failed
Fail Offside Rear Rear fog lamp not working (4.5.1 (a) (ii))	

MOT #9	2021-05-21 15:35
MOT test number	967154431239
Result	✓ Passed

CarCheck.co.uk page 3/12



(a) (i))

YR62FMM

report date: 2024-03-28

MOT #8 2021-05-20 15:35 **MOT test number** 302969172256 Result × Failed Fail Offside Front Anti-roll bar pin or bush excessively worn (5.3.4 (a) (i)) **Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i)) Fail Nearside Front Anti-roll bar pin or bush excessively worn (5.3.4 (a) (i)) Fail Front Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii)) **Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4

MOT #7		2020-09-24 13:10
MOT test	number	570645185306
Result		✓ Passed
MOT #6		2019-09-24 10:13
MOT test	number	838901326101
Result		✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.	.11 (c))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.	1.11 (c))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #5		2019-09-24 10:13
MOT test	number	629117159203
Result		× Failed
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11	L (c))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.	11 (c))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Pass wit	ch rectification Offside Headlamp aim too high (4.1.2 (a))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #4	2018-09-14 11:22
MOT test number	577997508308
Result	✓ Passed
Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #3	2017-09-14 15:19
MOT test number	346174308088
Result	✓ Passed
MOT #2	2016-09-22 12:46
MOT test number	321788659229
Result	✓ Passed
MOT #1	2015-09-14 10:20
MOT test number	960335071578
Result	✓ Passed
	•

CarCheck.co.uk page 5/12



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 December
Days left	216
MOT expiry date	8 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report here for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owner have? Check it in the premium report and see all owner registrations. Download the full is	
THE STREET STREE	

	More info >
Plate changes	
See in this check if this PEUGEOT had different number plates.	
Number of plates	
Current registration	UK UK
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2012-09-30
Last registration	2023-08-09
Complete history	See info



Registration #1	2012-09-30	20 mi
Registration #2	2015-09-14	23.111 mi
Registration #3	2016-09-22	33.288 mi
Registration #4	2017-09-14	43.124 mi
Registration #5	2018-09-14	53.420 mi
Registration #6	2019-09-24	62.940 mi
Registration #7	2019-09-24	62.940 mi
Registration #8		11.777 es
Registration #9		10.777 es
Registration #10		11.777 ea
Registration #10 Registration #11		11.777 ea 11.777 ea
		11.777 ea 11.777 ea 11.777 ea
Registration #11		11.777 es 11.777 es 11.777 es

mn.n.n

More info >

77.777 au

CarCheck.co.uk page 11/12



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	***
Video	see crash video

Dimensions & weight

Width	1630 mm
Height	1465 mm
Length	3430 mm
Wheel base	2340 mm
Kerb weight	900 kg
Max. allowed weight	1180 kg

Additional information

Fuel tank capacity	35 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	7155098

CarCheck.co.uk page 12/12