




report date: 2024-03-28

General information

<b>Make</b>	RENAULT TRUCKS
<b>Model</b>	MASTER 35 L3H2 P/V
<b>Colour</b>	White
<b>Year of manufacture</b>	2016
<b>Top speed</b>	87 mph
<b>Gearbox</b>	6 speed MANUAL

Engine & fuel consumption

<b>Power</b>	109 BHP
<b>Max. torque</b>	214 Nm at 1.500 rpm
<b>Engine capacity</b>	2.299 cc
<b>Cylinders</b>	4
<b>Fuel type</b>	Diesel
<b>Consumption city</b>	34.5 mpg
<b>Consumption extra urban</b>	39.2 mpg
<b>Consumption combined</b>	37.2 mpg
<b>CO2 emission</b>	197 g/km
<b>CO2 label</b>	J





## Internet history

### Entry 1

Date	2021-07-31
Pictures	23
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](http://cargurus.co.uk)



MOT history

MOT expiry date	2024-08-16
MOT pass rate	71 %
MOT passed	5
Failed MOT tests	2
Total advice items	16
Total items failed	3

MOT #7 2023-08-16 07:18

MOT test number 382069972758

Result ✔ Passed

Next expiry date 2024-08-16

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #6 2023-08-16 07:18

MOT test number 118895455192

Result ✘ Failed

- Advice** Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))



<b>MOT #5</b>	2022-08-15 15:24
<b>MOT test number</b>	512762566617
<b>Result</b>	✓ Passed
<b>Advice</b>	Nearside Front Wheel bearing slightly noisy (5.1.3 (b) (i))
<b>Advice</b>	Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
<b>Minor</b>	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
<b>Advice</b>	Rear Service brake fluctuating, but not excessively (1.2.1 (e))

<b>MOT #4</b>	2021-08-17 16:19
<b>MOT test number</b>	807466381908
<b>Result</b>	✓ Passed

<b>MOT #3</b>	2020-11-04 11:44
<b>MOT test number</b>	473506498929
<b>Result</b>	✓ Passed
<b>Minor</b>	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
<b>Advice</b>	Nearside Front Wheel bearing slightly noisy (5.1.3 (b) (i))

<b>MOT #2</b>	2019-11-04 14:40
<b>MOT test number</b>	800135211504
<b>Result</b>	✓ Passed

<b>MOT #1</b>	2019-11-04 14:15
<b>MOT test number</b>	829819939295
<b>Result</b>	✗ Failed
<b>Fail</b>	Offside Outline marker lamp not working 3 lamps not working (4.2.1 (a) (ii))
<b>Fail</b>	Nearside Outline marker lamp not working 2 not working (4.2.1 (a) (ii))



Tax & MOT check

✓  
**Taxed**

**Tax due:**  
1 September 2024

✓  
**MOT**

**Expires:**  
16 August 2024

**Tax status** Valid until 1 September

**Days left** 125

**MOT expiry date** 16 August 2024

**Full MOT history** [See MOT history](#)

Tax calculation

<b>Vehicle class</b>	39
<b>Standard rate (12 months)</b>	£ 275,00,-
<b>Standard rate (6 months)</b>	£ 151,25,-




Damage history

Check the damage history for this RENAULT TRUCKS. See if, where and when this RENAULT TRUCKS had damage and the car repair costs. We also check if this RENAULT TRUCKS was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra RENAULT TRUCKS salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT TRUCKS? How many owners did this RENAULT TRUCKS have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start	End

More info >

Plate changes

See in this check if this RENAULT TRUCKS had different number plates.

Number of plates	1
Current registration	BX66FMF
Plate since	2019-09-29
Current registration	BX66FMF
Plate since	2019-09-29

More info >



Finance check

Check if this RENAULT TRUCKS is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT TRUCKS has been settled.
If not, and you buy this RENAULT TRUCKS then you could lose the money and the car you paid for.
Download the premium report here and check if this RENAULT TRUCKS is financed.


Table with 2 columns: Field Name (Finance company, Date of agreement, Agreement type, Agreement term, Agreement number, Contact info) and Value (blurred).

More info >



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2016-11-10
Last registration	2023-08-16
Complete history	<a href="#">See info</a>



Registration #1	2016-11-10	21 mi
Registration #2	2019-11-04	112.662 mi
Registration #3	2019-11-04	112.662 mi
Registration #4	2020-11-04	144.096 mi
Registration #5	2023-08-16	144.096 mi
Registration #6	2023-08-16	144.096 mi
Registration #7	2023-08-16	144.096 mi
Registration #8	2023-08-16	144.096 mi
Registration #9	2023-08-16	144.096 mi

[More info >](#)



**Dimensions & weight**

<b>Width</b>	2070 mm
<b>Height</b>	2475 mm
<b>Length</b>	6198 mm
<b>Kerb weight</b>	2219 kg
<b>Max. allowed weight</b>	3500 kg

**Additional information**

<b>Number of seats</b>	3
<b>Number of axles</b>	2
<b>Engine number</b>	C003292