



report date: 2024-03-29

General information

Make	KIA
Model	SEDONA ES
Colour	Blue
Year of manufacture	-
Top speed	111 mph
0 - 60 mph	16.2 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	143 BHP
Max. torque	310 Nm at 2.000 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	24.8 mpg
Consumption extra urban	41.5 mpg
Consumption combined	33.2 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-10-28
Pictures	9
Listing price	<a href="#">View report</a>



source: autotrader.co.uk

**MOT history****MOT #22**

2022-09-15 09:55

**MOT test number**

768772927942

**Result****✗ Failed**

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Fail** Nearside Rear Upper Shock absorbers has an excessively worn bush (5.3.2 (c))
- Fail** Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Fail** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Fail** Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Fail** Offside Front Road wheel fixing missing (5.2.1 (a) (i))
- Fail** Offside Stop lamp(s) not working (4.3.1 (a) (ii))
- Fail** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Fail** Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

**MOT #21**

2021-09-06 14:56

**MOT test number**

100091991631

**Result****✓ Passed**

- Advice** Nearside Rear Wheel bearing has slight play (5.1.3 (a) (i))
- Advice** Nearside Rear Nail in tyre

**MOT #20**

2021-09-01 14:30

**MOT test number**

230892279572

**Result****✗ Failed**

- Advice** Nearside Rear Wheel bearing has slight play (5.1.3 (a) (i))
- Fail** Nearside Front Tyre has ply or cords exposed INNER EDGE (5.2.3 (d) (ii))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Advice** Nearside Rear Nail in tyre
- Fail** Offside Windscreen washer provides insufficient washer liquid (3.5 (a))
- Fail** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Fail** Offside Rear Parking brake inoperative on one side (1.4.1 (a))
- Fail** Nearside Windscreen washer provides insufficient washer liquid (3.5 (a))
- Fail** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

**MOT #19**

2020-09-03 15:31

**MOT test number**

280808398866

**Result****✓ Passed**

- Advice** Offside Headlamp has a product on the light source but not seriously reducing light output (4.1.4 (b))
- Advice** Passenger seat(s) missing at time of test ALL REAR SEATS
- Advice** Nearside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

**MOT #18** 2020-09-03 11:14**MOT test number** 575299001488**Result** ✗ Failed**Advice** Passenger seat(s) missing at time of test ALL REAR SEATS**Advice** Offside Headlamp has a product on the light source but not seriously reducing light output (4.1.4 (b))**Advice** Nearside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))**Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**MOT #17** 2019-04-20 09:58**MOT test number** 102468443479**Result** ✓ Passed**MOT #16** 2018-06-01 13:30**MOT test number** 981525542052**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Spare tyre defective**Advice** Offside Front Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #15** 2018-05-31 09:35**MOT test number** 351783858420**Result** ✗ Failed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Rear Wheel bearing rough when rotated (5.1.3 (b) (i))**Advice** Offside Front Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Spare tyre defective**MOT #14** 2017-06-06 14:54**MOT test number** 639891906544**Result** ✓ Passed**Advice** Spare tyre defective below limit**Advice** Offside Rear Tyre worn close to the legal limit worn on the edges (4.1.E.1)**Advice** Nearside Rear wheel bearing is noisy when spun by hand**Advice** Front Anti-roll bar has slight play in a pin/bush D bushes (2.4.G.2)**Advice** Nearside Rear Tyre worn close to the legal limit worn on the edges (4.1.E.1)**MOT #13** 2015-12-16 08:35**MOT test number** 901303573373**Result** ✓ Passed**Advice** Front Anti-roll bar has slight play in a pin/bush both D bushes (2.4.G.2)**Advice** Both rear tyres are wearing low on the edges**Advice** Spare tyre is worn below legal limit**Advice** Near side rear wheel bearing is slightly noisy when spun by hand

**MOT #12** 2014-12-29 16:40**MOT test number** 459833464408**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Spare tyre is below legal limit**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #11** 2014-12-29 13:41**MOT test number** 956273764391**Result** ✗ Failed**Fail** Nearside Rear Stop lamp not working (1.2.1b)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Spare tyre is below legal limit**Fail** Rear Braking system leaking (3.6.A.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #10** 2014-01-02 10:25**MOT test number** 226162204030**Result** ✓ Passed**Notice** Spare tyre is below min tread depth**MOT #9** 2014-01-02 10:25**MOT test number** 418292604008**Result** ✗ Failed**Pass with rectification** Exhaust system not adequately supported (7.1.1)**Notice** Spare tyre is below min tread depth



<b>MOT #8</b>	2012-10-16 09:11
<b>MOT test number</b>	567450192290
<b>Result</b>	✓ Passed
<b>Notice</b>	Nearside rear shock absorber damp
<b>Notice</b>	Centre exhaust bracket detached

<b>MOT #7</b>	2011-10-17 09:13
<b>MOT test number</b>	896140091268
<b>Result</b>	✗ Failed
<b>Pass with rectification</b>	Nearside Registration plate lamp not working (1.1.C.1d)
<b>Notice</b>	Fluid leak at front of engine
<b>Notice</b>	Surface corrosion to rear metal brake pipes
<b>Notice</b>	Exhaust centre bracket detached
<b>Notice</b>	Coolant leak from rear heater pipes

<b>MOT #6</b>	2011-10-17 09:13
<b>MOT test number</b>	337050491480
<b>Result</b>	✓ Passed
<b>Notice</b>	Exhaust centre bracket detached
<b>Notice</b>	Coolant leak from rear heater pipes
<b>Notice</b>	Surface corrosion to rear metal brake pipes
<b>Notice</b>	Fluid leak at front of engine

<b>MOT #5</b>	2010-10-15 08:51
<b>MOT test number</b>	804398280253
<b>Result</b>	✓ Passed
<b>Notice</b>	Oil leak

**MOT #4** 2009-10-16 10:00**MOT test number** 734549089205**Result** ✓ Passed**MOT #3** 2008-10-04 09:40**MOT test number** 881148878265**Result** ✗ Failed**Notice** Nail in nearside rear tyre**Notice** Nearside rear devoid of tread on edges**Pass with rectification** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Notice** Offside front devoid of tread on edges**Notice** Spare tyre defective**MOT #2** 2008-10-04 09:40**MOT test number** 944598378216**Result** ✓ Passed**Notice** Offside front devoid of tread on edges**Notice** Spare tyre defective**Notice** Nail in nearside rear tyre**Notice** Nearside rear devoid of tread on edges**MOT #1** 2007-10-15 15:59**MOT test number** 282278187250**Result** ✓ Passed



Damage history


Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this KIA had different number plates.

Number of plates	1
Current registration	RK54YCR
Plate since	2019-03-29
Current registration	RK54YCR
Plate since	2019-03-29

More info >



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2004-10-22
Last registration	2022-09-15
Complete history	<a href="#">See info</a>



Registration #1	2004-10-22	7 mi
Registration #2	2007-10-15	15.644 mi
Registration #3	2008-10-04	25.166 mi
Registration #4	2009-10-16	34.767 mi
Registration #5	2010-10-15	43.659 mi
Registration #6	2011-10-17	53.190 mi
Registration #7	2012-10-16	61.496 mi
Registration #8	2014-01-02	63.441 mi
Registration #9	2014-12-29	64.857 mi
Registration #10	2014-12-29	64.857 mi
Registration #11	2015-12-16	66.105 mi
Registration #12	2016-01-02	66.105 mi
Registration #13	2016-01-02	66.105 mi
Registration #14	2016-01-02	66.105 mi
Registration #15	2016-01-02	66.105 mi
Registration #16	2016-01-02	66.105 mi
Registration #17	2016-01-02	66.105 mi
Registration #18	2016-01-02	66.105 mi
Registration #19	2016-01-02	66.105 mi
Registration #20	2016-01-02	66.105 mi
Registration #21	2016-01-02	66.105 mi

More info >



Car features

The KIA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete KIA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1900 mm
Height	1805 mm
Length	4925 mm
Wheel base	2905 mm
Kerb weight	2230 kg
Max. allowed weight	2748 kg

Additional information

Fuel tank capacity	75 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	J3 668464