





report date: 2024-03-28

General information

Make	KIA
Model	CEED 2 ECODYNAMICS
Colour	Black
Year of manufacture	2013
Top speed	121 mph
0 - 60 mph	9.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	133 BHP
Max. torque	164 Nm at 4.850 rpm
Engine capacity	1.591 cc
Cylinders	4
Fuel type	Petrol
Consumption city	41.5 mpg
Consumption extra urban	62.8 mpg
Consumption combined	52.3 mpg
CO2 emission	124 g/km
CO2 label	D



CarCheck.co.uk page 1/12



Internet history

Entry 1

Date 2021-02-22


Pictures 45

Listing price <u>View report</u>









source: yesauto.com

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2025-02-22
MOT pass rate	90 %
MOT passed	9
Failed MOT tests	1
Total advice items	22
Total items failed	1

MOT #10	2024-02-22 15:16
MOT test number	424872546127
Result	✓ Passed
Next expiry date	2025-02-22
Advice Offside Front Lower Suspension arm pin or bush worn but not resultin (5.3.4 (a) (i))	ng in excessive movement
Advice Nearside Front Lower Suspension arm pin or bush worn but not result	ing in excessive movement
(5.3.4 (a) (i))	
Advice Front brake discs scored and corroded	

MOT #9		2023-02-02 14:04
MOT test	number	286455861085
Result		✓ Passed
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Bonnet secondary catch seized.	

CarCheck.co.uk page 3/12



LF13VUX

report date: 2024-03-28

MOT #8 2023-02-02 10:46 **MOT** test number 288438815371 Result × Failed Fail Offside Track rod end ball joint worn to the extent there is a serious risk of detachment (2.1.3 (b) (ii)) **Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **Advice** Bonnet secondary catch seized. Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Advice Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Advice

 MOT #7
 2022-02-03 11:57

 MOT test number
 256741633908

 Result
 ✓ Passed

 MOT #6
 2021-02-23 16:44

 MOT test number
 193011941603

 Result
 ✓ Passed

✓ Passed **MOT #5** 2020-08-28 13:53 **MOT** test number 636266961014 Result Passed **Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) Advice **Advice** Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i)) Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Advice Advice Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) Advice Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))

CarCheck.co.uk page 4/12



LF13VUX

report date: 2024-03-28

MOT #4		2019-04-26 08:27
MOT test	number	645704577559
Result		✓ Passed
MOT #3		2018-04-21 07:33
MOT test	number	387567423391
Result		✓ Passed
MOT #2		2017-04-29 08:44
MOT test	number	701824282550
Result		✓ Passed
MOT #1		2016-04-30 11:08
MOT test	number	103396566531
Result		✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit inside edge (4.1.E.1)	
Advice	Nearside Rear Tyre worn close to the legal limit inside edge (4.1.E.1)	
Advice	Offside Front Tyre worn close to the legal limit inside edge (4.1.E.1)	

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 February
Days left	279
MOT expiry date	22 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did Check it in the premium report and see all owner registrations. Download the full report h	
manage of the same	

	More info >
Plate changes	
See in this check if this KIA had different number plates.	
Number of plates	,
Current registration	NE UK
Plate since	
Current registration	NIE UK
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this KIA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2013-03-07
Last registration	2024-02-22
Complete history	See info



Registration #1	2013-03-07	26 mi
Registration #2	2016-04-30	27.171 mi
Registration #3	2017-04-29	33.431 mi
Registration #4	2018-04-21	39.985 mi
Registration #5	2019-04-26	49.523 mi
Registration #6	2020-08-28	62.036 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		0.777-46

More info >

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
50569	

Safety ratings

NCAP rating	****
Adult	89%
Children	88%
Pedestrian	61%
Safety systems	86%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	1780 mm
Height	1470 mm
Length	4310 mm
Wheel base	2650 mm
Kerb weight	1354 kg
Max. allowed weight	1720 kg

Additional information

Fuel tank capacity	53 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 12/12

Number of axles 2

Engine number G4FDDZ675768