



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	TRANSPORTER T30 SWB P/V 130TDI
Colour	Silver
Year of manufacture	2004
Top speed	104 mph
0 - 60 mph	15.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	128 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	2.460 cc
Cylinders	5
Fuel type	Diesel



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-08-24
Pictures	8
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



## MOT history

MOT expiry date	2024-05-03
MOT pass rate	65 %
MOT passed	15
Failed MOT tests	8
Total advice items	47
Total items failed	26

MOT #23	2023-05-04 14:06
MOT test number	402521561495
Result	✓ Passed
Next expiry date	2024-05-03
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #22	2022-03-14 17:35
MOT test number	494945851157
Result	✓ Passed
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #21	2020-12-03 10:37
MOT test number	551065159300
Result	✓ Passed

MOT #20	2019-10-24 10:16
MOT test number	164033539228
Result	✓ Passed
Advice	Rear exhaust box deteriorated

**MOT #19** 2018-10-08 11:07**MOT test number** 124522790822**Result** ✓ Passed**MOT #18** 2018-10-04 11:02**MOT test number** 791255580363**Result** ✗ Failed**Fail** Nearside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Fail** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**Fail** Offside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**MOT #17** 2017-10-04 11:33**MOT test number** 406599949003**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' x2 (8.3.1d)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #16**

2017-10-03 10:08

**MOT test number**

573862498594

**Result****✗ Failed**

- Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Fail** Front Suspension arm ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt N/S and O/S/F (2.4.G.2)
- Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' x2 (8.3.1d)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Fail** Nearside Front Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)
- Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)

**MOT #15**

2016-10-05 13:33

**MOT test number**

280959908110

**Result****✓ Passed****MOT #14**

2016-10-03 11:42

**MOT test number**

993711354479

**Result****✗ Failed**

- Fail** Parking brake: efficiency below requirements (3.7.B.7)
- Fail** Nearside Front Lower Suspension arm has excessive play in a pin/bush (2.4.G.2)
- Fail** Offside Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)
- Fail** Parking brake lever has no reserve travel (3.1.6b)
- Fail** Nearside Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)

**MOT #13** 2015-09-28 14:02**MOT test number** 603338118636**Result** ✓ Passed**Advice** Nearside Front Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**MOT #12** 2015-09-28 10:28**MOT test number** 651167442611**Result** ✗ Failed**Fail** Nearside Front Lower Suspension arm rubber bush deteriorated resulting in excessive movement front (2.4.G.2)**Fail** Offside Front All position lamps not working (1.1.A.3b)**Advice** Nearside Front Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**MOT #11** 2014-09-25 15:21**MOT test number** 158798564221**Result** ✓ Passed**Notice** N/S/R tyre wearing on inner edge**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Notice** Exhaust system slightly corroded**Advice** Offside Front Seat belt stitching slightly frayed (5.2.2b)**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

**MOT #10**

2014-09-16 13:27

**MOT test number**

488499254269

**Result****✗ Failed**

- Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
- Fail** Nearside Rear Registration plate lamp not working (1.1.C.1d)
- Fail** Nearside Rear coil spring broken (2.4.C.1a)
- Fail** Offside Front Seat belt anchorage prescribed area is excessively corroded (5.2.6)
- Notice** N/S/R tyre wearing on inner edge
- Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)
- Fail** Offside Front position lamp(s) not working (1.1.A.3b)
- Fail** Offside Rear Registration plate lamp not working (1.1.C.1d)
- Fail** Offside Suspension component mounting prescribed area is excessively corroded (2.4.A.3)
- Notice** Exhaust system slightly corroded
- Advice** Offside Front Seat belt stitching slightly frayed (5.2.2b)

**MOT #9**

2013-09-26 15:20

**MOT test number**

989289763236

**Result****✓ Passed**

- Notice** Off side front noise from wheel area when moving unable to see further attention needed
- Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
- Advice** Offside Rear Rear reflector slightly damaged but function not impaired (1.5.1c)
- Advice** Offside Front Brake hose slightly deteriorated (3.6.B.4d)
- Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)
- Advice** Nearside Rear Rear reflector slightly damaged but function not impaired (1.5.1c)
- Advice** Nearside Front Brake hose slightly deteriorated (3.6.B.4d)

**MOT #8** 2013-09-16 16:12**MOT test number** 195639053272**Result** ✗ Failed**Advice** Nearside Front Brake hose slightly deteriorated (3.6.B.4d)**Fail** Horn not working (1.6.2a)**Fail** Brakes imbalanced across an axle (3.7.B.5b)**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Offside Rear Rear reflector slightly damaged but function not impaired (1.5.1c)**Fail** Offside Driver's door cannot be opened from outside the vehicle (6.2.B.1b)**Notice** Off side front noise from wheel area when moving unable to see further attention needed**Advice** Offside Front Brake hose slightly deteriorated (3.6.B.4d)**Fail** Nearside Front Upper Anti-roll bar ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Advice** Nearside Rear Rear reflector slightly damaged but function not impaired (1.5.1c)**Fail** Offside Front position lamp(s) not working (1.1.A.3b)**MOT #7** 2012-09-21 15:51**MOT test number** 725705062253**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #6** 2011-09-30 15:19**MOT test number** 768243471208**Result** ✓ Passed



**MOT #5** 2011-09-26 15:04**MOT test number** 858249561244**Result** ✗ Failed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Fail** Nearside Rear coil spring fractured (2.4.C.1a)**Advice** Exhaust has part of the system slightly deteriorated (7.1.1a)**MOT #4** 2010-09-20 15:36**MOT test number** 843203360243**Result** ✓ Passed**MOT #3** 2009-09-21 14:20**MOT test number** 451974969264**Result** ✓ Passed**Notice** Front tyres getting thin**MOT #2** 2008-09-29 11:21**MOT test number** 202403678257**Result** ✓ Passed**Notice** Nearside rear shock damp**Notice** Stone chip windscreen less than 40mm**MOT #1** 2008-09-29 11:21**MOT test number** 751573578244**Result** ✗ Failed**Pass with rectification** Offside Stop lamp not working (1.2.1b)**Notice** Nearside rear shock damp**Notice** Stone chip windscreen less than 40mm



Tax & MOT check

✗  
Untaxed

Tax expired:  
4 September 2021

✓  
MOT

Expires:  
3 May 2024

Tax status	Expired at 4 September
Days left	969 days too late
MOT expiry date	3 May 2024
Full MOT history	<a href="#">See MOT history</a>



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 <b>WG54HHR</b>
Plate since	2024-03-29
Current registration	 <b>WG54HHR</b>
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2004-12-29
Last registration	2023-05-04
Complete history	<a href="#">See info</a>



Registration #1	2004-12-29	27 mi
Registration #2	2008-09-29	93.730 mi
Registration #3	2009-09-21	120.668 mi
Registration #4	2010-09-20	149.241 mi
Registration #5	2011-09-26	173.218 mi
Registration #6	2011-09-30	173.218 mi
Registration #7	2012-09-21	202.417 mi
Registration #8	2013-09-16	235.078 mi
Registration #9	2013-09-26	235.078 mi
Registration #10	2014-09-16	259.310 mi
Registration #11	2014-09-25	259.310 mi
Registration #12	2015-09-28	93.318 mi
Registration #13	2016-09-28	93.318 mi
Registration #14	2017-09-28	93.318 mi
Registration #15	2018-09-28	93.318 mi
Registration #16	2019-09-28	93.318 mi
Registration #17	2020-09-28	93.318 mi
Registration #18	2021-09-28	93.318 mi
Registration #19	2022-09-28	93.318 mi
Registration #20	2023-05-04	93.318 mi
Registration #21	2023-05-04	93.318 mi
Registration #22	2023-05-04	93.318 mi
Registration #23	2023-05-04	93.318 mi
Registration #24	2023-05-04	93.318 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2175 mm
Height	1940 mm
Length	4707 mm

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	4
Engine number	AXD 048701