





report date: 2024-03-28

General information

Make	VOLVO
Model	S60 D2 ES
Colour	White
Year of manufacture	2013
Top speed	121 mph
0 - 60 mph	10.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	115 BHP
Max. torque	270 Nm at 2.500 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	55.4 mpg
Consumption extra urban	72.4 mpg
Consumption combined	65.7 mpg
CO2 emission	114 g/km
CO2 label	С



CarCheck.co.uk page 1/12




Internet history

Entry 2

Date 2021-12-19

Pictures 35

Listing price <u>View report</u>









source: yesauto.com

Entry 1

Date 2021-12-16

Pictures 5

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2025-01-11
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	8
Total items failed	4

MOT #12	2024-01-08 11:39
MOT test number	107261434879
Result	✓ Passed
Next expiry date	2025-01-11

MOT #11	20	22-12-19 17:16
MOT test	number	977694762751
Result		✓ Passed
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	

MOT #10	2022-01-12 10:44
MOT test number	352075159999
Result	✓ Passed

MOT #9	2022-01-11 15:18
MOT test number	534661735187
Result	X Failed
Fail Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))	
Fail Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	

CarCheck.co.uk page 3/12



MOT #8 2021-03-27 09:54

MOT test number 772256245905

Result ✓ Passed

Advice

Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #7

MOT test number

Result

Advice

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT test number

Result

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

 MOT #5
 2019-02-28 11:14

 MOT test number
 259522790195

 Result
 ✓ Passed

 MOT #4
 2019-02-28 11:14

 MOT test number
 130840942380

 Result
 X Failed

 Pass with rectification
 Offside Front Headlamp aim too high (4.1.2 (a))

CarCheck.co.uk page 4/12



MOT #3

MOT test number

Result

Advice Vehicles internal headlight adjuster altered to recheck lights

MOT #2	2017-03-14 14:47
MOT test number	592001589735
Result	✓ Passed
MOT #1	2016-03-08 12:02
MOT test number	411697419675
Result	✓ Passed

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 January
Days left	248
MOT expiry date	11 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category



Extra VOLVO salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

*		
For how long did the current and previous owner(s) have this VOLVO? How many owners have? Check it in the premium report and see all owner registrations. Download the full research)

	More info	>
Plate changes		
See in this check if this VOLVO had different number plates.		
Number of plates		,
Current registration	UK UK	
Plate since		
Current registration	NK NE	
Plate since		
	More info	>

CarCheck.co.uk page 9/12



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Control info	

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2013-03-28
Last registration	2024-01-08
Complete history	See info



Registration #1	2013-03-28	20 mi
Registration #2	2016-03-08	13.322 mi
Registration #3	2017-03-14	15.078 mi
Registration #4	2018-03-14	16.929 mi
Registration #5	2019-02-28	19.047 mi
Registration #6	2019-02-28	19.047 mi
Registration #7	2020-03-18	21.768 mi
Registration #8	2020-03-19	21.768 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es

More info >

CarCheck.co.uk page 11/12



Car features

50225	Air conditionin
50295	
50482	
60501	
60566	
60567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1865 mm
Height	1484 mm
Length	4628 mm
Wheel base	2776 mm
Kerb weight	1519 kg
Max. allowed weight	2030 kg

Additional information

Fuel tank capacity	67 I	
Fuel delivery	Direct Injection	
Number of doors	4	
Number of seats CarCheck.co.uk	5	page 12/12