

Ford



# General information

| Make                | FORD              |
|---------------------|-------------------|
| Model               | RANGER XLT 4X4 TD |
| Colour              | Blue              |
| Year of manufacture | 2004              |
| Gearbox             | 5 speed Manual    |

# Engine & fuel consumption

| Power           | 107 BHP             |
|-----------------|---------------------|
| Max. torque     | 266 Nm at 2.000 rpm |
| Engine capacity | 2.499 сс            |
| Cylinders       | 4                   |
| Fuel type       | Diesel              |
|                 |                     |







# Internet history

Entry 1

Date

Listing price

2021-06-17

Pictures

View report

6

source: autotrader.co.uk



#### MOT history

| <b>MOT expiry date</b> 2022-01-30 |      |
|-----------------------------------|------|
| MOT pass rate                     | 65 % |
| MOT passed                        | 15   |
| Failed MOT tests                  | 8    |
| Total advice items                | 26   |
| Total items failed                | 12   |

| MOT #23  | 2021-01-28 15:14 |
|--|------------------|
| MOT test number                                | 566442038934     |
| Result   | Passed           |
| Next expiry date                               | 2022-01-30       |
| Advice Both front floors corrosion             |                  |
| Advice Front cross member slight corrosion     |                  |
| Advice O/s rear chassis side of tank corrosion |                  |
| Advice Slight corrosion in front inner wings   |                  |

# MOT #22 2021-07 15:05 MOT test number 822338040299 Result × Failed Fail Rear Exhaust system insecure (6.1.2 (a)) Advice Both very front floors slight corrosion Fail Nearside Front Seat belt anchorage prescribed area strength or continuity significantly reduced floor (7.1.1 (a) (i)) Advice Front cross member

**Fail** Nearside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength chassis (5.3.6 (a) (i))

Advice Offside Rear chassis next to tank





| MOT #21   | 2020-01-06 12:07 |
|---|------------------|
| MOT test number   | 317647444945     |
| Result  | ✓ Passed         |
|   |                  |
| MOT #20   | 2019-01-05 10:54 |
| MOT test number   | 626006794842     |
| Result  | ✓ Passed         |
| Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))                        |                  |
| MOT #19   | 2018-01-22 10:19 |
| MOT test number   | 441768320476     |
| Result  | ✓ Passed         |
| Advice Windscreen has damage to an area less than a 10mm circle within zone 'A' | '(8.3.1a)        |
| MOT #18   | 2018-01-22 10:19 |
| MO1 #18   | 2018-01-22 10:19 |

| MOT test number   | 804303821991   |
|---|--|
| Result  | × Failed   |
| <b>Pass with rectification</b><br>position lamps (1.1.C.1a) | Offside Rear Registration plate lamp does not illuminate simultaneously with the |
| Advice Windscreen has                                       | damage to an area less than a 10mm circle within zone 'A' (8.3.1a)               |
| Pass with rectification                                     | Offside Rear fog lamp not working (1.3.2b)                                       |
|   |  |

| MOT #17   | 2017-01-21 09:38 |
|---|------------------|
| MOT test number   | 859706356124     |
| Result  | ✓ Passed         |
| Advice Rear Tyre worn close to the legal limit both (4.1.E.1) |                  |





| MOT #16  |   | 2016-01-15 11:30 |
|----------|---|------------------|
| MOT test | number  | 207732540112     |
| Result   |   | ✓ Passed         |
| Advice   | Front registration plate deteriorated but not likely to be misread (6.3.1d) |                  |
| Advice   | Nearside Front Shock absorber has a slightly worn bush (2.7.4)              |                  |

| MOT #15  |   | 2015-01-24 12:56 |
|----------|---|------------------|
| MOT test | number  | 188884725003     |
| Result   |   | ✓ Passed         |
| Advice   | Exhaust has a minor leak of exhaust gases (7.1.2)                           |                  |
| Advice   | Front registration plate deteriorated but not likely to be misread (6.3.1d) |                  |
| Notice   | Center box bracket corroded   |                  |

| MOT #14   | 2014-01-26 11:16 |  |
|---|------------------|--|
| MOT test number   | 305576224044     |  |
| Result  | ✓ Passed         |  |
| Advice Brake pipe slightly corroded (3.6.B.2c)  |                  |  |
| Notice SILLS FLOOR CHASSSI BRAKE PIPES REQ CLEAN WAX OIL GREASE PREVENTIVE MAINTANACE REQ |                  |  |
| THROUGH OUT   |                  |  |

| MOT #13  |  | 2014-01-26 11:16 |
|--|--|------------------|
| MOT test number  |  | 109576824059     |
| Result   |  | 🗙 Failed         |
| <b>Notice</b> SILLS FLOOR CHASSSI BRAKE PIPES REQ CLEAN WAX OIL GREASE PREVENTIVE MAINTANACE REQ THROUGH OUT |  |                  |
| Pass with rectification  | Nearside Front Front position lamp(s) not work | king (1.1.A.3b)  |
| Advice Brake pipe slight   | ly corroded (3.6.B.2c)                         |                  |





| MOT #12  | 2013-01-11 11:34 |
|--|------------------|
| MOT test number  | 109591013403     |
| Result   | ✓ Passed         |
|  |                  |
| MOT #11  | 2012-01-16 10:15 |
| MOT test number  | 916936212096     |
| Result   | ✓ Passed         |
| Advice Front Brake pad(s) wearing thin (3.5.1g)  |                  |
| Notice Inner sills bit dry req wax oil   |                  |
|  |                  |
| MOT #10  | 2012-01-16 10:15 |
| MOT test number  | 295776112075     |
| Result   | 🗙 Failed         |
| Advice Front Brake pad(s) wearing thin (3.5.1g)  |                  |
| Notice Inner sills bit dry req wax oil   |                  |
| Pass with rectification         Nearside Rear Registration plate lamp not working (1.1.C.1d) |                  |

| МОТ #9          | 2011-01-09 12:00 |
|-----------------|------------------|
| MOT test number | 567899801041     |
| Result          | ✓ Passed         |
|                 |                  |

| MOT #8                  |  | 2010-01-06 14:41 |
|-------------------------|--|------------------|
| MOT test number         |  | 660006000006     |
| Result                  |  | 🗙 Failed         |
| Pass with rectification | Offside Rear fog lamp not working (1.3.2b) |                  |

| MOT #7          | 2010-01-06 14:41 |
|-----------------|------------------|
| MOT test number | 654016200017     |
| Result          | ✓ Passed         |





| MOT #6   | 2009-01-13 16:59 |
|--|------------------|
| MOT test number  | 860603019043     |
| Result   | ✓ Passed         |
| Notice O/S/R tyre 2mm  |                  |
|  |                  |
| MOT #5   | 2008-11-27 16:13 |
| MOT test number  | 944892738301     |
| Result   | 🗙 Failed         |
| Fail         Nearside Rear Leaf spring cracked (2.4.B.1a)        |                  |
| Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1) |                  |

| MOT #4          | 2008-01-31 14:58 |
|-----------------|------------------|
| MOT test number | 981591838091     |
| Result          | ✓ Passed         |

| MOT #3  | 2008-01-31 14:05 |
|---|------------------|
| MOT test number   | 263451538056     |
| Result  | 🗙 Failed         |
| <b>Fail</b> Offside Rear Rear fog lamp insecure (1.3.2a)            |                  |
| Fail         Centre Exhaust system not adequately supported (7.1.1) |                  |

| MOT #2          | 2007-03-05 13:24 |
|-----------------|------------------|
| MOT test number | 812844567074     |
| Result          | ✓ Passed         |
|                 |                  |
| MOT #1          | 2007-03-05 11:47 |

| MOT test number  | 502514167056 |
|--|--------------|
| Result   | 🗙 Failed     |
| Fail         Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1) |              |



AF04LRN report date: 2024-03-29

Tax & MOT check

| X<br>Untaxed                 | Х<br>MOT                    |
|------------------------------|-----------------------------|
| Tax expired:<br>15 June 2021 | Expired:<br>30 January 2022 |
| Tax status                   | Expired at 15 June 2021     |
| Days left                    | 1049 days too late          |
| MOT expiry date              | 30 January 2022             |
| Full MOT history             | See MOT history             |





#### Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 |             |
|----------|-------------|
| Date     | FERM        |
| Category | <br>A PLANE |
| Туре     |             |
| Damage 2 | AMPLE       |
| Damage 2 | E Stand     |
| Date     | *           |
| Category | <br>ante.   |
| Туре     |             |

#### Extra FORD salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





#### Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value          | 4 10.000 |
|-----------------------------|----------|
| Auction value               | 4 10.000 |
| Average private trade value | 4        |





### Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| And a second sec |             |
|--|-------------|
| ************   |             |
| ********   |             |
| *******  |             |
| ************   |             |
| ********   |             |
|  | More info > |
| Plate changes  |             |
| See in this check if this FORD had different number plates.  |             |
| Number of plates   | ,           |
| Carrent registration   |             |
| Plate since  |             |
| Current registration   |             |
| Plate since  |             |
|  |             |





#### Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

| Finance company   |  |
|-------------------|--|
| Date of agreement |  |
| Agreement type    |  |
| Agreement term    |  |
| Agreement number  |  |
| Contact info      |  |





# Mileage check

| Odometer                   | In miles        |
|----------------------------|-----------------|
| Mileage registrations      | 22              |
| First mileage registration | 2004-03-12      |
| Last registration          | 2021-01-28      |
| Complete history           | <u>See info</u> |



| Registration #1  | 2004-03-12 | 26 mi      |
|------------------|------------|------------|
| Registration #2  | 2007-03-05 | 21.587 mi  |
| Registration #3  | 2007-03-05 | 21.587 mi  |
| Registration #4  | 2008-01-31 | 29.754 mi  |
| Registration #5  | 2008-01-31 | 29.754 mi  |
| Registration #6  | 2008-11-27 | 43.821 mi  |
| Registration #7  | 2009-01-13 | 43.822 mi  |
| Registration #8  | 2010-01-06 | 54.138 mi  |
| Registration #9  | 2011-01-09 | 65.782 mi  |
| Registration #10 | 2012-01-16 | 76.700 mi  |
| Registration #11 | 2013-01-11 | 89.925 mi  |
| Registration #12 |            | 11.777 est |
| Registration #13 |            | 11.707 est |
| Registration #14 |            | 11.777 est |
| Registration #15 |            | 11.777 esi |
| Registration #16 |            | 11.777 est |
| Registration #17 |            | 11.777 esi |
| Registration #18 |            | 11.777 est |
| Registration #19 |            | 11.777 esi |
| Registration #20 |            | 10.777 est |
| Registration #21 |            |            |
| Registration #21 |            |            |





#### Car features

| 50225 | Air conditioning |
|-------|------------------|
| 50295 |                  |
| 50482 |                  |
| 60501 |                  |
| 0566  |                  |
| 0567  |                  |
| 0569  |                  |

# Additional information

| Fuel tank capacity | 70                 |
|--------------------|--------------------|
| Fuel delivery      | Indirect Injection |
| Number of doors    | 4                  |
| Engine number      | 407874             |