





report date: 2024-03-28

General information

Make	VAUXHALL
Model	VIVARO L2H1 2900 SPORTIVE CDTI
Colour	White
Year of manufacture	2018
Gearbox	6 speed Manual

Engine & fuel consumption

Power	118 BHP
Max. torque	300 Nm at 1.750 rpm
Engine capacity	1.598 сс
Cylinders	4
Fuel type	Diesel
Consumption city	35.3 mpg
Consumption extra urban	47.1 mpg
Consumption combined	42.2 mpg
CO2 emission	174 g/km
CO2 label	Н



CarCheck.co.uk page 1/10



Internet history

Entry 1

Date 2021-11-06

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/10



MOT history

Fail

MOT expiry date	2024-09-26
MOT pass rate	75 %
MOT passed	3
Failed MOT tests	1
Total advice items	2
Total items failed	3

MOT #4	2023-09-25 15:00
MOT test number	900360773258
Result	✓ Passed
Next expiry date	2024-09-26

MOT #3	2022-09-27 16:16
MOT test number	220156162193
Result	√ Passed

MOT #2	2022-09-24 09:52
MOT test number	404740114878
Result	X Failed
Fail Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))	
Fail Central Stop lamp(s) not working (4.3.1 (a) (ii))	

Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))

MOT #1	2021-08-12 11:35
MOT test	number 477000334114
Result	✓ Passed
Advice	Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

CarCheck.co.uk page 3/10



Tax & MOT check



✓ MOT

Expires: 26 September 2024

Tax status	Valid until 1 November
Days left	186
MOT expiry date	26 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 320,00,-
Standard rate (6 months)	£ 176,00,-

CarCheck.co.uk page 4/10



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report <u>here</u> for the results.

Damage 1


Date

Category
Type

Damage 2

Date
Category

Туре



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 5/10



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 6/10



Owner history

Owner history	
For how long did the current and previous owner(s) have this VAUXHALL? How many own VAUXHALL have? Check it in the premium report and see all owner registrations. Downloaner.	

	More info >
Plate changes	
See in this check if this VAUXHALL had different number plates.	
Mumber of plates	,
Current registration	UK NE
Plate since	
Current registration	AIN
Plate since	
	More info >

CarCheck.co.uk page 7/10



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VAUXHALL is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
0	

Contact info

More info >

CarCheck.co.uk page 8/10



Mileage check

Odometer	In miles
Mileage registrations	6
First mileage registration	2018-07-19
Last registration	2023-09-25
Complete history	See info



Registration #1	2018-07-19	8 mi
Registration #2	2021-08-12	68.638 mi
Registration #3		11,777 mi
Registration #4		71,777 es
Registration #5		71,777 66
Registration #6		11.777 es

Registration #6

More info >

CarCheck.co.uk page 9/10



Safety ratings

NCAP rating	大大大 大大
Adult	52%
Children	91%
Pedestrian	53%
Safety systems	57%
Overall rating	61%
Video	see crash video



Dimensions & weight

Width	2283 mm
Height	1971 mm
Length	5398 mm
Kerb weight	1750 kg
Max. allowed weight	3030 kg

Additional information

Fuel tank capacity	80 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	3
Engine number	R9M H4 - C158668LWZ

CarCheck.co.uk page 10/10