





report date: 2024-03-29

General information

Make	ТОУОТА
Model	AYGO VVT-I X-TREND
Colour	Silver
Year of manufacture	2019
Top speed	99 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	69 BHP
Max. torque	95 Nm at 4.300 rpm
Engine capacity	998 сс
Cylinders	3
Fuel type	Petrol
Consumption combined	57.7 mpg
CO2 emission	93 g/km
CO2 label	Α



CarCheck.co.uk page 1/11



GU19CKV

report date: 2024-03-29

Internet history

Entry 2

Date 2022-03-01

Pictures 19

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 1

Date 2022-01-22

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/11



MOT history

MOT expiry date	2025-01-22
MOT pass rate	60 %
MOT passed	3
Failed MOT tests	2
Total advice items	18
Total items failed	1

MOT #5	2024-01-23 15:10
MOT test number	242100817377
Result	✓ Passed
Next expiry date	2025-01-22
Advice Offside Rear Nail in tyre	
Minor Windscreen wiper blade defective (3.4 (b) (i))	
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #4		2024-01-23 14:35
MOT test	number	493805372201
Result		× Failed
MAJOR	Nearside Windscreen washer not working (3.5 (a))	
Minor	Windscreen wiper blade defective (3.4 (b) (i))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Rear Nail in tyre	
MAJOR	Offside Windscreen washer not working (3.5 (a))	

CarCheck.co.uk page 3/11



Advice

Advice

Advice

Advice

Advice

GU19CKV

report date: 2024-03-29

MOT test number

Result

Advice

Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice

Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice

Offside Front Tyre worn close to legal limit/worn on edge advise to change (5.2.3 (e))

Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT test number

Result

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Pass with rectification Nearside Headlamp aim too low (4.1.2 (a))

Offside Front Tyre worn close to legal limit/worn on edge advise to change (5.2.3 (e))

Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #1 2022-01-21 16:34

MOT test number 184008751646

Result ✓ Passed

CarCheck.co.uk page 4/11



Tax & MOT check



Tax status	Valid until 1 March
Days left	305
MOT expiry date	22 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
First licence fee (12 months)	£ 165,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owner have? Check it in the premium report and see all owner registrations. Download the full it		ГА

	More info	>
Plate changes		
See in this check if this TOYOTA had different number plates.		
Number of plates		
Current registration	UK SIS	
Plate since		
Current registration	OK SIZ	
Plate since		
	More info	>

CarCheck.co.uk page 8/11



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2019-03-29
Last registration	2024-01-23
Complete history	See info



Registration #1	2019-03-29	18 mi
Registration #2	2022-01-21	13.354 mi
Registration #3		9.777 es
Registration #4		11.777 es
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		71.777 es

More info >

CarCheck.co.uk page 10/11



Car features

50225	Air conditionin
60295	
60482	
60501	
60566	
60567	
60569	

Safety ratings

NCAP rating	****
Adult	82%
Children	63%
Pedestrian	64%
Safety systems	57%
Overall rating	69%
Video	see crash video



Dimensions & weight

Width	1615 mm
Height	1460 mm
Length	3465 mm
Max. allowed weight	1240 kg

Additional information

Number of seats	4
Number of axles	2
Engine number	1KR8786865

CarCheck.co.uk page 11/11