





report date: 2024-03-29

## General information

Make	HYUNDAI
Model	I20 ACTIVE
Colour	Grey
Year of manufacture	2013
Top speed	106 mph
0 - 60 mph	12.9 seconds
Gearbox	4 speed automatic

### Engine & fuel consumption

Power	99 BHP
Max. torque	137 Nm at 4.200 rpm
Engine capacity	1.396 сс
Cylinders	4
Fuel type	Petrol
Consumption city	34.9 mpg
Consumption extra urban	58.9 mpg
Consumption combined	47.1 mpg
CO2 emission	140 g/km
CO2 label	E



CarCheck.co.uk page 1/13



## Internet history

#### Entry 1

Date 2021-02-26

Pictures 5

Listing price <u>View report</u>









source: yesauto.com

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2024-12-12
MOT pass rate	67 %
MOT passed	8
Failed MOT tests	4
Total advice items	19
Total items failed	7

MOT #12	2023-12-13 11:33
MOT test number	728779531069
Result	✓ Passed
Next expiry date	2024-12-12
Advice Offside Front Service by	ake fluctuating, but not excessively (1.2.1 (e))
Advice Surface rust on all brak	e discs
Advice Nearside Front Service	orake fluctuating, but not excessively (1.2.1 (e))

MOT #11	2023-06-27 10:05
MOT test number	875175912269
Result	<b>×</b> Failed
Fail  Offside Front Lower Suspension arm ball joint dust cover no longer prevent  (b) (ii))	ts the ingress of dirt (5.3.4
Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Fail Nearside Front Lower Suspension arm ball joint dust cover no longer preve (5.3.4 (b) (ii))	nts the ingress of dirt
<b>Fail</b> Offside Rear Tyre has a bulge, caused by separation or partial failure of its sidewall (5.2.3 (d) (ii))	structure bulge on outer
Advice Brake fluid dark in colour	
Minor Nearside Front Track rod end ball joint dust cover damaged or deteriorating ingress of dirt (2.1.3 (g) (i))	ted, but preventing the
Fail Nearside Front Outer Drive shaft joint constant velocity boot split or insecuingress of dirt (6.1.7 (g) (ii))	ire, no longer prevents the

CarCheck.co.uk page 3/13



MOT #10 2022-02-24 16:48

**MOT test number** 889610172079

Result Passed

Advice Offside Front Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))

MOT #9 2021-02-25 11:25

**MOT test number** 385645015140

MOT #8 2020-04-21 14:50

**MOT test number** 533323651371

MOT #7 2020-04-21 07:57

MOT test number 292865478993

**Result** ★ Failed

Advice Front Brake pad(s) wearing thin 2-3mm (1.1.13 (a) (ii))

**Advice** Rear Brake disc worn, but not excessively (1.1.14 (a) (i))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

MOT #6 2019-05-21 10:47

**MOT test number** 840917722031

Advice Child Seat fitted not allowing full inspection of adult belt

CarCheck.co.uk page 4/13



Pass with rectification

LL13TWA
report date: 2024-03-29

MOT test number

730144234387

Result

Advice Offside Front Fog lamp damaged and loose

Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Tyre worn close to legal limit/worn on edge both rear (5.2.3 (e))

Advice Tyre slightly damaged/cracking or perishing both rear (5.2.3 (d) (i))

**MOT #4** 2018-06-01 13:59 **MOT** test number 501425643284 Result × Failed Tyre worn close to legal limit/worn on edge both rear (5.2.3 (e)) **Advice Advice** Tyre slightly damaged/cracking or perishing both rear (5.2.3 (d) (i)) Advice Offside Front Fog lamp damaged and loose **Pass with rectification** Headlamp aim too high both (4.1.2 (a)) Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

 MOT #3
 2017-05-28 11:34

 MOT test number
 355419628360

 Result
 ✓ Passed

 MOT #2
 2017-05-28 11:34

 MOT test number
 980106879987

 Result
 X Failed

Offside Rear Registration plate lamp not working (1.1.C.1d)

CarCheck.co.uk page 5/13



**MOT #1** 2016-05-17 15:52

**MOT test number** 333213551422

**Result** ✓ Passed

CarCheck.co.uk page 6/13



#### Tax & MOT check



✓ MOT

Expires: 12 December 2024

Tax status	Valid until 1 December
Days left	216
MOT expiry date	12 December 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	48
Band	Е
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 7/13



#### Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



#### Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



#### Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



## Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owner have? Check it in the premium report and see all owner registrations. Download the full is	
manus .	
***************************************	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this HYUNDAI had different number plates.	
Number of plates	
Current registration	UK ZIK
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 10/13



#### Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

**Contact info** 

More info >

CarCheck.co.uk page 11/13



## Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2013-06-12
Last registration	2023-12-13
Complete history	See info



Registration #1	2013-06-12	24 mi
Registration #2	2016-05-17	30.443 mi
Registration #3	2017-05-28	45.267 mi
Registration #4	2017-05-28	45.267 mi
Registration #5	2018-06-01	61.355 mi
Registration #6	2018-06-01	61.355 mi
Registration #7	2019-05-21	74.065 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		91.777 es
Registration #12		D.777 es
Registration #13		11.777 es

mn.n.n

More info >

77.777 86

CarCheck.co.uk page 12/13



## Car features

S0225	Air conditionin
S0295	
50482	
50501	
50566	
50567	
50569	

## Safety ratings

NCAP rating	****
Adult	88%
Children	83%
Pedestrian	64%
Safety systems	86%
Overall rating	82%
Video	see crash video



## Dimensions & weight

Width	1710 mm
Height	1490 mm
Length	3995 mm
Wheel base	2525 mm
Kerb weight	1156 kg
Max. allowed weight	1565 kg

# Additional information

Fuel tank capacity	45 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 13/13

Number of axles 2

**Engine number** G4FADW658470