



report date: 2024-03-29

General information

Make	VOLVO
Model	S60 D3 SE
Colour	Gold
Year of manufacture	2011
Top speed	137 mph
0 - 60 mph	8.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	161 BHP
Max. torque	400 Nm at 1.400 rpm
Engine capacity	1.984 cc
Cylinders	5
Fuel type	Diesel
Consumption city	39.2 mpg
Consumption extra urban	67.3 mpg
Consumption combined	53.3 mpg
CO2 emission	139 g/km
CO2 label	E





Internet history

Entry 2

Date	2021-11-05
Pictures	11
Listing price	<a href="#">View report</a>



source: autotrader.co.uk

Entry 1

Date	2021-10-22
Pictures	0
Listing price	<a href="#">View report</a>

source: autotrader.co.uk



MOT history

MOT expiry date	2025-03-02
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	31
Total items failed	2

MOT #14	2024-02-28 10:51
MOT test number	934374705495
Result	✓ Passed
Next expiry date	2025-03-02
Advice	Auxiliary drive belt deteriorated

MOT #13	2024-02-27 14:10
MOT test number	856370088254
Result	✗ Failed
Advice	Auxiliary drive belt deteriorated
MAJOR	Offside Front Service brake excessively binding (1.2.1 (f))
MAJOR	Front Brakes imbalanced across an axle (1.2.1 (b) (i))
MAJOR	Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened nearside and offside (1.1.14 (a) (ii))
MAJOR	Offside Front Service brake excessively fluctuating (1.2.1 (e))
Advice	Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))

**MOT #12**

2023-02-28 11:31

**MOT test number**

855713986930

**Result**

✓ Passed

- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both sides (1.1.14 (a) (ii))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge worn inner edge (5.2.3 (e))
- Advice** Offside Rear Tyre slightly damaged slightly distorted tread inner edge (5.2.3 (d) (ii))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge worn inner edge on 1.6mm (5.2.3 (e))

**MOT #11**

2023-02-27 14:52

**MOT test number**

675450505539

**Result**

✗ Failed

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge worn inner edge (5.2.3 (e))
- Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Offside Rear Tyre slightly damaged slightly distorted tread inner edge (5.2.3 (d) (ii))
- DANGEROUS** Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
- DANGEROUS** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge worn inner edge on 1.6mm (5.2.3 (e))
- Pass with rectification** Offside Headlamp aim too high (4.1.2 (a))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both sides (1.1.14 (a) (ii))
- DANGEROUS** Nearside Front Tyre has ply or cords damaged (5.2.3 (d) (ii))

**MOT #10**

2022-02-28 09:55

**MOT test number**

366947759428

**Result**

✓ Passed

- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both sides inner surfaces (1.1.14 (a) (ii))

**MOT #9** 2022-02-28 09:55**MOT test number** 307235751953**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim too low (4.1.2 (a))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both sides inner surfaces (1.1.14 (a) (ii))**MOT #8** 2021-03-03 15:34**MOT test number** 883831525669**Result** ✓ Passed**Advice** Under vehicle covers fitted**Advice** Items removed from driver's view prior to test**Advice** Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #7** 2020-03-03 15:56**MOT test number** 898349258732**Result** ✓ Passed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Under vehicle covers fitted**MOT #6** 2019-01-30 10:15**MOT test number** 959295888034**Result** ✓ Passed**MOT #5** 2018-01-30 10:02**MOT test number** 642235080730**Result** ✓ Passed

**MOT #4** 2017-02-02 15:20**MOT test number** 547114626446**Result** ✓ Passed**MOT #3** 2016-03-01 12:37**MOT test number** 871917113626**Result** ✓ Passed**Advice** Offside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #2** 2015-02-26 09:57**MOT test number** 799037955059**Result** ✓ Passed**MOT #1** 2014-03-12 12:13**MOT test number** 257191274097**Result** ✓ Passed**Advice** Nearside Rear Lower Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Offside Rear Lower Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 May 2024

✓  
**MOT**  
**Expires:**  
2 March 2025

<b>Tax status</b>	Valid until 1 May
<b>Days left</b>	2
<b>MOT expiry date</b>	2 March 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	E
<b>Single payment (12 months)</b>	£ 180,00,-
<b>Single six month payment</b>	£ 99,00,-
<b>Total payable by 12 monthly instalments</b>	£ 189,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2011-03-15
Last registration	2024-02-28
Complete history	<a href="#">See info</a>



Registration #1	2011-03-15	21 mi
Registration #2	2014-03-12	37.054 mi
Registration #3	2015-02-26	48.658 mi
Registration #4	2016-03-01	60.878 mi
Registration #5	2017-02-02	68.968 mi
Registration #6	2018-01-30	89.964 mi
Registration #7	2019-01-30	119.891 mi
Registration #8	2020-03-03	129.528 mi
Registration #9	2021-03-03	131.592 mi
Registration #10	2022-03-03	131.592 mi
Registration #11	2023-03-03	131.592 mi
Registration #12	2024-03-03	131.592 mi
Registration #13	2025-03-03	131.592 mi
Registration #14	2026-03-03	131.592 mi
Registration #15	2027-03-03	131.592 mi
Registration #16	2028-03-03	131.592 mi
Registration #17	2029-03-03	131.592 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1885 mm
Height	1484 mm
Length	4028 mm
Wheel base	2775 mm
Kerb weight	1581 kg
Max. allowed weight	2090 kg

Additional information

Fuel tank capacity	67 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

**Engine number**

868977