





report date: 2024-03-28

General information

Make	MINI
Model	COOPER AUTO ONE
Colour	Black
Year of manufacture	2011
Top speed	108 mph
Gearbox	6 speed automatic

Engine & fuel consumption

Power	98 BHP	
Max. torque	153 Nm at 3.000 rpm	
Engine capacity	1.598 сс	
Cylinders	4	
Fuel type	Petrol	
Consumption city	31.7 mpg	
Consumption extra urban	53.3 mpg	
Consumption combined	42.8 mpg	
CO2 emission	154 g/km	
CO2 label	G	



CarCheck.co.uk page 1/12



Internet history

Entry 1

Date 2022-05-08

Pictures 33

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-05-17
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	7
Total items failed	4

MOT #13	2023-05-18 13:57
MOT test number	166238762335
Result	✓ Passed
Next expiry date	2024-05-17

MOT #12	2023-05-17 09:53	
MOT test number	377959339355	
Result	★ Failed	
Advice Offside Rear Brake disc worn, pitted or so (a) (ii))	cored, but not seriously weakened badly corroded (1.1.14	
Advice Offside Rear Brake pad(s) wearing thin (1	1.13 (a) (ii))	
Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened badly corroded (1.1.14 (a) (ii))		
Fail Offside Rear Brake pad(s) worn down to wear indicator (1.1.13 (a) (i))		
Advice Nearside Rear Brake pad(s) wearing thin	(1.1.13 (a) (ii))	

MOT #11	2022-04-01 11:13
MOT test number	323948142192
Result	✓ Passed

CarCheck.co.uk page 3/12



MOT #10 2022-04-01 09:01

MOT test number 218134659212

Result X Failed

Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))

Fail Front Windscreen washer provides insufficient washer liquid (3.5 (a))

MOT #9 2021-07-08 10:10

MOT test number 356577924154

Result \(\sqrt{Passed} \)

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement arm rear bush (5.3.4 (a) (i))

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement arm rear bush (5.3.4 (a) (i))

MOT #8 2020-06-15 09:04

MOT test number 901922148750

Result ✓ Passed

MOT #7 2020-06-15 09:04

MOT test number 697770372596

Result X Failed

Pass with rectification Offside Windscreen washer not working (3.5 (a))

MOT #6 2019-06-14 11:58

MOT test number 660627307188

MOT #5 2018-10-08 08:08

MOT test number 664906350003

Result

Passed

CarCheck.co.uk page 4/12



MOT #4 2017-09-20 11:00

MOT test number 599673760134

MOT #3 2016-09-22 08:53

MOT test number 652561109317

Result Passed

Advice Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #2 2015-09-23 15:07

MOT test number 867312385399

Result \rightarrow Passed

MOT #1 2014-06-09 15:21

MOT test number 965280164184

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 May
Days left	367
MOT expiry date	17 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1


Date

Category
Type

Damage 2

Date

Category



Extra MINI salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

Owner mistory		
For how long did the current and previous owner(s) have this MINI? How many owners di Check it in the premium report and see all owner registrations. Download the full report		

HEREER PARTY AND ADDRESS OF THE PARTY AND ADDR		

	More info >	
Plate changes		
See in this check if this MINI had different number plates.		
Number of plates		
Current registration	NK NE	
Plate since		
Current registration	OK OK	
Plate since		
	More info >	

CarCheck.co.uk page 9/12



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

 $\quad \text{More info} \quad > \quad$

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2011-05-20
Last registration	2023-05-18
Complete history	See info



Registration #1	2011-05-20	9 mi
Registration #2	2014-06-09	36.512 mi
Registration #3	2015-09-23	42.201 mi
Registration #4	2016-09-22	44.374 mi
Registration #5	2017-09-20	46.254 mi
Registration #6	2018-10-08	48.696 mi
Registration #7	2019-06-14	49.782 mi
Registration #8	2020-06-15	51.724 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		91,700 esi
Registration #12		11.777 es
Registration #13		91,700 esi
Registration #14		11.777 es
Registration #15		11.177 es

More info >

CarCheck.co.uk page 11/12



Car features

50225	Air conditionin
50295	
50482	
60501	
60566	
60567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1683 mm
Height	1414 mm
Length	3699 mm
Wheel base	2467 mm
Kerb weight	1200 kg
Max. allowed weight	1630 kg

Additional information

Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4
Number of axles Carcheck.co.uk	2 page 12/12